

HT4001[®]

***Plasma Arc
Cutting System -
Gas Panel and
High Frequency Console***

***Instruction Manual
802970 - Revision 2***

***Integrated Plasma System
For use with the *TITAN*[™]***

Hypertherm
*The world leader in
plasma cutting technology*

MESSER 
**MG Systems &
Welding, Inc.**

NOTICE

Use the HT4001 instruction manual, 802000, as well as this manual, 802970, to install, operate and maintain the HT4001 with Titan system.

- This manual contains information to install and operate the HT4001 with Titan system. A parts list for the gas panel and high frequency console is also included.
- See the 802000 manual for general maintenance and information relevant to the HT4001 power supply, slave and accessories.

Page 1

[illegible]

HT4001
Gas Panel and High Frequency Console
for *TITAN*[™]

Plasma Arc Cutting System

Instruction Manual
IM-297
(P/N 802970)

Revision 2 December, 1999

Hypertherm, Inc.
Hanover, NH USA
<http://www.hypertherm.com>
[email:info@hypertherm.com](mailto:info@hypertherm.com)

© Copyright 1999 Hypertherm, Inc.
All Rights Reserved

Hypertherm, HyDefinition, HT, HyLife, LongLife, MAX, PAC and Powermax are trademarks of Hypertherm, Inc.,
and may be registered in the United States and/or other countries

Hypertherm Offices Worldwide:

Hypertherm, Inc.

Etna Road, P.O. Box 5010
Hanover, NH 03755 USA
Tel.: (603) 643-3441 (Main Office)
Fax: (603) 643-5352 (All Departments)
Tel.: (800) 643-9878 (Technical Service)
Tel.: (800) 737-2978 (Customer Service)
email: info@hypertherm.com (General Information)
email: service@hypertherm.com (Technical/Customer Services)

Hypertherm Plasmatechnik GmbH

Technologiepark Hanau
Rodenbacher Chaussee 6
D-63457 Hanau-Wolfgang, Germany
Tel.: 49 6181 58 2100
Fax: 49 6181 58 2134

European Technical Support Organization (ETSO)

Technologiepark Hanau
Rodenbacher Chaussee 6
D-63457 Hanau-Wolfgang, Germany
Tel.: 49 6181 58 2100
Fax: 49 6181 58 2134

Hypertherm Singapore Pte Ltd

No. 19 Kaki Bukit Road 2
K.B. Warehouse Complex
Singapore 417847, Republic of Singapore
Tel.: 65 841 2489
Fax: 65 841 2490

Hypertherm U.K.

9 Berkeley Court • Manor Park
Runcorn, Cheshire, England WA7 1TQ
Tel.: 44 1928 579 074
Fax: 44 1928 579 604

France

10, Allée de l'Isara
F-95000 Cergy-Pontoise, France
Tel.: 33 1 34 24 03 05
Fax: 33 1 34 25 09 64

Italy

Via Torino 2
20123 Milan, Italy
Tel.: 39 02 725 46 312
Fax: 39 02 725 46 400

The Netherlands

Burg, Haverkampstraat 13
7091 CN Dinxperlo, Holland
Tel.: 31 315 655866
Fax: 31 315 655886



ATTENTION



Genuine Hypertherm parts are the factory-recommended replacement parts for your Hypertherm system. Use of other than genuine parts may be cause for invalidation of the Hypertherm warranty.

GENERAL

HYPERTHERM, Inc. warrants that Products shall be free from defects in materials and workmanship, under proper and normal use for which such Equipment is recommended, for a period of two (2) years, except only with respect to the Torch, for which the warranty period shall be one (1) year, from the date of its delivery to you.

HYPERTHERM, at its sole option, shall repair, replace, or adjust, free of charge, any Products covered by this warranty which shall be returned with HYPERTHERM's prior authorization (which shall not be unreasonably withheld), properly packed, to HYPERTHERM's place of business in Hanover, New Hampshire, all costs, insurance and freight prepaid, and which examination proves not to be free from defects in materials and workmanship. HYPERTHERM shall not be liable for any repairs, replacements, or adjustments of Products covered by this warranty, except those made pursuant to this paragraph or with HYPERTHERM's written consent. This warranty shall not apply to any Product which has been mishandled, incorrectly installed, modified or assembled by you or any other person. HYPERTHERM shall be liable for breach of this warranty only if it receives written notice of such breach within the applicable warranty period specified herein above. THE FOREGOING SHALL CONSTITUTE THE SOLE REMEDY TO DISTRIBUTORS OR THEIR CUSTOMERS FOR ANY BREACH BY HYPERTHERM OF ITS WARRANTY.

PATENT INDEMNITY

Except only in cases of Products not manufactured by HYPERTHERM or manufactured by a person other than HYPERTHERM not in strict conformity with HYPERTHERM's specifications, and in cases of designs, processes, formulae or combinations not developed or purported to be developed by HYPERTHERM, HYPERTHERM agrees to indemnify, protect and hold harmless Distributors and their customers against any and all liability or claims in any manner imposed upon or accruing against Distributors and their customers because of the use in or about the construction or operation of Equipment or any design, system, formula, combination, article or material which infringes or alleges to infringe on any patent or other right. Distributors shall notify HYPERTHERM promptly upon learning of any action or threatened action in connection with any such alleged infringement, and each party may appoint its own counsel for any such action or threatened action.

DISCLAIMER OF OTHER WARRANTIES

HYPERTHERM MAKES NO WARRANTIES REGARDING PRODUCTS MANUFACTURED BY IT OR OTHERS (INCLUDING WITHOUT IMPLIED LIMITATION WARRANTIES AS TO MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE), EITHER EXPRESS OR IMPLIED, EXCEPT AS PROVIDED HEREIN. This warranty is in lieu of any and all warranties, express or implied, by law or otherwise; and Distributors are not authorized to give any other warranty purporting to be binding upon HYPERTHERM upon resale of Products to their customers. IN NO EVENT shall HYPER-THERM be liable for incidental or consequential damages or injury to the person or property of anyone by reason of any defect in any Equipment sold hereunder.

PLUMBING AND ELECTRICAL CODES

National and local codes governing plumbing and electrical installation shall take precedent over any instructions contained in this manual. IN NO EVENT shall Hypertherm be liable for incidental or consequential injury to persons or property damage by reason of any code violation or poor work practices.

Table of Contents

| | |
|--|------------|
| NOTICE | 0-1 |
| WARRANTY | i |
| GENERAL | i |
| PATENT INDEMNITY | i |
| DISCLAIMER OF OTHER WARRANTIES | i |
| Section 1 SAFETY | 1-1 |
| About Notes, Cautions and Warnings | 1-1 |
| Eye Protection | 1-2 |
| Skin Protection | 1-2 |
| Toxic Fume Prevention | 1-2 |
| Fire Prevention | 1-2 |
| Electric Shock Prevention | 1-2 |
| Electric Shock Prevention (continued) | 1-3 |
| Explosion Prevention | 1-3 |
| Pressure Regulators | 1-3 |
| Noise Protection | 1-4 |
| Grounding | 1-4 |
| Safety Reminders | 1-4 |
| Electronic Health Support Equipment | 1-4 |
| Section 2 SPECIFICATIONS | 2-1 |
| SYSTEM COMPONENTS | 2-1 |
| HT4001 Power Supply | 2-1 |
| HT4001 Machine Torch | 2-1 |
| Remote High Frequency & Motor Valve Console | 2-1 |
| Gas Panel | 2-1 |
| Timer/Counter - Optional | 2-1 |
| Water Muffler - Optional | 2-1 |
| H-401 Slave Power Supply - Optional | 2-1 |
| Water Chiller - Optional | 2-2 |
| SPECIFICATIONS | 2-2 |
| System Requirements | 2-2 |
| HT4001 Power Supply | 2-2 |
| HT4001 Power Supply - with Slave | 2-3 |
| PAC620 Machine Torches | 2-3 |
| Remote High Frequency & Motor Valve (RHF&MV) Console | 2-4 |
| Gas Panel | 2-4 |
| Timer/Counter - Optional | 2-5 |
| Water Muffler - Optional | 2-5 |
| Water Chiller - Optional | 2-5 |
| Section 3 INSTALLATION | 3-1 |
| PRE-INSTALLATION | 3-1 |
| SYSTEM UNITS PLACEMENT | 3-1 |
| POWER SUPPLY CONNECTIONS | 3-4 |
| GAS PANEL CONNECTIONS | 3-9 |
| RHF&MV CONSOLE CONNECTIONS | 3-10 |
| TORCH CONNECTIONS | 3-10 |

TABLE OF CONTENTS

| | |
|--|-------------|
| Routing the Torch Leads | 3-10 |
| MOUNTING THE MACHINE TORCH | 3-13 |
| Torch Alignment | 3-13 |
| Section 4 OPERATION | 4-1 |
| FRONT PANEL CONTROLS AND INDICATORS | 4-2 |
| HT4001LCMP Gas Panel (Fig. 4-1) | 4-2 |
| DAILY START-UP | 4-3 |
| Check Torch | 4-3 |
| Turn Gases and Water On | 4-3 |
| Turn Power Supply On and Adjust Voltage/Current | 4-4 |
| Adjust Preflow Gases | 4-4 |
| Adjust Cut Flow Gases and Water Injection Flow Rate | 4-4 |
| CUTTING TECHNIQUES | 4-5 |
| How to Get Better Cut Quality | 4-5 |
| Dross Conditions | 4-5 |
| Shape of the Cut Surface | 4-6 |
| How to Get Longer Consumable Life | 4-6 |
| How to Get Better Pierces | 4-7 |
| How to Increase Cutting Speed | 4-7 |
| COMMON CUTTING FAULTS | 4-8 |
| TECHNICAL QUESTIONS | 4-8 |
| CUT CHARTS | 4-8 |
| HT4001 without Slave | 4-10 |
| PAC620 Torch - Standard Consumables | 4-10 |
| Mild Steel - Oxygen Plasma | 4-10 |
| HT4001 without Slave | 4-11 |
| PAC620 Torch - Standard Consumables | 4-11 |
| Mild Steel - Nitrogen Plasma | 4-11 |
| HT4001 without Slave | 4-12 |
| PAC620 Torch - Standard Consumables | 4-12 |
| Stainless Steel - Nitrogen Plasma | 4-12 |
| HT4001 without Slave | 4-13 |
| PAC620 Torch - Standard Consumables | 4-13 |
| Aluminum - Nitrogen Plasma | 4-13 |
| HT4001 without Slave | 4-14 |
| PAC620 Torch - Beveling Consumables | 4-14 |
| Mild Steel - Oxygen Plasma | 4-14 |
| HT4001 without Slave | 4-15 |
| PAC620 Torch - Beveling Consumables | 4-15 |
| Mild Steel - Oxygen Plasma | 4-15 |
| HT4001 without Slave | 4-16 |
| PAC620 Torch - Beveling Consumables | 4-16 |
| Mild Steel or Stainless Steel - Nitrogen Plasma | 4-16 |
| HT4001 without Slave | 4-17 |
| PAC620 Torch - Beveling Consumables | 4-17 |
| Aluminum - Nitrogen Plasma | 4-17 |
| HT4001 w/Slave | 4-18 |
| PAC620 Torch - Standard Consumables | 4-18 |
| Mild Steel or Stainless Steel - Nitrogen Plasma | 4-18 |
| HT4001 w/Slave | 4-19 |
| PAC620 Torch - Standard Consumables | 4-19 |
| Aluminum - Nitrogen Plasma | 4-19 |
| HT4001 w/Slave | 4-20 |
| PAC620 Torch - Beveling Consumables | 4-20 |

TABLE OF CONTENTS

| | |
|--|----------------|
| Mild Steel or Stainless Steel - Nitrogen Plasma | 4-20 |
| HT4001 w/Slave | 4-21 |
| PAC620 Torch - Beveling Consumables | 4-21 |
| Aluminum - Nitrogen Plasma | 4-21 |
| CHANGING CONSUMABLE PARTS | 4-22 |
| Removal and Inspection | 4-22 |
| Replacement | 4-22 |
| Changing the Water Tube | 4-24 |
| Section 5 PARTS LIST | 5-1 |
| GAS PANEL - 077024 | 5-3 |
| RHF&MV CONSOLE - 077028 | 5-5 |
| HT4001 TITAN STANDARD TORCH ASSEMBLY WITH 25' LEADS - 128256 | 5-6 |
| HT4001 TITAN BEVEL TORCH ASSEMBLY WITH 25' LEADS - 128257 | 5-6 |
| PAC620 BEVELING TORCH ASSEMBLY - 028741 | 5-7 |
| TORCH MOUNTING BRACKET - 020046 | 5-7 |
| PAC620 STANDARD TORCH ASSEMBLY - 028507 | 5-8 |
| TORCH MOUNTING BRACKET - 020046 | 5-8 |

List of Figures

| | |
|--|------|
| Figure 2-1 PAC620 Standard Torch Assembly with Dimensions | 2-3 |
| Figure 2-2 PAC620 Bevel Torch Assembly with Dimensions | 2-3 |
| Figure 2-3 Mounting Dimensions - RHF&MV Console | 2-4 |
| Figure 2-4 Mounting Dimensions - Gas Panel | 2-4 |
| Figure 2-5 Mounting Dimensions - Timer/Counter | 2-5 |
| Figure 3-1 HT4001 with Titan Interconnection Diagram | 3-3 |
| Figure 3-2 Torch Connections - 1 of 2 | 3-11 |
| Figure 3-3 Torch Connections - 2 of 2 | 3-12 |
| Figure 3-4 Torch Alignment | 3-13 |
| Figure 4-1 HT4001 Titan Gas Panel Controls and Indicators | 4-2 |
| Figure 4-2 Changing Consumable Parts | 4-23 |
| Figure 4-3 Changing the Water Tube | 4-24 |
| Figure 5-1 HT4001 Titan Gas Panel | 5-2 |
| Figure 5-2 HT4001 Titan RHF&MV Console | 5-4 |
| Figure 5-3 128256 or 128257 Torch Assembly | 5-6 |
| Figure 5-4 PAC620 Beveling Torch Assembly | 5-7 |
| Figure 5-5 PAC620 Standard Torch Assembly | 5-8 |

Section 1 SAFETY

In this section:

| | | | |
|--|-----|---|-----|
| About Notes, Cautions and Warnings | 1-1 | Pressure Regulators | 1-3 |
| Safety Instructions | 1-2 | Hoses | 1-3 |
| Eye Protection | 1-2 | Noise Protection | 1-4 |
| Skin Protection | 1-2 | Grounding | 1-4 |
| Toxic Fume Prevention | 1-2 | Input Power | 1-4 |
| Fire Prevention | 1-2 | Work Cable | 1-4 |
| Electric Shock Prevention | 1-2 | Work Table | 1-4 |
| Explosion Prevention | 1-3 | Safety Reminders | 1-4 |
| Compressed Gas Cylinders | 1-3 | Electronic Health Support Equipment | 1-4 |

Before using this plasma arc system. . . .

Each person who will operate this equipment, perform service or maintenance, or supervise its use must read the safety instructions and warnings in this manual and the labels on the equipment.

About Notes, Cautions and Warnings

Notes: Throughout this manual, useful information for operating the plasma system is presented in “notes”, such as shown in this paragraph.

Cautions: Information in bold type and surrounded by a box describes a situation that may cause damage to the plasma system.



WARNINGS



Warnings describe situations that present a physical danger to the operator, and advice to avoid or correct the situation. Each type of warning includes applicable danger symbols, such as a hand burn, electrical shock, fire, explosion, etc.



WARNING — Instant-On Torches

Instant-on torches produce a plasma arc immediately after the torch switch is pushed.

Always hold a hand torch away from your body as a precaution against accidental torch firing. Be aware of this hazard, which has potential for serious bodily injury.




WARNING — Electric Shock

- Never touch the torch body, workpiece or the water in a water table when operating the plasma system.
- When using a water table, be sure that it is correctly connected to earth ground.
- Operating the plasma system completes an electrical circuit between the torch and the workpiece and anything touching the workpiece. The workpiece is part of the electrical circuit.

SAFETY

Eye Protection

- Wear dark safety glasses or goggles with side shields, or a welding helmet, in accordance with applicable national or local codes, to protect eyes against the plasma arc's ultraviolet and infrared rays.

| Arc Current | | Lens Shade | |
|-------------|---|------------|-----------|
| | | AWS (USA) | ISO-4850 |
| Up to 100 A |  | No. 8 | No. 11 |
| 100–200 A | | No. 10 | No. 11–12 |
| 200–400 A | | No. 12 | No. 13 |
| Over 400 A | | No. 14 | No. 14 |

- Replace the glasses, goggles or helmet when the lens becomes pitted or broken.
- Warn other people in the area not to look directly at the arc unless they are wearing glasses, goggles or a helmet.
- Prepare the cutting area in a manner that reduces the reflection and transmission of ultraviolet light:
 - Paint walls and other surfaces with dark colors to reduce reflection.
 - Install protective screens or curtains to reduce ultraviolet transmission.

Skin Protection

- Wear protective clothing to protect against burns caused by ultraviolet light, sparks and hot metal:
 - Gauntlet gloves, safety shoes and hat.
 - Flame-retardant clothing which covers all exposed areas.
 - Cuffless trousers to prevent entry of sparks and slag.

Toxic Fume Prevention

- Keep the cutting area well ventilated.
- Remove all chlorinated solvents from the cutting area before cutting. Certain chlorinated solvents decompose when exposed to ultraviolet radiation to form phosgene gas.
- Wear proper breathing mask and use proper ventilation when cutting galvanized metal.
- Do not cut containers with toxic materials inside. Clean containers that have held toxic materials thoroughly before cutting.



WARNING — Toxic Fumes

Do not cut metal or painted metals containing zinc, lead, cadmium or beryllium unless the operator, or anyone else subjected to the fumes, wears respiratory equipment or an air-supplied helmet.



Fire Prevention



- Make fire extinguishers available in the cutting area.
- Remove all combustible materials from the immediate cutting area to a distance of at least 35 feet (10 m).
- Quench freshly cut metal or allow metal to cool before handling it or bringing it into contact with combustible materials.
- Never use a plasma system to cut containers with potentially flammable materials inside. Such containers must be thoroughly cleaned prior to cutting.
- Ventilate potentially flammable atmospheres before cutting with a plasma system. When cutting with oxygen as the plasma gas, an exhaust ventilation system is required.
- Never operate the plasma system in an atmosphere which contains heavy concentrations of dust, flammable gas or combustible liquid vapors unless properly vented.

Electric Shock Prevention



All Hypertherm plasma systems use high voltage (up to 300 VDC) to initiate the plasma arc. Take the following precautions when operating the plasma system:

- Wear insulated gloves and boots, and keep body and clothing dry.
- Do not stand, sit or lie on—or touch—any wet surface when using the plasma system.
- Maintain proper insulation against electrical shock. If you must work in or near a damp area, use extreme caution.
- Provide a wall-mounted disconnect switch with properly sized fuses close to the power supply. This switch allows the operator to turn the power supply off quickly in an emergency situation.
- Conform to all local electrical codes for primary wiring sizes and types.
- Inspect the primary power cord frequently for damage or cracking of the cover. Bare wiring can kill. Do not use a system with a damaged power cord. Replace a damaged power cord immediately.
- Inspect the torch leads. Replace if frayed or damaged.
- Do not pick up the workpiece, including the waste cutoff, while you cut. Leave the workpiece in place or on the workbench with the work cable attached during the cutting process.

Electric Shock Prevention (continued)

- Before changing the torch parts, disconnect the main power or unplug the power supply. After changing torch parts and replacing the retaining cap, plug in the power supply again.
- Never bypass or shortcut the safety interlocks.
- Before removing a power supply cover for maintenance, disconnect the main power at the wall disconnect switch or unplug the power supply. To avoid exposure to severe electrical hazard, wait five minutes after disconnecting the main power to allow capacitors to discharge.
- Never operate the plasma system unless the power supply unit covers are in place. Exposed power supply connections present a severe electrical hazard.
- Never use a cylinder that is not upright and secured in place.
- Never move or transport a cylinder without its protective valve cover in place.
- Never use a gas cylinder or its contents for any purpose other than that for which it is intended.
- Never lubricate cylinder valves with oil or grease.
- Never allow electrical contact between the plasma arc and a cylinder.
- Never expose cylinders to excessive heat, sparks, slag or open flame.
- Never use hammers, wrenches or other tools to open stuck cylinder valves.

Explosion Prevention



WARNING — Compressed Gas

The plasma system uses compressed gas. Observe proper precautions when handling and using compressed gas equipment and cylinders.

- Do not use the plasma system if explosive dust or vapors may be present.
- Do not cut pressurized cylinders or any closed container.



WARNING — Hydrogen Explosion Hazard

If your system uses hydrogen, remember that this is a flammable gas that presents an explosion hazard. Keep flames away from cylinders containing hydrogen mixtures and hoses that carry hydrogen mixtures. Also, keep flames and sparks away from the torch when using argon-hydrogen as the plasma gas.



WARNING — Hydrogen Detonation with Aluminum Cutting

When cutting aluminum underwater, or with the water touching the underside of the aluminum, free hydrogen gas may collect under the workpiece and detonate during plasma cutting operations.

Installing an aeration manifold on the floor of the water table is an effective way to eliminate the possibility of hydrogen detonation when cutting aluminum. Refer to the Appendix section of this manual for instructions on how to fabricate an aeration manifold.

Compressed Gas Cylinders

Handle and use compressed gas cylinders in accordance with safety standards published by the U.S. Compressed Gas Association (CGA), American Welding Society (AWS), Canadian Standards Association (CSA) or applicable national or local codes.

- Never use a cylinder that leaks or is physically damaged.

Hoses

- Label and color-code all gas hoses in order to clearly identify the type of gas in each hose. Consult applicable national or local codes.
- Never use the oxygen hose for any gas other than oxygen.
- Examine hoses at regular intervals for leaks, wear, loose connections or other hazard.
- Replace hose that is damaged in any way.

Hoses (continued)

- Keep hose lengths to a minimum to prevent damage, reduce pressure drop and to prevent possible flow restrictions.
- Prevent kinking by laying out hoses as straight as possible between termination points.
- Coil any excess hose and place it out of the way to prevent damage and to eliminate the danger of tripping.

Noise Protection



The plasma cutting process can generate high levels of noise. Depending on the arc current, material being cut, acoustics and size of the cutting room, distance from the torch and other factors, acceptable noise levels as defined by national or local codes may be exceeded by your plasma system.

- Always wear proper ear protection when cutting or gouging with the plasma system.

Grounding

Input Power

- Be sure to connect the power cord ground wire to the ground in the disconnect box.
- If installation of the plasma system involves connecting the power cord to the power supply, be sure to properly connect the power cord ground wire. Conform to Canadian Standards Association (CSA) standards by placing the power cord ground wire on the stud first; then place any other ground wires on top of the power cord ground. Fasten the retaining nut tightly.
- Tighten all electrical connections to avoid excessive heating.

Work Cable

- Attach the work cable securely to the workpiece or the work table by making good metal-to-metal contact.
Do not connect it to the piece that will fall away when the cut is complete.

Work Table

- Connect the work table to a high-quality earth ground, in accordance with the U.S. National Electrical Code, Article 250, Section H, Grounding Electrode System, or other appropriate national or local codes.

Safety Reminders

- Never bypass or shortcut the safety interlocks on any of the plasma system units.
- Except in Hypertherm's largest mechanized systems, all Hypertherm torches are designed with a safety interlock that prevents firing of the plasma arc when the retaining cap is loosened.
- Each Hypertherm plasma system is designed to be used only with specific Hypertherm torches. Do not substitute other torches which could overheat and present a potentially dangerous situation to the operator and any personnel in the area. Hypertherm's warranty does not cover problems caused by the use of torches not made by Hypertherm.
- Use only consumable parts and replacement parts made by Hypertherm. Hypertherm's warranty does not cover problems caused by the use of parts not made by Hypertherm.
- Never operate the plasma system with any of its covers not in place. This would be hazardous to the operator and other people in the area, and prevents the proper cooling of the equipment.

Electronic Health Support Equipment

Plasma arc cutting and gouging systems create electric and magnetic fields that may interfere with the correct operation of electronic health support equipment, such as pacemakers or hearing aids. Any person who wears a pacemaker or hearing aid should consult a doctor before operating or being near any plasma system when it is in use. To minimize exposure to EMF:

- Keep both the work cable and the torch lead on one side of your body. Keep your body from coming in between the torch lead and the work cable.
- Route torch leads as close as possible to work cable.
- Do not wrap the torch lead or work cable around your body.
- Stay as far away from the power supply as possible.

Section 2

SPECIFICATIONS

SYSTEM COMPONENTS

See the block diagram in **Section 3** for details of the system interconnections.

HT4001 Power Supply

The power supply houses four 100-amp, 15kHz choppers and an optional Torch Height Control (THC). The power supply can be connected to the H-401 or H-601 slave power supply to output up to 750 amps.

HT4001 Machine Torch

The HT4001 machine torch is a water-injection torch capable of cutting most metals from gauge to 3-inch (76 mm) thickness. To achieve consumable long life, all cuts must begin and end on the plate surface.

Remote High Frequency&Motor Valve Console (also called "High Frequency Console")

The remote high frequency and motor valve console houses the high frequency starting circuit, two water flow switches, a motorized metering valve and plasma solenoid valves that switch to allow plasma gas flow for both preflow and operation modes. Note: This console is mounted approximately 25 feet (7.6 m) from the torch.

Gas Panel

The gas panel holds metering and solenoid valves for the plasma gases, flow meters, pressure gauges for plasma gases, and a pressure gauge and flowmeter for the water supply.

Timer/Counter - Optional

The timer/counter allows the operator to monitor the number of arc starts and the cumulative time that the arc is on in hours. The arc starts can be reset.

Water Muffler - Optional

The water muffler for the HT4001 Titan system is an option which greatly improves cutting safety and pollution control capabilities. The water muffler can be used to cut above, below and at the water line. The water muffler requires an air supply and a water supply. Refer to the Water Muffler instruction manual 801730 for more detailed information.

H-401 Slave Power Supply - Optional

This unit can function as a "slave" when paralleled with the HT4001 power supply, providing up to 750 amps of current for the HT4001 system. Refer to the H-401 & H-601 instruction manual 800410 for more detailed information.

SPECIFICATIONS

Water Chiller - Optional

The water chiller for the HT4001 with Titan system is a refrigeration unit capable of reducing the water supply temperature and increasing the water pressure to the RHF&MV console. The water chiller requires a water supply and may also require a water softener. See *Water Supply Requirements* in the **Pre-Installation** section of the HT4001 instruction manual 802000. Refer also to Water Chiller Model D Instruction Manual 802410.

SPECIFICATIONS

System Requirements

Power Requirements:

Refer to HT4001 Power Supply specifications below:

Gas Requirements:

Plasma Gas Types Oxygen, Nitrogen

Gas Quality:

Oxygen 99.5%
Nitrogen 99.995%

Oxygen Gas Inlet Pressure 120 psi +/- 10 psi (8.3 bar +/- 0.7 bar)
Nitrogen Gas Inlet Pressure 150 psi +/- 10 psi (10.3 bar +/- 0.7 bar)
Air Gas Inlet Pressure (for Water Muffler) 120 psi (8.3 bar)

Water Requirements:

Water Flow 2.5 gpm (9.5 l/m) to RHF&MV console
Water Inlet Pressure 150 psi (10.3 bar) to RHF, gas console & MV console

HT4001 Power Supply

Maximum OCV (U_o) 361 VDC
Maximum Output Current (I_o) 400 A
Output Voltage (U_o) 80-200 VDC
Duty Cycle Rating (X) 100% @ 40°C at 400 A and 200 V
Ambient Temperatures/Duty Cycle Power supplies will operate between +14° and 104°F (-10° and +40°C).
Power supplies operated in an ambient temperature above 86°F (30°C) may show some decrease in duty cycle.
Power Factor ($\cos\phi$) 0.94
Cooling Forced Air (Class F)

HT4001 Power Supply Input Power: (U_i - Input voltage; I_i - Input current)

077002 with THC / 077016 without THC 200 VAC (U_i), 3Ø, 50-60 Hz @ 257A (I_i)
220 VAC (U_i), 3Ø, 50-60 Hz @ 234A (I_i)
077003 with THC / 077017 without THC 380 VAC (U_i), 3Ø, 50-60 Hz @ 135A (I_i)
415 VAC (U_i), 3Ø, 50-60 Hz @ 124A (I_i)
077004 with THC / 077018 without THC 240 VAC (U_i), 3Ø, 60 Hz @ 214A (I_i)
480 VAC (U_i), 3Ø, 60 Hz @ 107A (I_i)
077005 with THC / 077019 without THC 575 VAC (U_i), 3Ø, 60 Hz @ 89A (I_i)
600 VAC (U_i), 3Ø, 60 Hz @ 86A (I_i)

Dimensions and Weight:

Width 34" (863 mm)
Maximum Height 51" (1295 mm); 63" (1600 mm) on 200/220V units
Maximum Depth 48-11/16" (1236 mm)
Weight 1800 lbs (817 kg)

HT4001 Power Supply - with Slave

| | |
|--|--------------------------------|
| Maximum OCV (U_o) | 400 VDC |
| Maximum Output Current (I_o) | 760 A |
| Output Voltage (U_2) | 80-200 VDC |
| Duty Cycle Rating (X) | 100% @ 40°C at 760 A and 200 V |

See the H-401 & H-601 instruction manual 800410 for further specifications on the slave power supply.

PAC620 Machine Torches

| | |
|--|---|
| Maximum cutting thickness | See Cut Charts for details. |
| Maximum current at 100% duty cycle | 760 A |
| Plasma Gas Flow | Oxygen - 114 scfh (54 l/min) Nitrogen - 223 scfh (105 l/min) |
| Injection Water Flow Rate | 0.38 to 0.48 gpm (1.4 to 1.8 l/min) |
| Water coolant flow rate (max.) | 1.7 gpm (6.4 l/min) |

Dimensions and Weight:

| | |
|----------------|---|
| Diameter | 2" (50 mm) |
| Length | 17.15" (435 mm) standard; 15.37" (390 mm) bevel |
| Weight | 3-1/2 lbs (1.58 kg) |




Figure 2-1 PAC620 Standard Torch Assembly with Dimensions




Figure 2-2 PAC620 Bevel Torch Assembly with Dimensions

SPECIFICATIONS

Remote High Frequency & Motor Valve (RHF&MV) Console

Dimensions and Weight:

Width 20" (508 mm)
 Height 16" (406 mm)
 Depth 8.8" (223 mm)
 Weight 60 lbs (27 kg)




Figure 2-3 Mounting Dimensions - RHF&MV Console

Gas Panel

Dimensions and Weight:

Width 9" (228 mm)
 Height 34" (864 mm)
 Depth 6" (150 mm)
 Weight 24 lbs (11 kg)





Figure 2-4 Mounting Dimensions - Gas Panel

Timer/Counter - Optional

Dimensions and Weight:

| | |
|--------------|------------------|
| Width | 6-1/2" (16.5 cm) |
| Height | 2-1/2" (6.4 cm) |
| Depth | 8-5/8" (21.9 cm) |
| Weight | 3 lbs (1 kg) |

**Figure 2-5 Mounting Dimensions -
Timer/Counter**



Water Muffler - Optional

Refer to the Water Muffler Instruction Manual 801730.

Water Chiller - Optional

Refer to the Water Chiller Instruction Manual 802410.

Section 3

INSTALLATION

PRE-INSTALLATION

See the HT4001 instruction manual 802000 **Pre-installation** section for system requirements.

SYSTEM UNITS PLACEMENT


- Position all required units prior to making electrical, gas and interface connections.
- Ground all external modules in the HT4001 with Titan system to earth.
- To prevent leaks in the system, tighten all gas and water connections to the following specifications:


| Gas or water hose size | Torque Specification | | |
|---------------------------|----------------------|--------|---------|
| | lbf-in | lbf-ft | kgf-cm |
| up to 3/8" (10 mm) | 75-85 | 6.25-7 | 86-98 |
| 1/2" (13 mm) | 360-480 | 30-40 | 415-550 |

Use 2 wrenches when tightening to prevent damage to the mating component.

Use the diagram on the following 2 pages to make system interconnections. Follow the number guide on the diagram to find out specific information on each cable, hose or connection. The numbered items are detailed on the pages following the interconnection diagram.

See the HT4001 instruction manual 802000 for H-401 slave connections.





- * 1/8 NPT male adapter provided for plasma supply hose
- ** 1/8 NPT inert adapter provided for plasma supply hose

Figure 3-1 HT4001 with Titan Interconnection Diagram

INSTALLATION


POWER SUPPLY CONNECTIONS

Note: All leads between the power supply and the RHF&MV console can be ordered as a 60-foot (18.3 m) package under one number - 128222.

① Negative Lead - Power Supply (PS) to RHF&MV Console

Note: Two negative leads are needed when using the slave power supply.
See Appendix A in instruction manual 802000 for connections and information.


| ① | Part No. | Length |
|---|----------|----------------|
| | 123316 | 60 ft (18.3 m) |



② Positive Lead - PS to Work Table

Note: Two positive leads are needed when using the slave power supply.
See Appendix A in instruction manual 802000 for connections and information.

| ② | Part No. | Length |
|---|----------|----------------|
| | 023382 | 15 ft (4.6 m) |
| | 023136 | 20 ft (6.1 m) |
| | 023078 | 25 ft (7.6 m) |
| | 023101 | 30 ft (9.2 m) |
| | 023135 | 40 ft (12.2 m) |
| | 023079 | 50 ft (15 m) |
| | 123316 | 60 ft (18.3 m) |




③ Nozzle Lead - PS to RHF&MV Console

| ③ | Part No. | Length |
|---|----------|----------------|
| | 123327 | 60 ft (18.3 m) |




④ RHF Cable - PS to RHF&MV Console

| ④ | Part No. | Length |
|---|----------|----------------|
| | 123314 | 60 ft (18.3 m) |



| From 1X1 | To 2X1 | Signal | From 1X1 | To 2X1 | Signal |
|----------|--------|---------------------|----------|--------|-----------------------|
| 34 | 1 | Door Interlock | 10 | 10 | FS2 Injection Water |
| 35 | 4 | Door Interlock | 11 | 13 | FS2 Injection Water |
| 36 | | Shield | 12 | | Shield |
| 4 | 2 | SV6 Injection Water | 1 | 12 | FL1 to T1 / HV Xfrmer |
| 8 | 5 | SV6 Injection Water | 2 | 15 | FL1 to T1 / HV Xfrmer |
| 9 | | Shield | 3 | | Shield |
| 23 | 7 | FS1 Cooling Water | | | |
| 24 | 8 | FS1 Cooling Water | | | |
| 25 | | Shield | | | |

5 Gas Panel Cable - PS to Gas Panel




| Part No. | Length |
|----------|------------------|
| 023496 | 50 ft (15 m) |
| 023497 | 75 ft (23 m) |
| 023498 | 100 ft (30.5 m) |
| 123067 | 110 ft (33.6 m) |
| 123087 | 125 ft (38.1 m) |
| 023499 | 150 ft (46 m) |
| 123031 | 170 ft (51.9 m) |
| 023500 | 200 ft (62 m) |
| 023812 | 250 ft (76.3 m) |
| 023819 | 300 ft (91.5 m) |
| 023576 | 350 ft (106.8 m) |

| From 1X2 | To 3X1 | Signal |
|----------|--------|--|
| 29 | 29 | SV5/Plasma OFF |
| 30 | 30 | SV5/Plasma OFF |
| 34 | 34 | Gnd |
| 5 | 5 | S1/O ₂ , N ₂ Select |
| 6 | 6 | S1/O ₂ , N ₂ Select |
| 1 | 1 | Gnd |
| 2 | 2 | S2/Test Preflow |
| 3 | 3 | S2/Test Preflow |
| 7 | 7 | Gnd |
| 8 | 8 | S2/Test Cut Flow |
| 9 | 9 | S2/Test Cut Flow |
| 4 | 4 | Gnd |
| 16 | 16 | SV4A/Cut Flow |
| 17 | 17 | SV4A/Cut Flow |
| 10 | 10 | Gnd |
| 23 | 23 | SV4B/Preflow |
| 24 | 24 | SV4B/Preflow |
| 25 | 25 | Gnd |
| 11 | 11 | SV2, SV3/O ₂ , N ₂ Preflow |
| 12 | 12 | SV2, SV3/O ₂ , N ₂ Preflow |
| 18 | 18 | Gnd |
| 35 | 35 | SV1A/Plasma O ₂ Cut Flow |
| 36 | 36 | SV1A/Plasma O ₂ Cut Flow |
| 31 | 31 | Gnd |
| 19 | 19 | SV1B/Plasma N ₂ Cut Flow |
| 20 | 20 | SV1B/Plasma N ₂ Cut Flow |
| 13 | 13 | Gnd |
| 14 | 14 | PS1, PS2/Plasma Pressure |
| 15 | 15 | PS1, PS2/Plasma Pressure |
| 21 | 21 | Gnd |
| 26 | 26 | S3, Increase/Decrease |
| 27 | 27 | S3, Increase/Decrease |
| 28 | 28 | Gnd |
| 32 | 32 | LT1 DC On |
| 33 | 33 | LT1 DC On |
| 37 | 37 | Gnd |

INSTALLATION

⑥ Machine I/O Interface Cable - PS to Machine Interface



| Part No. | Length | Part No. | Length |
|----------|-----------------|----------|-----------------|
| 023892 | 25 ft (7.5 m) | 123089 | 125 ft (38.1 m) |
| 023893 | 50 ft (15 m) | 023896 | 150 ft (46 m) |
| 023894 | 75 ft (23 m) | 123033 | 170 ft (51.9 m) |
| 023895 | 100 ft (30.5 m) | 023897 | 200 ft (61 m) |
| 123069 | 110 ft (33.6 m) | | |

| From 1X6 | COLOR | To Mach. End Terminal | Description and Comments |
|----------|--------|-----------------------|--|
| 1 | Wht | 87 | Hold (12VDC) Signal. Synchronizes starting of 2 or more systems. Closed=ON; Open=OFF |
| 5 | Blk | 86 | Hold - Common |
| 10 | Shield | Cut | Hold - Shield |
| 2 | Yel | 173 | Initial Height (12VDC) Signal. Closed=OFF ; Open=ON |
| 6 | Blk | 174 | Initial Height - Common |
| 11 | Shield | Cut | Initial Height - Shield. |
| 3 | Brn | 171 | Auto Height (12VDC) Signal. Closed=OFF; Open=ON or Corner (12VDC) |
| 7 | Blk | 172 | Auto Height - Common |
| 12 | Shield | Cut | Auto Height - Shield |
| 9 | Blu | 82 | Plasma Start (24VAC) - Signal. Close=Start |
| 15 | Blk | 83 | Plasma Start - Signal. |
| 14 | Shield | Cut | Plasma Start - Shield. |
| 22 | Red | 77 | Upper Limit Switch, Hot. Normally closed. Open when fully retracted. |
| 21 | Wht | 76 | Upper Limit Switch, Neutral. |
| 20 | Shield | Cut | Upper Limit Switch, Shield. |
| 28 | Yel | 80 | Plasma Emergency Stop (24VAC) Signal. Closed =stop. |
| 33 | Red | 81 | Plasma Emergency Stop - Signal |
| 27 | Shield | Cut | Plasma Emergency Stop - Shld |
| 34 | Red | 169 | †Down Relay, Load (Solid state, rated to switch 24 to 120VAC, 1amp. DC relay optional) Closed=Down |
| 29 | Blk | 170 | Down Relay, Line |
| 23 | Shield | Cut | Down Relay, Shield |
| 35 | Gm | 167 | †Up Relay, Load (Solid state, rated to switch 24 to 120VAC, 1amp. DC relay optional) Closed=Up |
| 30 | Blk | 168 | Up Relay, Line |
| 24 | Shield | Cut | Up Relay, Shield |
| 36 | Red | 84 | †*Arc Xfer Output - Signal Contact closes after arc transfer and time delay. Dry contact relay. |
| 31 | Blu | 85 | *Arc Xfer Output - Signal |
| 25 | Shield | Cut | *Arc Xfer Output - Shield |
| 37 | Red | 79 | **Arc Voltage Isolated + Divided (1/100) Signal |
| 32 | Gm | 78 | **Arc Voltage Isolated + Divided (1/100) Sig |
| 26 | Shield | | **Arc Voltage Isolated + Divided (1/100),Shld |

Notes: * Note on the μ P PCB that resistor R150 and capacitor C78 are connected in series across the contacts. In some cases one lead of R150 must be cut from the control PC board as the R-C circuit may provide enough current flow to maintain machine motion input to cutting machine.

** Note on the μ P PCB that resistor R155 and capacitor C79 are connected in series across the contacts. In some cases one lead of R155 must be cut from the control PC board as the R-C circuit may provide enough current flow to maintain machine motion input to cutting machine.




†WARNING



When installing or servicing the HT4001, AC or DC line voltages may be present on the UP, DOWN and TRANSFER signals even if the power supply line disconnect switch is OFF. Make certain that all line disconnect switches relating to the HT4001 system are OFF during installation and when servicing.

7 Machine V/C Interface Cable - PS to Machine Interface




| Part No. | Length | Part No. | Length |
|----------|----------------|----------|-----------------|
| 023902 | 6 ft (1.8 m) | 023855 | 75 ft (23 m) |
| 023851 | 15 ft (4.5 m) | 023856 | 100 ft (30.5 m) |
| 023852 | 25 ft (7.5 m) | 023903 | 125 ft (38 m) |
| 023853 | 35 ft (10.6 m) | 023857 | 150 ft (46 m) |
| 023854 | 50 ft (15 m) | 023858 | 200 ft (61 m) |

| From 1X7 | COLOR | Description |
|----------|-----------------|---------------|
| 1 | Black | Current 5 |
| 2 | Wht | Current 10 |
| 3 | Red | Current 20 |
| 4 | Green | Current 40 |
| 5 | Orange | Current 80 |
| 6 | Blue | Current 100 |
| 7 | White/Black | Current 200 |
| 8 | Red/Black | Current 400 |
| 9 | Green/Black | Current 800 |
| 10 | Shield | Shield |
| 11 | Blue/Black | Current ICom |
| 12 | Black/White | spare |
| 13 | Red/White | spare |
| 14 | Green/White | Voltage V1.25 |
| 15 | Blue/White | Voltage V2.5 |
| 16 | Black/Red | Voltage V5 |
| 17 | White/Red | Voltage V10 |
| 18 | Orange/Red | Voltage V20 |
| 19 | Blue/Red | Voltage V40 |
| 20 | Red/Green | Voltage V80 |
| 21 | Orange/Green | Voltage V100 |
| 22 | Black/White/Red | Voltage V200 |
| 23 | White/Black/Red | Voltage VCom |

8 Timer/Counter Cable - PS to Timer/Counter

Pass the timer/counter cable through one of the 2" bushings in the lower rear of the HT4001 power supply and connect to TB3. TB3 is located on the inside rear wall of the power supply.




| Part No. | Length |
|----------|-----------------|
| 023789 | 10 ft (3 m) |
| 023790 | 25 ft (7.5 m) |
| 023791 | 50 ft (15 m) |
| 023792 | 75 ft (23 m) |
| 023793 | 100 ft (30.5 m) |
| 123063 | 110 ft (33.6 m) |
| 123083 | 125 ft (38.1 m) |
| 023794 | 150 ft (46 m) |
| 123027 | 170 ft (51.9 m) |

| From PS TB3 | Color | To Timer/Cntr 11X1 | Description |
|-------------|-------|--------------------|-------------------|
| 53 | Wht | 1 | Starts & Arc Time |
| 52 | Black | 2 | Starts & Arc Time |
| 8 | Drain | 3 | Drain |
| 50 | Red | 15 | Error Counter |
| 51 | Black | 16 | Error Counter |
| 3 | Drain | 12 | Drain |

INSTALLATION

9 Water Muffler Air Control Cable - PS to Water Muffler Air Control Box

See water muffler instruction manual IM173 for remaining connections to water muffler and detailed information on the water muffler system.



| From 1X11 | Color | To WM Air Cntrl 10X1 | Signal |
|-----------|-------|----------------------|--------------------|
| 11 | Wht | 1 | Water Muffler Hot |
| 12 | Black | 2 | AC Neutral |
| 13 | Red | 3 | Contactoer Coil |
| 14 | Brown | 4 | Water Muffler Coil |
| 6 | Green | 5 | Ground |


9

| Part No. | Length |
|----------|-----------------|
| 023905 | 25 ft (7.5 m) |
| 023906 | 50 ft (15 m) |
| 023907 | 75 ft (23 m) |
| 023908 | 100 ft (30.5 m) |
| 123149 | 120 ft (36.6 m) |
| 023909 | 150 ft (46 m) |
| 123043 | 180 ft (54.9 m) |
| 023910 | 200 ft (61 m) |

10 Water Muffler Pump Cable - Power Supply to Water Muffler Pump

10


| Part No. | Length |
|----------|---------------|
| 023866 | 50 ft (15 m) |
| 023867 | 75 ft (23 m) |
| 023868 | 100 ft (30.5) |



| From 1X10 | Color | Signal |
|-----------|-------|--------------------|
| 2 | Black | Water Muffler Coil |
| 4 | White | AC Neutral |
| 3 | Green | Ground |

11 Hold cable - PS to Second HT4001 Power Supply

When using a multi-torch system, the hold cable interfaces the two HT4001 power supplies. Make connections at TB3 on both supplies. TB3 is located on the inside rear wall of the HT4001 power supply.



11

| PS1 TB3 End | Color | PS2 TB3 End | Signal |
|-------------|--------|-------------|-------------|
| 86 | Black | 86 | Hold signal |
| 87 | Red | 87 | Hold common |
| GND | Shield | GND | Hold shield |

| Part No. | Length |
|----------|-----------------|
| 023340 | 15 ft (4.5 m) |
| 023341 | 25 ft (7.5 m) |
| 023342 | 50 ft (15 m) |
| 023343 | 100 ft (30.5 m) |
| 023344 | 150 ft (46 m) |

GAS PANEL CONNECTIONS


See page 3-3 for gas panel connection to power supply.

Hoses from supply gases to the gas panel are provided by the customer.

Note: The following 20-ft length (6.1 m) hoses and cable between the gas panel and the RHF&MV console can be ordered as a package with one number - 128224.

⑫ Injection Water Hose - Gas Panel to RHF&MV Console


Note: Turn counterclockwise to tighten



| Part No. | Length |
|----------|---------------|
| 024018 | 20 ft (6.1 m) |


⑬ Plasma Preflow Gas Hose - Gas Panel to RHF&MV Console

Note: Turn counterclockwise to tighten



| Part No. | Length |
|----------|---------------|
| 024308 | 20 ft (6.1 m) |

⑭ Plasma Cut Flow Gas Hose - Gas Panel to RHF&MV Console



| Part No. | Length |
|----------|---------------|
| 024017 | 20 ft (6.1 m) |

⑮ Gas Panel/RHF&MV Console Cable - Gas Panel to RHF&MV Console



| Part No. | Length |
|----------|---------------|
| 023647 | 20 ft (6.1 m) |

| From 3X2 | To 4X1 | Signal |
|----------|--------|----------------------|
| 16 | 16 | SV4A Preflow/Cutflow |
| 17 | 17 | SV4A Preflow/Cutflow |
| 10 | 10 | Ground |
| 23 | 23 | SV4B Preflow/Cutflow |
| 24 | 24 | SV4B Preflow/Cutflow |
| 25 | 25 | Ground |
| 29 | 29 | SV5 Plasma Off |
| 30 | 30 | SV5 Plasma Off |
| 34 | 34 | Ground |
| 11 | 11 | MV1 Decrease |
| 12 | 12 | 120VAC Neut. |
| 18 | 18 | Ground |
| 14 | 14 | MV1 Increase |
| 21 | 21 | Ground |

INSTALLATION

RHF&MV CONSOLE CONNECTIONS


See pages 3-2 and 3-3 for RHF&MV console connections to the power supply and gas panel.

16 Cooling Hose Set- RHF Console to Water Cooling System

There are two 3/8" hoses with #6 swivel connectors in this hose set. For two-torch systems, double the hose order.

Caution: Connect WATER OUT on the RHF&MV console to RETURN on the water chiller, and connect WATER IN on the RHF&MV console to DISCHARGE on the water chiller.

See the water chiller instruction manual 802410 for details.



| Part No. | Length | Part No. | Length |
|----------|----------------|----------|-----------------|
| 028652 | 10 ft (3 m) | 028444 | 100 ft (30.5 m) |
| 028440 | 15 ft (4.5 m) | 028902 | 110 ft (33.6 m) |
| 028653 | 20 ft (6 m) | 028896 | 115 ft (35.1 m) |
| 028441 | 25 ft (7.5 m) | 128129 | 120 ft (36.6 m) |
| 128173 | 35 ft (10.5 m) | 028747 | 125 ft (38.1 m) |
| 028442 | 50 ft (15 m) | 028445 | 150 ft (46 m) |
| 128052 | 60 ft (18 m) | 128064 | 170 ft (51.9 m) |
| 028443 | 75 ft (23 m) | 028637 | 200 ft (61 m) |
| 128078 | 85 ft (25.9 m) | | |

TORCH CONNECTIONS


See page 3-1 for torque specifications

Routing the Torch Leads

Prior to connecting the torch leads to the RHF&MV console, gas panel and torch, the torch leads must be routed between the cutting machine, RHF&MV console and the torch. You will generally need to route the leads through a festoon or a power track.

Caution: Before routing the leads, make sure the torch is removed from the torch leads. Damage to the torch could result from dropping, banging, or scraping. Once the torch leads have been routed, proceed with torch connections.

17 Injection Water Hose - Gas Console to Torch



| Part No. | Length | Part No. | Length |
|----------|----------------|----------|-----------------|
| 024033 | 15 ft (4.5 m) | 024208 | 45 ft (13.7 m) |
| 024018 | 20 ft (6 m) | 024258 | 50 ft (15 m) |
| 024034 | 25 ft (7.5 m) | 024179 | 53 ft (16 m) |
| 024035 | 30 ft (9 m) | 024128 | 60 ft (18 m) |
| 024036 | 35 ft (10.5 m) | 024345 | 75 ft (23 m) |
| 024037 | 40 ft (12.2 m) | 024346 | 100 ft (30.5 m) |


1. Slide the injection water hose through the torch insulating sleeve.
2. Using a 7/16" open-end wrench on the left-handed torch fitting and a 7/16" open-end wrench on the left-handed injection water hose fitting, turn the water-hose fitting in a counterclockwise direction to tighten.
3. Make injection water hose connection at gas panel.

The following shielded torch leads, plasma gas hose, off-valve cable, off-valve hose, and off valve with torch can be ordered as a 25-foot (7.5 m) package under one number: 128256 for the standard torch or 128257 for the beveling torch

⑱ Shielded Torch Leads - RHF&MV Console to Torch

⑱

| Part No. | Length |
|----------|---------------|
| 028511 | 25 ft (7.5 m) |



1. Slide the shielded torch leads through the insulating sleeve.
2. Using a 9/16" open-end wrench on the two largest torch fittings and a 1/2" open-end wrench on the two largest lead fittings, connect the leads to the torch. Note color code on torch and torch leads.
3. Attach and **hand tighten** the white pilot arc lead from the torch leads to the corresponding connector on the torch body.





Figure 3-2 Torch Connections - 1 of 2


INSTALLATION

19 Plasma Gas Hose - RHF&MV Console to Off-Valve



| Part No. | Length |
|----------|---------------|
| 024214 | 25 ft (7.5 m) |


20 Off-Valve Cable - RHF&MV Console to Torch Off-Valve



| Part No. | Length |
|----------|---------------|
| 123315 | 25 ft (7.5 m) |

| From 4X2 | Color | To Off-Valve Connector | Signal |
|----------|-------|------------------------|-------------------|
| 1 | Black | 1 | Plasma Off & Vent |
| 2 | Red | 2 | Plasma Off & Vent |
| 3 | N/A | Cut | Drain |
| 4 | Clear | Ground | Ground |

21 Off-Valve Hose - Off-Valve to Torch



| Part No. | Length |
|----------|--------------|
| 024317 | 5 ft (1.5 m) |

1. Connect one end of the off-valve hose to the remaining lead fitting of the torch. Use 7/16" open-end wrenches to tighten this connection. (Fig. 3-3, 2 of 2)
2. Slide the insulating sleeve over the torch body and screw together.
3. Connect the other end of the off-valve hose to the off valve. (Fig. 3-3, 2 of 2)
4. Connect the other end of the plasma gas hose to the off valve. (Fig. 3-3, 2 of 2)
5. Connect the off-valve cable to the off valve. (Fig. 3-3, 2 of 2)
6. Attach the torch to the torch mounting bracket. See *Mounting the Machine Torch* on page 3-13.




Figure 3-3 Torch Connections -2 of 2

MOUNTING THE MACHINE TORCH

1. Loosen the securing screws and install the machine torch (with torch leads attached) in the torch mounting bracket. See Figure 3-4.
2. Position the torch until the torch body extends all the way through the bracket, so that the bracket is now around the plastic torch sleeve and not touching the stainless steel torch body. Position the torch approximately 0.25 " (6 mm) from the work surface.
3. Tighten the securing screws.




Figure 3-4 Torch Alignment

Torch Alignment

Prior to cutting with the machine torch, ensure that the torch is at right angles to the workpiece to get a clean, vertical cut. Use a square to align the torch. The torch should be aligned at 0° and 90°. See Figure 3-4.

Section 4

OPERATION

Refer to HT4001 Instruction manual 802000 for explanation of power supply and timer/counter front panel controls and indicators.

OPERATION

FRONT PANEL CONTROLS AND INDICATORS

HT4001 Titan Gas Panel (Fig. 4-1)




Figure 4-1 HT4001 Titan Gas Panel Controls and Indicators

DAILY START-UP

Prior to start-up, ensure that your cutting environment and your clothing meet the safety requirements outlined in the *Safety* section of this manual. If problems occur during start-up, refer to **Section 3** for installation requirements.



WARNING




Before operating this system, you must read the *Safety* section thoroughly! Turn main disconnect switch to the HT4001 power supply OFF before proceeding with the following steps

Check Torch

1. Remove the consumables from the torch and check for worn or damaged parts. **Always place the consumables on a clean, dry, oil free surface after removing. Dirty consumables can cause the torch to malfunction.**
 - Check the pit depth of the electrode using the electrode gauge assembly. The electrode should be replaced when the depth exceeds .050 inch (1.3 mm).
 - Wipe the current ring in the torch with a clean paper towel or Q-tip.
 - Refer to the *Cut Charts* later in this section to choose the correct consumables for your cutting needs.
2. Replace consumable parts. Refer to *Changing Consumable Parts* later in this section for detailed information on replacing consumables.
3. Ensure that the torch is squared to the material. Refer to **Section 3: Installation** for the torch alignment procedure.

Turn Gases and Water On




4. Set S2 toggle switch on the gas panel to RUN.
5. Set the main disconnect switches for the power supply and the water chiller to ON.
6. Set S1 on the gas panel to N₂ or O₂.
7. Turn the required supply gases On.
 - When using nitrogen as the plasma gas, adjust supply regulator to read 150 psi +/- 10 psi (10.3 bar +/- 0.7 bar) at the N₂ pressure gauge on the gas panel.
 - When using oxygen as the plasma gas, adjust supply regulator to read 120 psi +/- 10 psi (8.3 bar +/- 0.7 bar) at the O₂ pressure gauge on the gas panel.
8. Turn the water supply to the water chiller ON.
9. Turn on the water chiller by depressing the START switch.

OPERATION

Turn Power Supply On and Adjust Voltage/Current

10. Turn on the power supply by moving the POWER circuit breaker on the rear of the power supply to the UP position. Ensure that the POWER AC indicator on the power supply illuminates. If the POWER ON light fails to illuminate, see **Section 3: Installation** for proper setup.
11. Set the voltage and current. Select the arc current and arc voltage from the *Cut Charts* for the type and thickness of metal to be cut.

Note: If using the H-401 power supply as a slave and you need to reduce the existing arc current level, lower the current to below 360A before resetting to the desired value. Note also that the current control adjust knob on the front of the H-401 supply will have no effect on setting current for the slave.



Adjust Preflow Gases

12. Set S2 on the gas panel to TEST PREFLOW. Set the preflow flow rates on the N₂ (FM1) and/or O₂ (FM2) flow meters using the MV2 and/or MV3 metering valves. Select the test preflow rates from the *Cut Charts*.

Note: If you have changed consumable parts or if the power supply has been off for more than 1 hour, purge gas lines by leaving the system in TEST PREFLOW for 1 minute.

Adjust Cut Flow Gases and Water Injection Flow Rate

13. Set S2 on the gas panel to TEST CUT FLOW.
14. Set the cut flow rate on the N₂ or O₂ flow meters using the S3 cut flow momentary switch. Select the cut flow rates from the *Cut Charts*.

Note: If you have changed consumable parts or if the power supply has been off for more than 1 hour, purge gas lines by leaving system in TEST CUT FLOW for 1 minute.

15. Check the water flow rate at the water flow meter (FM3) and adjust with the MV4 metering valve. See the *Cut Charts* for water flow rates.
16. Verify that there is a uniform conical water pattern at the front of the torch. If the pattern is irregular, shut the power supply down at the main disconnect switch and check the nozzle and swirl ring. Replace with new parts, if they are worn or damaged.
17. Set S2 to RUN after the test preflow and test operate flow rates have been set.

The system is now ready for operation.

CUTTING TECHNIQUES

The *Cut Charts* in this section display parameters to provide the best cut angle, least dross and best cut surface finish. The following suggestions serve to explain certain cut conditions and how they can be improved upon or avoided.

How to Get Better Cut Quality

In order to get the best cut quality, verify that the HT4001 Titan system is set up properly. The 3 major components of cut quality are: cut angle, dross conditions, and shape of cut surface.

Cut Angle

Cut angle is defined as either positive or negative. A positive cut angle is when there is more material removed from the top of the kerf than from the bottom of the kerf (V-shaped cut). A negative cut angle is when there is more material removed from the bottom of the cut than from the top of the kerf (under cut). The 2 most common cut angle faults are: cuts not acceptably square, and non-uniform cut angles (one side positive and one side negative). Causes and possible solutions are listed below.

1. Cuts not acceptably square (greater than 5° angle on all sides):

- Improper torch standoff distance. A positive cut angle indicates a stand-off that is too high. A negative cut angle indicates a standoff that is too low. Vary the arc voltage to correct the cut angle.
- Damaged consumable parts. If the nozzle orifice is worn uniformly, the cut angle will show positive. Check and replace consumables, if necessary. Refer to *Changing Consumable Parts* later in this section.
- Machine travel is in the wrong direction. The square cut angle is on the right side relative to the forward motion of the torch.

2. Non-uniform cut angles:

- Damaged or worn nozzle and/or shield. Check and replace consumables, if necessary. Refer to *Changing Consumable Parts* later in this section.
- The torch out of vertical alignment with the workpiece. Verify that the torch is at right angles to the workpiece in order to get a clean, vertical cut. See *Torch Alignment* in the **Installation** section.

Dross Conditions

1. Low Speed Dross

- When the travel speed is too slow, the arc shoots ahead and dross forms as a heavy bubbly deposit at the bottom of the kerf that can be easily removed. Increasing the speed will reduce this type of dross.

OPERATION

2. High Speed Dross

- When the travel speed is too fast, the arc lags behind and dross forms as a thin, linear bead of solid metal attached very close to the kerf. The dross appears to be a fused continuation of the kerf wall, is welded to the bottom of the cut, and is very difficult to remove. Reduce high speed dross by decreasing the travel speed. If this does not remove the dross, lower the torch standoff distance by decreasing arc voltage.

3. Intermittent Dross

- Can be caused by worn consumable parts
- May be material dependent
- May be dependent on metal temperature. Warm and hot metal is much more prone to dross accumulation than cool metal. For example, the first cut in a series of cuts will likely have the least amount of dross. As the workpiece heats up, dross levels are likely to increase on subsequent cuts.

Shape of the Cut Surface

The ideal shape of the cut face is straight. Sometimes the cut face becomes either concave or convex. Maintain the correct torch height and cut speed to keep the cut face straight.

1. Concave cut face (bevel on inside)

- Caused by the standoff distance being too low. Increasing the arc voltage will increase the standoff distance and straighten the cut face.

2. Convex cut face (top of cut rounded)

- Caused by the standoff distance being too high or the cutting current being too high. Try reducing the arc voltage and then reducing the cutting current.

How to Get Longer Consumable Life

In order to optimize consumable life, follow these guidelines:

1. Pierce Height

The pierce height should be twice as high as the cutting height to prevent pierce splatter from building up on the front of the nozzle and/or shield.

2. Pierce Delay

Pierce delay is determined and programmed on the machine interface. Allow enough time for the pierce to be complete before starting the machine motion.

3. Ramp Down

In order to properly ramp down gas and current to extend consumable life, the torch must end its cut while over the workpiece.

4. Extending Electrode Life

- Program the lead out when the drop part is the one wanted, but do not program the lead out into the drop part.
- Use a chain cut, if possible.
- Purge the gas lines before cutting.

5. Extending Nozzle Life

- Do not lead out to the drop part, which will cause the arc to stretch.
- Purge the gas lines to clean the plasma chamber before cutting.
- Make sure that the torch does not dive into the plate during cutting.

6. Extending Shield Life

- Make sure that the shield does not touch the plate during cutting. The pierce height should be twice as high as the cutting height.
- Keep the shield front clean to prevent double arcing.

7. Material

Attempting to cut highly magnetic metal plate will shorten consumable life. Long consumable life is difficult to achieve when cutting plate that is high in nickel content.

How to Get Better Pierces

1. Set the initial pierce height to twice the cutting height.
2. **Increase the pierce delay time.** The pierce delay must be on long enough to let the arc pierce through the material before the machine moves.

How to Increase Cutting Speed

1. **Use a higher current level.** The consumables must be changed when increasing the current.
2. **Reduce the torch standoff distance.** However, the shield must not touch the plate. The cutting surface will bevel inside if the standoff distance is too low.

OPERATION

COMMON CUTTING FAULTS

- Torch pilot arc will initiate, but will not transfer. Causes can be:
 1. Work cable connection on cutting table not making good contact.
 2. Malfunction in HT4001 Titan system.
- Workpiece is not totally penetrated, and there is excessive sparking on top of the workpiece. Causes can be:
 1. Current is set too low (check *Cut Chart* information).
 2. Cut speed is too high (check *Cut Chart* information).
 3. Torch parts are worn (see *Changing Consumable Parts*).
 4. Metal being cut is too thick.
- Dross forms on the bottom of the cut - See *Dross Conditions* earlier in this section.
- Cut angle not square - See *How to Get Better Cut Quality* earlier in this section.
- Short consumable life - See *How to Get Longer Consumable Life* earlier in this section.

TECHNICAL QUESTIONS

Claims for defective merchandise -- If your system does not function correctly:

1. Re-check all pre-installation and installation requirements and connections.
2. If you are unable to solve the problem, call your distributor. He or she will be able to help you, or refer you to an authorized Hypertherm repair facility.
3. If you need additional assistance, call Customer Service at 1-800-737-2978 or Technical Service at 1-800-643-9878.

CUT CHARTS

The Cut Charts on the following pages are optimized to provide the best cut angle, least dross and best cut surface finish. Keep in mind that the charts provide a good starting point and that optimum cutting must be tuned to the application and materials on site. Increasing cut speed, lowering the torch standoff, for example, all present certain trade-offs. Depending on the cutting application, it is up to the operator to determine if the trade-offs are acceptable.

Caution: Before cutting, check all settings and adjustments and check for damaged torch parts and worn consumable parts.

HT4001 without Slave - CUT CHART AND CONSUMABLE PARTS INDEX

| Consum. Type | Metal | Amps | Plasma Gas | Retaining Cap | Nozzle | Swirl Ring | Electrode | Page |
|---|------------------|------|------------|---------------|--------|------------|-----------|------|
| * S T A N D A R D | Mild Steel | 260 | Oxygen | 020579 | 020086 | 020623 | 020663 | 4-10 |
| | | 340 | Oxygen | 020579 | 020086 | 120135 | 120630 | 4-10 |
| | | 260 | Nitrogen | 020579 | 020089 | 020039 | 020082 | 4-11 |
| | | 400 | Nitrogen | 020579 | 020084 | 020039 | 020082 | 4-11 |
| | Stainless | 260 | Nitrogen | 020579 | 020089 | 020039 | 020082 | 4-12 |
| | | 400 | Nitrogen | 020579 | 020084 | 020039 | 020082 | 4-12 |
| | Aluminum | 260 | Nitrogen | 020579 | 020089 | 020039 | 020082 | 4-13 |
| | | 400 | Nitrogen | 020579 | 020084 | 020039 | 020082 | 4-13 |
| ** B E V E L | Mild Steel | 260 | Oxygen | 120390 | 120384 | 020623 | 020975 | 4-14 |
| | | 340 | Oxygen | 120390 | 120384 | 120460 | 120836 | 4-15 |
| | Mild / Stainless | 260 | Nitrogen | 120390 | 120386 | 020039 | 020968 | 4-16 |
| | | 400 | Nitrogen | 120390 | 120387 | 020039 | 020968 | 4-16 |
| | Aluminum | 260 | Nitrogen | 120390 | 120386 | 020039 | 020968 | 4-17 |
| | | 400 | Nitrogen | 120390 | 120387 | 020039 | 020968 | 4-17 |


HT4001 with Slave - CUT CHART AND CONSUMABLE PARTS INDEX

| Consum. Type | Metal | Amps | Plasma Gas | Retaining Cap | Nozzle | Swirl Ring | Electrode | Page |
|---|------------------|------|------------|---------------|--------|------------|-----------|------|
| * S T A N D A R D | Mild / Stainless | 260 | Nitrogen | 020580 | 020281 | 020039 | 020285 | 4-18 |
| | | 400 | Nitrogen | 020580 | 020282 | 020039 | 020285 | 4-18 |
| | | 600 | Nitrogen | 020580 | 020283 | 020039 | 020285 | 4-18 |
| | | 760 | Nitrogen | 020580 | 020284 | 020040 | 020285 | 4-18 |
| | Aluminum | 260 | Nitrogen | 020580 | 020281 | 020039 | 020285 | 4-19 |
| | | 400 | Nitrogen | 020580 | 020282 | 020039 | 020285 | 4-19 |
| | | 600 | Nitrogen | 020580 | 020283 | 020039 | 020285 | 4-19 |
| | | 760 | Nitrogen | 020580 | 020284 | 020040 | 020285 | 4-19 |
| ** B E V E L | Mild / Stainless | 260 | Nitrogen | 120390 | 120386 | 020039 | 020968 | 4-20 |
| | | 400 | Nitrogen | 120390 | 120387 | 020039 | 020968 | 4-20 |
| | | 600 | Nitrogen | 120390 | 120388 | 020039 | 020968 | 4-20 |
| | | 760 | Nitrogen | 120390 | 120389 | 020040 | 020968 | 4-20 |
| | Aluminum | 260 | Nitrogen | 120390 | 120386 | 020039 | 020968 | 4-21 |
| | | 400 | Nitrogen | 120390 | 120387 | 020039 | 020968 | 4-21 |
| | | 600 | Nitrogen | 120390 | 120388 | 020039 | 020968 | 4-21 |
| | | 760 | Nitrogen | 120390 | 120389 | 020040 | 020968 | 4-21 |

* Use standard consumables with the PAC620 if the torch will only be making cuts 90° to the work surface.

** Use bevel consumables with the PAC620 if the torch will be making cuts between 45° and 90° to the work surface.

HT4001 without Slave **PAC620 Torch - Standard Consumables** Mild Steel - Oxygen Plasma



E
N
G
L
I
S
H


| Electrode | Material Thickness (in) (mm) | | Test Preflow Rate | | Test Cut Flow Rate | | Water Flow Setting (%) | Arc Volts (V) | Arc Current (A) | Torch Standoff | | Travel Speed | |
|-----------|---------------------------------|------|--------------------------|----------------------------|--------------------------|-----------|---------------------------|------------------|--------------------|----------------|-----|--------------|--|
| | | | (N ₂) (%) | & (O ₂) (%) | (O ₂) (%) | (in) (mm) | | | | (ipm) (mm/min) | | | |
| 260A | 1/4 | 6.35 | 16 | 11 | 80 | 60 | 120 | 260 | 1/8 | 3 | 170 | 4320 | |
| | 1/2 | 12.7 | 16 | 11 | 80 | 60 | 130 | 260 | 3/16 | 5 | 100 | 2540 | |
| | 3/4 | 19.1 | 16 | 11 | 80 | 60 | 135 | 260 | 3/16 | 5 | 70 | 1780 | |
| | 1 | 25.4 | 16 | 11 | 80 | 60 | 140 | 260 | 3/16 | 5 | 50 | 1270 | |
| 340A | 1/2 | 12.7 | 16 | 11 | 80 | 60 | 130 | 340 | 1/8 | 3 | 110 | 2800 | |
| | 3/4 | 19.1 | 16 | 11 | 80 | 60 | 140 | 340 | 3/16 | 5 | 85 | 2160 | |
| | 7/8 | 22.2 | 16 | 11 | 80 | 60 | 145 | 340 | 3/16 | 5 | 75 | 1900 | |
| | 1 | 25.4 | 16 | 11 | 80 | 60 | 145 | 340 | 3/16 | 5 | 65 | 1650 | |
| | 1-1/4 | 31.8 | 16 | 11 | 80 | 60 | 145 | 340 | 3/16 | 5 | 45 | 1140 | |

M
E
T
R
I
C

| Electrode | Material Thickness (mm) | Test Preflow | | Test Cut Flow | | Water Flow Setting (%) | Arc Volts (V) | Arc Current (A) | Torch Standoff (mm) | Travel Speed (mm/min) |
|-----------|----------------------------|----------------------------------|----------------------------|----------------------------------|----|------------------------------|---------------------|-----------------------|---------------------------|-----------------------------|
| | | Rate (N ₂) (%) | & (O ₂) (%) | Rate (O ₂) (%) | | | | | | |
| 260A | 8 | 16 | 11 | 80 | 60 | 125 | 260 | 3-4 | 3850 | |
| | 10 | 16 | 11 | 80 | 60 | 130 | 260 | 4 | 3300 | |
| | 12 | 16 | 11 | 80 | 60 | 130 | 260 | 4-5 | 2730 | |
| | 15 | 16 | 11 | 80 | 60 | 135 | 260 | 5 | 2260 | |
| | 20 | 16 | 11 | 80 | 60 | 135 | 260 | 5 | 1700 | |
| | 25 | 16 | 11 | 80 | 60 | 140 | 260 | 5 | 1300 | |
| 340A | 15 | 16 | 11 | 80 | 60 | 135 | 340 | 5 | 2570 | |
| | 20 | 16 | 11 | 80 | 60 | 140 | 340 | 5 | 2080 | |
| | 25 | 16 | 11 | 80 | 60 | 145 | 340 | 5 | 1680 | |
| | 30 | 16 | 11 | 80 | 60 | 145 | 340 | 5 | 1280 | |

- Notes:
- Minimum O₂ inlet pressures remain at one setting of 120 psi (8.2 bar) for all material thickness.
 - Minimum N₂ inlet pressures remain at one setting of 150 psi (10.3 bar) for all material thickness.
 - O₂ flow rate at full scale is 127 scfh (60 l/min) @ 120 psi (8.2 bar) inlet pressure.
 - N₂ flow rate at full scale is 374 scfh (176 l/min) @ 150 psi (10.3 bar) inlet pressure.
 - Water inlet pressure is 150 psi (10.3 bar) minimum to RHF, gas console & MV console.
 - Set initial torch height (before piercing) to approximately twice the Torch Standoff distance for the material you are cutting.

HT4001 without Slave **PAC620 Torch - Standard Consumables** **Mild Steel - Nitrogen Plasma**



ENGLISH


| Nozzle | Material Thickness (in) (mm) | | Test Preflow | Test Cut Flow | Water Flow Setting (%) | Arc Volts (V) | Arc Current (A) | Torch Standoff (in) (mm) | | Travel Speed (ipm) (mm/min) | |
|----------------------------------|---------------------------------|------|----------------------------------|----------------------------------|------------------------------|---------------------|-----------------------|--------------------------------|----|-----------------------------------|-------|
| | | | Rate (N ₂) (%) | Rate (N ₂) (%) | | | | | | | |
| .120" 260A max. | .035 | .889 | 30 | 30 | 45 | 125 | 260 | 1/8 | 3 | 450 | 11430 |
| | .075 | 1.91 | 30 | 30 | 45 | 130 | 260 | 1/8 | 3 | 300 | 7620 |
| | 1/8 | 3.18 | 30 | 30 | 45 | 135 | 260 | 1/4 | 6 | 200 | 5080 |
| | 1/4 | 6.35 | 30 | 30 | 45 | 145 | 260 | 5/16 | 8 | 145 | 3690 |
| .166" 400A max. | 1/8 | 3.18 | 45 | 45 | 62 | 140 | 300 | 1/4 | 6 | 175 | 4450 |
| | 1/4 | 6.35 | 45 | 45 | 62 | 140 | 360 | 1/4 | 6 | 145 | 3690 |
| | 3/8 | 9.53 | 45 | 45 | 62 | 145 | 360 | 1/4 | 6 | 125 | 3180 |
| | 1/2 | 12.7 | 45 | 45 | 62 | 150 | 400 | 1/4 | 6 | 95 | 2420 |
| | 3/4 | 19.1 | 45 | 45 | 62 | 150 | 400 | 5/16 | 8 | 50 | 1270 |
| | 1 | 25.4 | 45 | 45 | 62 | 155 | 400 | 3/8 | 10 | 30 | 760 |

METRIC

| Nozzle | Material Thickness (mm) | | Test Preflow | Test Cut Flow | Water Flow Setting (%) | Arc Volts (V) | Arc Current (A) | Torch Standoff (mm) | | Travel Speed (mm/min) | |
|-----------------------------------|----------------------------|--|----------------------------------|----------------------------------|------------------------------|---------------------|-----------------------|---------------------------|-----|-----------------------------|------|
| | | | Rate (N ₂) (%) | Rate (N ₂) (%) | | | | | | | |
| 3 mm 260A max. | 6 | | 30 | 30 | 45 | 145 | 260 | | 8 | | 3840 |
| 4.2 mm 400A max. | 6 | | 45 | 45 | 62 | 140 | 360 | | 6 | | 4660 |
| | 8 | | 45 | 45 | 62 | 145 | 360 | | 6 | | 3420 |
| | 10 | | 45 | 45 | 62 | 145 | 360 | | 6 | | 3060 |
| | 12 | | 45 | 45 | 62 | 150 | 400 | | 6 | | 2580 |
| | 15 | | 45 | 45 | 62 | 150 | 400 | | 6-7 | | 2000 |
| | 20 | | 45 | 45 | 62 | 150 | 400 | | 8 | | 1190 |
| | 25 | | 45 | 45 | 62 | 155 | 400 | | 10 | | 790 |

- Notes:
- Minimum N₂ inlet supply pressure remains at one setting of 150 psi (10.3 bar) for all material thickness.
 - Water inlet pressure is 150 psi (10.3 bar) minimum to RHF, gas console & MV console.
 - N₂ flow rate at full scale is 374 scfh (176 l/min) @ 150 psi (10.3 bar) inlet pressure.
 - Set initial torch height (before piercing) to approximately twice the Torch Standoff distance for the material you are cutting.
- Note: If arc does not transfer when set at twice the torch standoff (in the case of thick metal being cut at high current), gradually lower the initial height of the torch until transfer occurs.

HT4001 without Slave **PAC620 Torch - Standard Consumables** **Stainless Steel - Nitrogen Plasma**



E
N
G
L
I
S
H

| Nozzle | Material Thickness (in) (mm) | | Test Preflow | Test Cut Flow | Water Flow Setting (%) | Arc Volts (V) | Arc Current (A) | Torch Standoff (in) (mm) | | Travel Speed (ipm) (mm/min) | |
|---------------------------|---------------------------------|------|----------------------------------|----------------------------------|------------------------------|---------------------|-----------------------|--------------------------------|---|-----------------------------------|-------|
| | | | Rate (N ₂) (%) | Rate (N ₂) (%) | | | | | | | |
| .120" 260A max. | .035 | .889 | 30 | 30 | 45 | 125 | 260 | 1/8 | 3 | 450 | 11430 |
| | .075 | 1.91 | 30 | 30 | 45 | 130 | 260 | 1/8 | 3 | 300 | 7620 |
| | 1/8 | 3.18 | 30 | 30 | 45 | 135 | 260 | 1/8 | 3 | 200 | 5080 |
| | 1/4 | 6.35 | 30 | 30 | 45 | 145 | 260 | 1/8 | 3 | 150 | 3810 |
| .166" 400A max. | 3/8 | 9.53 | 45 | 45 | 62 | 150 | 380 | 3/16 | 5 | 125 | 3170 |
| | 1/2 | 12.7 | 45 | 45 | 62 | 155 | 400 | 3/16 | 5 | 100 | 2540 |
| | 3/4 | 19.1 | 45 | 45 | 62 | 160 | 400 | 3/16 | 5 | 50 | 1270 |
| | 1 | 25.4 | 45 | 45 | 62 | 165 | 400 | 1/4 | 6 | 30 | 760 |
| | 1-1/2 | 38.1 | 45 | 45 | 62 | 185 | 400 | 1/4 | 6 | 20 | 510 |
| | 2 | 50.8 | 45 | 45 | 62 | 200 | 400 | 1/4 | 6 | 12 | 300 |

M
E
T
R
I
C


| Nozzle | Material Thickness (mm) | | Test Preflow | Test Cut Flow | Water Flow Setting (%) | Arc Volts (V) | Arc Current (A) | Torch Standoff (mm) | | Travel Speed (mm/min) | |
|----------------------------|----------------------------|--|----------------------------------|----------------------------------|------------------------------|---------------------|-----------------------|---------------------------|-----|-----------------------------|------|
| | | | Rate (N ₂) (%) | Rate (N ₂) (%) | | | | | | | |
| 3 mm 260A max. | 6 | | 30 | 30 | 45 | 145 | 260 | | 3 | | 3950 |
| 4.2 mm 400A max. | 10 | | 45 | 45 | 62 | 150 | 380 | | 5 | | 3070 |
| | 12 | | 45 | 45 | 62 | 155 | 400 | | 5 | | 2680 |
| | 15 | | 45 | 45 | 62 | 160 | 400 | | 5 | | 2080 |
| | 20 | | 45 | 45 | 62 | 160 | 400 | | 5-6 | | 1200 |
| | 25 | | 45 | 45 | 62 | 165 | 400 | | 6 | | 790 |
| | 35 | | 45 | 45 | 62 | 180 | 400 | | 6 | | 570 |
| | 50 | | 45 | 45 | 62 | 200 | 400 | | 6 | | 310 |

- Notes:
- Minimum N₂ inlet supply pressure remains at one setting of 150 psi (10.3 bar) for all material thickness.
 - Water inlet pressure is 150 psi (10.3 bar) minimum to RHF, gas console & MV console.
 - N₂ flow rate at full scale is 374 scfh (176 l/min) @ 150 psi (10.3 bar) inlet pressure.
 - Set initial torch height (before piercing) to approximately twice the Torch Standoff distance for the material you are cutting.
- Note: If arc does not transfer when set at twice the torch standoff (in the case of thick metal being cut at high current), gradually lower the initial height of the torch until transfer occurs.

HT4001 without Slave

PAC620 Torch - Standard Consumables

Aluminum - Nitrogen Plasma



E
N
G
L
I
S
H


| Nozzle | Material Thickness (in) (mm) | | Test Preflow Rate (N ₂) (%) | Test Cut Flow Rate (N ₂) (%) | Water Flow Setting (%) | Arc Volts (V) | Arc Current (A) | Torch Standoff (in) (mm) | | Travel Speed (ipm) (mm/min) | |
|--------------------|---------------------------------|------|--|---|------------------------------|---------------------|-----------------------|--------------------------------|---|-----------------------------------|-------|
| .120" 260A max. | .035 | .889 | 30 | 30 | 45 | 125 | 260 | 1/8 | 3 | 540 | 13700 |
| | .075 | 1.91 | 30 | 30 | 45 | 130 | 260 | 1/8 | 3 | 360 | 9140 |
| | 1/8 | 3.18 | 30 | 30 | 45 | 135 | 260 | 1/8 | 3 | 240 | 6100 |
| | 1/4 | 6.35 | 30 | 30 | 45 | 145 | 260 | 1/8 | 3 | 180 | 4570 |
| .166" 400A max. | 3/8 | 9.53 | 45 | 45 | 62 | 150 | 360 | 3/16 | 5 | 150 | 3800 |
| | 1/2 | 12.7 | 45 | 45 | 62 | 155 | 380 | 3/16 | 5 | 120 | 3050 |
| | 3/4 | 19.1 | 45 | 45 | 62 | 160 | 400 | 3/16 | 5 | 60 | 1520 |
| | 1 | 25.4 | 45 | 45 | 62 | 165 | 400 | 1/4 | 6 | 35 | 900 |
| | 1-1/2 | 38.1 | 45 | 45 | 62 | 190 | 400 | 1/4 | 6 | 30 | 760 |
| | 2 | 50.8 | 45 | 45 | 62 | 200 | 400 | 1/4 | 6 | 15 | 380 |

M
E
T
R
I
C

| Nozzle | Material Thickness (mm) | | Test Preflow Rate (N ₂) (%) | Test Cut Flow Rate (N ₂) (%) | Water Flow Setting (%) | Arc Volts (V) | Arc Current (A) | Torch Standoff (mm) | | Travel Speed (mm/min) | |
|---------------------|----------------------------|--|--|---|------------------------------|---------------------|-----------------------|---------------------------|--|-----------------------------|--|
| 3 mm 260A max. | 6 | | 30 | 30 | 85 | 145 | 260 | 3 | | 4730 | |
| 4.2 mm 400A max. | 10 | | 45 | 45 | 62 | 150 | 360 | 5 | | 3700 | |
| | 12 | | 45 | 45 | 62 | 155 | 380 | 5 | | 3200 | |
| | 15 | | 45 | 45 | 62 | 160 | 400 | 5 | | 2500 | |
| | 20 | | 45 | 45 | 62 | 160 | 400 | 5-6 | | 1420 | |
| | 25 | | 45 | 45 | 62 | 165 | 400 | 6 | | 940 | |
| | 35 | | 45 | 45 | 62 | 190 | 400 | 6 | | 790 | |
| | 50 | | 45 | 45 | 62 | 200 | 400 | 6 | | 400 | |

- Notes:
- Minimum N₂ inlet supply pressure remains at one setting of 150 psi (10.3 bar) for all material thickness.
 - Water inlet pressure is 150 psi (10.3 bar) minimum to RHF, gas console & MV console.
 - N₂ flow rate at full scale is 374 scfh (176 l/min) @ 150 psi (10.3 bar) inlet pressure.
 - Set initial torch height (before piercing) to approximately twice the Torch Standoff distance for the material you are cutting.
- Note: If arc does not transfer when set at twice the torch standoff (in the case of thick metal being cut at high current), gradually lower the initial height of the torch until transfer occurs.

HT4001 without Slave **PAC620 Torch - Beveling Consumables** Mild Steel - Oxygen Plasma



ENGLISH


| Electrode | Material Thickness (in) (mm) | | Test Preflow Rate | | Test Cut Flow Rate | Water Flow Setting (%) | Arc Volts (V) | Arc Current (A) | Torch Standoff (in) (mm) | | Travel Speed (ipm) (mm/min) | |
|-----------|---------------------------------|------|-----------------------|-----------------------|-----------------------|------------------------|---------------|-----------------|--------------------------|---|-----------------------------|------|
| | | | (N ₂) (%) | (O ₂) (%) | (O ₂) (%) | | | | | | | |
| 260A | 1/4 | 6.35 | 16 | 11 | 85-90 | 73 | 120 | 260 | 1/8 | 3 | 165 | 4190 |
| | 1/2 | 12.7 | 16 | 11 | 85-90 | 73 | 125 | 260 | 1/8 | 3 | 100 | 2540 |
| | 3/4 | 19.1 | 16 | 11 | 85-90 | 73 | 135 | 260 | 3/16 | 5 | 65 | 1650 |
| | 1 | 25.4 | 16 | 11 | 85-90 | 73 | 140 | 260 | 1/4 | 6 | 45 | 1140 |

METRIC

| Electrode | Material Thickness (mm) | Test Preflow Rate | | Test Cut Flow | Water Flow Setting (%) | Arc Volts (V) | Arc Current (A) | Torch Standoff (mm) | Travel Speed (mm/min) |
|-----------|----------------------------|--------------------------|----------------------------|----------------------------------|---------------------------|------------------|--------------------|------------------------|--------------------------|
| | | (N ₂) (%) | & (O ₂) (%) | Rate (O ₂) (%) | | | | | |
| 260A | 6 | 16 | 11 | 85-90 | 73 | 122 | 260 | 3 | 4200 |
| | 8 | 16 | 11 | 85-90 | 73 | 124 | 260 | 3-4 | 3600 |
| | 10 | 16 | 11 | 85-90 | 73 | 127 | 260 | 4 | 3000 |
| | 12 | 16 | 11 | 85-90 | 73 | 130 | 260 | 4-5 | 2500 |
| | 15 | 16 | 11 | 85-90 | 73 | 132 | 260 | 5 | 2100 |
| | 20 | 16 | 11 | 85-90 | 73 | 136 | 260 | 5-6 | 1500 |
| | 25 | 16 | 11 | 85-90 | 73 | 141 | 260 | 6 | 1100 |

- Notes:
- Minimum O₂ inlet pressure remains at one setting of 120 psi (8.2 bar) for all material thickness.
 - Minimum N₂ inlet pressure remains at one setting of 150 psi (10.3 bar) for all material thickness.
 - O₂ flow rate at full scale is 127 scfh (60 l/min) @ 120 psi (8.2 bar) inlet pressure.
 - N₂ flow rate at full scale is 374 scfh (176 l/min) @ 150 psi (10.3 bar) inlet pressure.
 - Water inlet pressure is 150 psi (10.3 bar) minimum to RHF, gas console & MV console.
 - Set initial torch height (before piercing) to approximately twice the Torch Standoff distance for the material you are cutting.

HT4001 without Slave **PAC620 Torch - Beveling Consumables** **Mild Steel - Oxygen Plasma**



E
N
G
L
I
S
H


| Electrode | Material Thickness (in) (mm) | | Test Preflow Rate (N ₂) & (O ₂) (%) (%) | | Test Cut Flow Rate (O ₂) (%) | Water Flow Setting (%) | Arc Volts (V) | Arc Current (A) | Torch Standoff (in) (mm) | | Travel Speed (ipm) (mm/min) | |
|-----------|---------------------------------|------|---|----|--|---------------------------|------------------|--------------------|-----------------------------|---|--------------------------------|------|
| 340A | 1/2 | 12.7 | 16 | 11 | 85 | 73 | 135 | 340 | 3/16 | 5 | 110 | 2800 |
| | 3/4 | 19.1 | 16 | 11 | 85 | 73 | 140 | 340 | 3/16 | 5 | 85 | 2160 |
| | 1 | 25.4 | 16 | 11 | 85 | 73 | 145 | 340 | 3/16 | 5 | 65 | 1650 |
| | 1-1/4 | 31.8 | 16 | 11 | 85 | 73 | 145 | 340 | 3/16 | 5 | 45 | 1140 |

M
E
T
R
I
C

| Electrode | Material Thickness (mm) | Test Preflow Rate (N ₂) & (O ₂) (%) (%) | | Test Cut Flow Rate (O ₂) (%) | Water Flow Setting (%) | Arc Volts (V) | Arc Current (A) | Torch Standoff (mm) | Travel Speed (mm/min) |
|-----------|----------------------------|---|----|--|---------------------------|------------------|--------------------|------------------------|--------------------------|
| 340A | 15 | 16 | 11 | 85 | 73 | 135 | 340 | 5 | 2570 |
| | 20 | 16 | 11 | 85 | 73 | 140 | 340 | 5 | 2080 |
| | 25 | 16 | 11 | 85 | 73 | 145 | 340 | 5 | 1680 |
| | 30 | 16 | 11 | 85 | 73 | 145 | 340 | 5 | 1280 |

- Notes:
- Minimum O₂ inlet pressure remains at one setting of 120 psi (8.2 bar) for all material thickness.
 - Minimum N₂ inlet pressure remains at one setting of 150 psi (10.3 bar) for all material thickness.
 - O₂ flow rate at full scale is 127 scfh (60 l/min) @ 120 psi (8.2 bar) inlet pressure.
 - N₂ flow rate at full scale is 374 scfh (176 l/min) @ 150 psi (10.3 bar) inlet pressure.
 - Water inlet pressure is 150 psi (10.3 bar) minimum to RHF, gas console & MV console.
 - Set initial torch height (before piercing) to approximately twice the Torch Standoff distance for the material you are cutting.

HT4001 without Slave **PAC620 Torch - Beveling Consumables** Mild Steel or Stainless Steel - Nitrogen Plasma



ENGLISH


| Nozzle | Material Thickness (in) (mm) | | Test Preflow | Test Cut Flow | Water Flow Setting (%) | Arc Volts (V) | Arc Current (A) | Torch Standoff (in) (mm) | | Travel Speed (ipm) (mm/min) | |
|--------------------|---------------------------------|------|----------------------------------|----------------------------------|---------------------------|------------------|--------------------|--------------------------------|----|-----------------------------------|-------|
| | | | Rate (N ₂) (%) | Rate (N ₂) (%) | | | | | | | |
| .120" 260A max. | .035 | .889 | 30 | 30 | 45 | 125 | 240 | 1/8 | 3 | 425 | 10800 |
| | .075 | 1.91 | 30 | 30 | 45 | 130 | 240 | 1/8 | 3 | 285 | 7240 |
| | 1/8 | 3.18 | 30 | 30 | 45 | 145 | 240 | 3/16 | 5 | 190 | 4830 |
| | 1/4 | 6.35 | 30 | 30 | 45 | 155 | 240 | 3/16 | 5 | 145 | 3680 |
| .166" 400A max. | 1/8 | 3.18 | 45 | 45 | 62 | 125 | 300 | 1/4 | 6 | 170 | 4320 |
| | 1/4 | 6.35 | 45 | 45 | 62 | 135 | 340 | 1/4 | 6 | 140 | 3560 |
| | 3/8 | 9.53 | 45 | 45 | 62 | 145 | 360 | 1/4 | 6 | 120 | 3050 |
| | 1/2 | 12.7 | 45 | 45 | 62 | 145 | 380 | 5/16 | 8 | 90 | 2290 |
| | 3/4 | 19.1 | 45 | 45 | 62 | 150 | 400 | 5/16 | 8 | 50 | 1270 |
| | 1 | 25.4 | 45 | 45 | 62 | 155 | 400 | 3/8 | 10 | 30 | 760 |

METRIC

| Nozzle | Material Thickness (mm) | | Test Preflow | Test Cut Flow | Water Flow Setting (%) | Arc Volts (V) | Arc Current (A) | Torch Standoff (mm) | | Travel Speed (mm/min) | |
|---------------------|----------------------------|--|----------------------------------|----------------------------------|---------------------------|------------------|--------------------|---------------------------|--|-----------------------------|--|
| | | | Rate (N ₂) (%) | Rate (N ₂) (%) | | | | | | | |
| 3 mm 260A max. | 6 | | 30 | 30 | 45 | 155 | 240 | 5 | | 3800 | |
| 4.2 mm 400A max. | 6 | | 45 | 45 | 62 | 135 | 340 | 6 | | 3640 | |
| | 8 | | 45 | 45 | 62 | 140 | 360 | 6 | | 3300 | |
| | 10 | | 45 | 45 | 62 | 145 | 360 | 6 | | 2930 | |
| | 12 | | 45 | 45 | 62 | 145 | 380 | 6-7 | | 2450 | |
| | 15 | | 45 | 45 | 62 | 150 | 400 | 8 | | 1900 | |
| | 20 | | 45 | 45 | 62 | 150 | 400 | 8 | | 1200 | |
| | 25 | | 45 | 45 | 62 | 155 | 400 | 10 | | 790 | |

- Notes:
- Minimum N₂ inlet supply pressure remains at one setting of 150 psi (10.3 bar) for all material thickness.
 - Water inlet pressure is 150 psi (10.3 bar) minimum to RHF, gas console & MV console.
 - N₂ flow rate at full scale is 374 scfh (176 l/min) @ 150 psi (10.3 bar) inlet pressure.
 - Set initial torch height (before piercing) to approximately twice the Torch Standoff distance for the material you are cutting.
- Note: If arc does not transfer when set at twice the torch standoff (in the case of thick metal being cut at high current), gradually lower the initial height of the torch until transfer occurs.

HT4001 without Slave **PAC620 Torch - Beveling Consumables** Aluminum - Nitrogen Plasma



ENGLISH

| Nozzle | Material Thickness (in) (mm) | | Test Preflow | Test Cut Flow | Water Flow Setting (%) | Arc Volts (V) | Arc Current (A) | Torch Standoff (in) (mm) | | Travel Speed (ipm) (mm/min) | |
|--------------------|---------------------------------|------|----------------------------------|----------------------------------|---------------------------|------------------|--------------------|--------------------------------|----|-----------------------------------|-------|
| | | | Rate (N ₂) (%) | Rate (N ₂) (%) | | | | | | | |
| .120" 260A max. | .035 | .889 | 30 | 30 | 45 | 120 | 240 | 1/8 | 3 | 520 | 13200 |
| | .075 | 1.91 | 30 | 30 | 45 | 125 | 240 | 1/8 | 3 | 345 | 8760 |
| | 1/8 | 3.18 | 30 | 30 | 45 | 130 | 260 | 3/16 | 5 | 230 | 5840 |
| | 1/4 | 6.35 | 30 | 30 | 45 | 140 | 260 | 1/4 | 6 | 170 | 4320 |
| .166" 400A max. | 1/8 | 3.18 | 55 | 55 | 62 | 140 | 280 | 1/4 | 6 | 220 | 5590 |
| | 1/4 | 6.35 | 55 | 55 | 62 | 150 | 320 | 1/4 | 6 | 165 | 4190 |
| | 3/8 | 9.53 | 55 | 55 | 62 | 150 | 340 | 1/4 | 6 | 130 | 3300 |
| | 1/2 | 12.7 | 55 | 55 | 62 | 150 | 360 | 1/4 | 6 | 110 | 2800 |
| | 3/4 | 19.1 | 55 | 55 | 62 | 150 | 380 | 5/16 | 8 | 60 | 1520 |
| | 1 | 25.4 | 55 | 55 | 62 | 165 | 380 | 3/8 | 10 | 35 | 890 |

METRIC

| Nozzle | Material Thickness (mm) | | Test Preflow | Test Cut Flow | Water Flow Setting (%) | Arc Volts (V) | Arc Current (A) | Torch Standoff (mm) | | Travel Speed (mm/min) | |
|---------------------|----------------------------|--|----------------------------------|----------------------------------|---------------------------|------------------|--------------------|---------------------------|--|-----------------------------|--|
| | | | Rate (N ₂) (%) | Rate (N ₂) (%) | | | | | | | |
| 3 mm 260A max. | 6 | | 30 | 30 | 45 | 140 | 260 | 6 | | 4500 | |
| 4.2 mm 400A max. | 6 | | 55 | 55 | 62 | 150 | 320 | 6 | | 4340 | |
| | 8 | | 55 | 55 | 62 | 150 | 340 | 6 | | 3720 | |
| | 10 | | 55 | 55 | 62 | 150 | 340 | 6 | | 3220 | |
| | 12 | | 55 | 55 | 62 | 150 | 360 | 6 | | 2900 | |
| | 15 | | 55 | 55 | 62 | 150 | 360 | 6-7 | | 2330 | |
| | 20 | | 55 | 55 | 62 | 155 | 380 | 8 | | 1430 | |
| | 25 | | 55 | 55 | 62 | 165 | 380 | 10 | | 930 | |


- Notes:
- Minimum N₂ inlet supply pressure remains at one setting of 150 psi (10.3 bar) for all material thickness.
 - Water inlet pressure is 150 psi (10.3 bar) minimum to RHF, gas console & MV console.
 - N₂ flow rate at full scale is 374 scfh (176 l/min) @ 150 psi (10.3 bar) inlet pressure.
 - Set initial torch height (before piercing) to approximately twice the Torch Standoff distance for the material you are cutting.

Note: If arc does not transfer when set at twice the torch standoff (in the case of thick metal being cut at high current), gradually lower the initial height of the torch until transfer occurs.

HT4001 w/Slave

PAC620 Torch - Standard Consumables

Mild Steel or Stainless Steel - Nitrogen Plasma



E
N
G
L
I
S
H

| Nozzle | Material Thickness (in) (mm) | | Test Preflow | Test Cut Flow | Water Flow Setting (%) | Arc Volts (V) | Arc Current (A) | Torch Standoff (in) (mm) | | Travel Speed (ipm) (mm/min) | |
|--------------------|---------------------------------|------|----------------------------------|----------------------------------|---------------------------|------------------|--------------------|--------------------------------|----|-----------------------------------|-------|
| | | | Rate (N ₂) (%) | Rate (N ₂) (%) | | | | | | | |
| .120" 260A max. | .035 | .889 | 30 | 30 | 45 | 125 | 260 | 1/8 | 3 | 450 | 11430 |
| | .075 | 1.91 | 30 | 30 | 45 | 130 | 260 | 1/8 | 3 | 300 | 7620 |
| | 1/8 | 3.18 | 30 | 30 | 45 | 135 | 260 | 1/4 | 6 | 200 | 5080 |
| | 1/4 | 6.35 | 30 | 30 | 45 | 145 | 260 | 5/16 | 8 | 145 | 3680 |
| .166" 400A max. | 1/8 | 3.18 | 45 | 45 | 62 | 140 | 300 | 1/4 | 6 | 175 | 4450 |
| | 1/4 | 6.35 | 45 | 45 | 62 | 140 | 360 | 1/4 | 6 | 145 | 3690 |
| | 3/8 | 9.53 | 45 | 45 | 62 | 145 | 360 | 1/4 | 6 | 125 | 3180 |
| | 1/2 | 12.7 | 45 | 45 | 62 | 150 | 400 | 1/4 | 6 | 95 | 2420 |
| | 3/4 | 19.1 | 45 | 45 | 62 | 150 | 400 | 5/16 | 8 | 50 | 1270 |
| | 1 | 25.4 | 45 | 45 | 62 | 155 | 400 | 3/8 | 10 | 30 | 760 |
| .187" 600A max. | 1/2 | 12.7 | 45 | 45 | 65 | 145 | 480 | 5/16 | 8 | 110 | 2800 |
| | 3/4 | 19.1 | 45 | 45 | 65 | 155 | 500 | 3/8 | 10 | 70 | 1780 |
| | 1 | 25.4 | 45 | 45 | 65 | 160 | 560 | 3/8 | 10 | 60 | 1530 |
| | 1-1/2 | 38.1 | 45 | 45 | 65 | 170 | 600 | 3/8 | 10 | 30 | 760 |
| | 2 | 50.8 | 45 | 45 | 65 | 180 | 600 | 3/8 | 10 | 20 | 510 |
| .220" 760A max. | 2 | 50.8 | 70 | 70 | 73 | 180 | 700 | 1/2 | 13 | 25 | 630 |
| | 3 | 76.2 | 70 | 70 | 73 | 200 | 760 | 5/8 | 16 | 12 | 300 |

M
E
T
R
I
C


| Nozzle | Material Thickness (mm) | | Test Preflow | Test Cut Flow | Water Flow Setting (%) | Arc Volts (V) | Arc Current (A) | Torch Standoff (mm) | Travel Speed (mm/min) |
|---------------------|----------------------------|--|----------------------------------|----------------------------------|---------------------------|------------------|--------------------|---------------------------|-----------------------------|
| | | | Rate (N ₂) (%) | Rate (N ₂) (%) | | | | | |
| 3 mm 260A max. | 6 | | 30 | 30 | 45 | 145 | 260 | 8 | 3800 |
| 4.2 mm 400A max. | 6 | | 45 | 45 | 62 | 140 | 360 | 6 | 3770 |
| | 8 | | 45 | 45 | 62 | 145 | 360 | 6 | 3430 |
| | 10 | | 45 | 45 | 62 | 145 | 360 | 6 | 3050 |
| | 12 | | 45 | 45 | 62 | 150 | 380 | 6 | 2600 |
| | 15 | | 45 | 45 | 62 | 150 | 400 | 6-7 | 2000 |
| | 20 | | 45 | 45 | 62 | 150 | 400 | 9 | 1200 |
| 4.7 mm 600A max. | 25 | | 45 | 45 | 62 | 155 | 400 | 10 | 790 |
| | 15 | | 45 | 45 | 65 | 150 | 500 | 9 | 2400 |
| | 20 | | 45 | 45 | 65 | 155 | 500 | 10 | 1750 |
| | 25 | | 45 | 45 | 65 | 160 | 560 | 10 | 1540 |
| | 35 | | 45 | 45 | 65 | 165 | 580 | 10 | 950 |
| 5.5 mm 760A max. | 50 | | 45 | 45 | 65 | 180 | 600 | 10 | 520 |
| | 60 | | 70 | 70 | 73 | 190 | 740 | 15 | 510 |
| | 75 | | 70 | 70 | 73 | 200 | 760 | 16 | 320 |

- Notes:
- Minimum N₂ inlet supply pressure remains at one setting of 150 psi (10.3 bar) for all material thickness.
 - Water inlet pressure is 150 psi (10.3 bar) minimum to RHF, gas console & MV console.
 - N₂ flow rate at full scale is 374 scfh (176 l/min) @ 150 psi (10.3 bar) inlet pressure.
 - Set initial torch height (before piercing) to approximately twice the Torch Standoff distance for the material you are cutting.
- Note: If arc does not transfer when set at twice the torch standoff (in the case of thick metal being cut at high current), gradually lower the initial height of the torch until transfer occurs.

HT4001 w/Slave

PAC620 Torch - Standard Consumables

Aluminum - Nitrogen Plasma



E
N
G
L
I
S
H

| Nozzle | Material Thickness (in) (mm) | | Test Preflow Rate (N ₂) (%) | Test Cut Flow Rate (N ₂) (%) | Water Flow Setting (%) | Arc Volts (V) | Arc Current (A) | Torch Standoff (in) (mm) | | Travel Speed (ipm) (mm/min) | |
|---------------------------|---------------------------------|------|--|---|------------------------------|---------------------|-----------------------|--------------------------------|----|-----------------------------------|-------|
| .120" 260A max. | .035 | .889 | 30 | 30 | 45 | 125 | 260 | 1/8 | 3 | 540 | 13710 |
| | .075 | 1.91 | 30 | 30 | 45 | 130 | 260 | 1/8 | 3 | 360 | 9150 |
| | 1/8 | 3.18 | 30 | 30 | 45 | 135 | 260 | 3/16 | 5 | 240 | 6100 |
| | 1/4 | 6.35 | 30 | 30 | 45 | 145 | 260 | 1/4 | 6 | 180 | 4570 |
| .166" 400A max. | 1/8 | 3.18 | 45 | 45 | 62 | 140 | 300 | 1/4 | 6 | 230 | 5840 |
| | 1/4 | 6.35 | 45 | 45 | 62 | 145 | 320 | 1/4 | 6 | 180 | 4570 |
| | 3/8 | 9.53 | 45 | 45 | 62 | 150 | 360 | 1/4 | 6 | 150 | 3810 |
| | 1/2 | 12.7 | 45 | 45 | 62 | 150 | 380 | 1/4 | 6 | 120 | 3050 |
| | 3/4 | 19.1 | 45 | 45 | 62 | 160 | 400 | 5/16 | 8 | 60 | 1530 |
| | 1 | 25.4 | 45 | 45 | 62 | 170 | 400 | 3/8 | 10 | 35 | 890 |
| .187" 600A max. | 1 | 25.4 | 45 | 45 | 65 | 155 | 500 | 3/8 | 10 | 80 | 2030 |
| | 1-1/2 | 38.1 | 45 | 45 | 65 | 170 | 560 | 3/8 | 10 | 45 | 1150 |
| | 2 | 50.8 | 45 | 45 | 65 | 180 | 600 | 3/8 | 10 | 30 | 760 |
| .220" 760A max. | 2 | 50.8 | 70 | 70 | 73 | 180 | 700 | 1/2 | 13 | 30 | 760 |
| | 3 | 76.2 | 70 | 70 | 73 | 200 | 760 | 5/8 | 16 | 15 | 380 |

M
E
T
R
I
C


| Nozzle | Material Thickness (mm) | Test Preflow Rate (N ₂) (%) | Test Cut Flow Rate (N ₂) (%) | Water Flow Setting (%) | Arc Volts (V) | Arc Current (A) | Torch Standoff (mm) | Travel Speed (mm/min) |
|----------------------------|----------------------------|--|---|------------------------------|---------------------|-----------------------|---------------------------|-----------------------------|
| 3 mm 260A max. | 6 | 30 | 30 | 45 | 145 | 260 | 6 | 4740 |
| 4.2 mm 400A max. | 6 | 45 | 45 | 62 | 145 | 320 | 6 | 4700 |
| | 8 | 45 | 45 | 62 | 150 | 340 | 6 | 4170 |
| | 10 | 45 | 45 | 62 | 150 | 360 | 6 | 3700 |
| | 12 | 45 | 45 | 62 | 150 | 380 | 6 | 3200 |
| | 15 | 45 | 45 | 62 | 155 | 400 | 7 | 2500 |
| | 20 | 45 | 45 | 62 | 160 | 400 | 8-9 | 1420 |
| 4.7 mm 600A max. | 25 | 45 | 45 | 62 | 170 | 400 | 10 | 930 |
| | 30 | 45 | 45 | 65 | 165 | 540 | 10 | 1710 |
| | 40 | 45 | 45 | 65 | 175 | 600 | 10 | 1090 |
| 5.5 mm 760A max. | 50 | 45 | 45 | 65 | 180 | 600 | 10 | 780 |
| | 60 | 70 | 70 | 73 | 190 | 740 | 14 | 620 |
| | 75 | 70 | 70 | 73 | 200 | 760 | 16 | 380 |

- Notes:
- Minimum N₂ inlet supply pressure remains at one setting of 150 psi (10.3 bar) for all material thickness.
 - Water inlet pressure is 150 psi (10.3 bar) minimum to RHF, gas console & MV console.
 - N₂ flow rate at full scale is 374 scfh (176 l/min) @ 150 psi (10.3 bar) inlet pressure.
 - Set initial torch height (before piercing) to approximately twice the Torch Standoff distance for the material you are cutting.
- Note: If arc does not transfer when set at twice the torch standoff (in the case of thick metal being cut at high current), gradually lower the initial height of the torch until transfer occurs.

HT4001 w/Slave

PAC620 Torch - Beveling Consumables

Mild Steel or Stainless Steel - Nitrogen Plasma



E
N
G
L
I
S
H

| Nozzle | Material Thickness | | Test Preflow Rate (N ₂) (%) | Test Cut Flow Rate (N ₂) (%) | Water Flow Setting (%) | Arc Volts (V) | Arc Current (A) | Torch Standoff | | Travel Speed | |
|---------------------------|--------------------|------|---|--|------------------------|---------------|-----------------|----------------|------|--------------|----------|
| | (in) | (mm) | | | | | | (in) | (mm) | (ipm) | (mm/min) |
| .120" 260A max. | .035 | .889 | 30 | 30 | 45 | 125 | 240 | 1/8 | 3 | 425 | 10800 |
| | .075 | 1.91 | 30 | 30 | 45 | 130 | 240 | 1/8 | 3 | 285 | 7240 |
| | 1/8 | 3.18 | 30 | 30 | 45 | 145 | 240 | 3/16 | 5 | 190 | 4820 |
| | 1/4 | 6.35 | 30 | 30 | 45 | 155 | 240 | 3/16 | 5 | 145 | 3680 |
| .166" 400A max. | 1/8 | 3.18 | 45 | 45 | 62 | 125 | 300 | 1/4 | 6 | 170 | 4320 |
| | 1/4 | 6.35 | 45 | 45 | 62 | 135 | 340 | 1/4 | 6 | 140 | 3550 |
| | 3/8 | 9.53 | 45 | 45 | 62 | 145 | 360 | 1/4 | 6 | 120 | 3050 |
| | 1/2 | 12.7 | 45 | 45 | 62 | 145 | 380 | 5/16 | 8 | 90 | 2280 |
| | 3/4 | 19.1 | 45 | 45 | 62 | 150 | 400 | 5/16 | 8 | 50 | 1270 |
| | 1 | 25.4 | 45 | 45 | 62 | 155 | 400 | 3/8 | 10 | 30 | 760 |
| .187" 600A max. | 1/2 | 12.7 | 55 | 55 | 65 | 140 | 480 | 3/8 | 10 | 100 | 2540 |
| | 3/4 | 19.1 | 55 | 55 | 65 | 145 | 500 | 3/8 | 10 | 70 | 1780 |
| | 1 | 25.4 | 55 | 55 | 65 | 150 | 560 | 3/8 | 10 | 60 | 1520 |
| | 1-1/2 | 38.1 | 55 | 55 | 65 | 165 | 580 | 3/8 | 10 | 30 | 760 |
| | 2 | 50.8 | 55 | 55 | 65 | 175 | 600 | 7/16 | 11 | 20 | 510 |
| .220" 760A max. | 1-1/4 | 31.8 | 60 | 60 | 73 | 170 | 700 | 1/2 | 13 | 40 | 1020 |
| | 2 | 50.8 | 60 | 60 | 73 | 175 | 720 | 1/2 | 13 | 25 | 630 |
| | 3 | 76.2 | 60 | 60 | 73 | 185 | 760 | 5/8 | 16 | 12 | 300 |


M
E
T
R
I
C

| Nozzle | Material Thickness (mm) | Test Preflow Rate (N ₂) (%) | Test Cut Flow Rate (N ₂) (%) | Water Flow Setting (%) | Arc Volts (V) | Arc Current (A) | Torch Standoff (mm) | Travel Speed (mm/min) |
|----------------------------|-------------------------|---|--|------------------------|---------------|-----------------|---------------------|-----------------------|
| 3 mm 260A max. | 6 | 30 | 30 | 45 | 155 | 240 | 5 | 3800 |
| 4.2 mm 400A max. | 6 | 45 | 45 | 62 | 135 | 340 | 6 | 3640 |
| | 8 | 45 | 45 | 62 | 140 | 360 | 6 | 3300 |
| | 10 | 45 | 45 | 62 | 145 | 360 | 6 | 2930 |
| | 12 | 45 | 45 | 62 | 145 | 380 | 6-7 | 2450 |
| | 15 | 45 | 45 | 62 | 150 | 400 | 8 | 1910 |
| | 20 | 45 | 45 | 62 | 150 | 400 | 8 | 1190 |
| 4.7 mm 600A max. | 25 | 45 | 45 | 62 | 155 | 400 | 10 | 790 |
| | 15 | 55 | 55 | 65 | 140 | 500 | 10 | 2260 |
| | 20 | 55 | 55 | 65 | 145 | 500 | 10 | 1740 |
| | 25 | 55 | 55 | 65 | 150 | 560 | 10 | 1540 |
| 5.5 mm 760A max. | 35 | 55 | 55 | 65 | 160 | 580 | 10 | 950 |
| | 50 | 55 | 55 | 65 | 175 | 600 | 11 | 530 |
| | 35 | 60 | 60 | 73 | 170 | 700 | 13 | 950 |
| | 50 | 60 | 60 | 73 | 175 | 720 | 13 | 650 |
| 760A max. | 60 | 60 | 60 | 73 | 180 | 740 | 15 | 510 |
| | 75 | 60 | 60 | 73 | 185 | 760 | 16 | 320 |

- Notes:
- Minimum N₂ inlet supply pressure remains at one setting of 150 psi (10.3 bar) for all material thickness.
 - Water inlet pressure is 150 psi (10.3 bar) minimum to RHF, gas console & MV console.
 - N₂ flow rate at full scale is 374 scfh (176 l/min) @ 150 psi (10.3 bar) inlet pressure.
 - Set initial torch height (before piercing) to approximately twice the Torch Standoff distance for the material you are cutting.

Note: If arc does not transfer when set at twice the torch standoff (in the case of thick metal being cut at high current), gradually lower the initial height of the torch until transfer occurs.

HT4001 w/Slave **PAC620 Torch - Beveling Consumables** Aluminum - Nitrogen Plasma



ENGLISH

| Nozzle | Material Thickness | | Test Preflow | Test Cut Flow | Water Flow Setting (%) | Arc Volts (V) | Arc Current (A) | Torch Standoff | | Travel Speed | |
|---------------------------|--------------------|------|----------------------------|----------------------------|------------------------|---------------|-----------------|----------------|------|--------------|----------|
| | (in) | (mm) | Rate (N ₂) (%) | Rate (N ₂) (%) | | | | (in) | (mm) | (ipm) | (mm/min) |
| .120" 260A max. | .035 | .889 | 30 | 30 | 45 | 120 | 240 | 1/8 | 3 | 520 | 13200 |
| | .075 | 1.91 | 30 | 30 | 45 | 125 | 240 | 1/8 | 3 | 345 | 8760 |
| | 1/8 | 3.18 | 30 | 30 | 45 | 130 | 260 | 3/16 | 5 | 230 | 5840 |
| | 1/4 | 6.35 | 30 | 30 | 45 | 140 | 260 | 1/4 | 6 | 170 | 4320 |
| .166" 400A max. | 1/8 | 3.18 | 55 | 55 | 62 | 140 | 280 | 1/4 | 6 | 220 | 5590 |
| | 1/4 | 6.35 | 55 | 55 | 62 | 150 | 320 | 1/4 | 6 | 165 | 4190 |
| | 3/8 | 9.53 | 55 | 55 | 62 | 150 | 340 | 1/4 | 6 | 130 | 3300 |
| | 1/2 | 12.7 | 55 | 55 | 62 | 150 | 360 | 1/4 | 6 | 110 | 2790 |
| | 3/4 | 19.1 | 55 | 55 | 62 | 150 | 380 | 5/16 | 8 | 60 | 1520 |
| | 1 | 25.4 | 55 | 55 | 62 | 165 | 380 | 3/8 | 10 | 35 | 890 |
| .187" 600A max. | 1 | 25.4 | 55 | 55 | 65 | 165 | 500 | 3/8 | 10 | 70 | 1780 |
| | 1-1/2 | 38.1 | 55 | 55 | 65 | 170 | 600 | 3/8 | 10 | 35 | 890 |
| | 2 | 50.8 | 55 | 55 | 65 | 170 | 600 | 3/8 | 10 | 25 | 630 |
| .220" 760A max. | 2 | 50.8 | 60 | 60 | 73 | 175 | 700 | 1/2 | 13 | 30 | 760 |
| | 3 | 76.2 | 60 | 60 | 73 | 200 | 760 | 5/8 | 16 | 20 | 510 |

METRIC

| Nozzle | Material Thickness | | Test Preflow | Test Cut Flow | Water Flow Setting (%) | Arc Volts (V) | Arc Current (A) | Torch Standoff | | Travel Speed | |
|----------------------------|--------------------|------|----------------------------|----------------------------|------------------------|---------------|-----------------|----------------|------|--------------|----------|
| | (mm) | (mm) | Rate (N ₂) (%) | Rate (N ₂) (%) | | | | (mm) | (mm) | (mm/min) | (mm/min) |
| 3 mm 260A max. | 6 | | 30 | 30 | 45 | 140 | 260 | 6 | | 4500 | |
| 4.2 mm 400A max. | 6 | | 55 | 55 | 62 | 150 | 320 | 6 | | 4350 | |
| | 8 | | 55 | 55 | 62 | 150 | 340 | 6 | | 3700 | |
| | 10 | | 55 | 55 | 62 | 150 | 340 | 6 | | 3200 | |
| | 12 | | 55 | 55 | 62 | 150 | 360 | 6 | | 2900 | |
| | 15 | | 55 | 55 | 62 | 150 | 360 | 7 | | 2350 | |
| | 20 | | 55 | 55 | 62 | 150 | 380 | 8 | | 1400 | |
| 4.7 mm 600A max. | 25 | | 55 | 55 | 62 | 165 | 380 | 10 | | 930 | |
| | 30 | | 55 | 55 | 65 | 170 | 560 | 10 | | 1460 | |
| | 35 | | 55 | 55 | 65 | 170 | 600 | 10 | | 1100 | |
| 5.5 mm 760A max. | 50 | | 55 | 55 | 65 | 170 | 600 | 10 | | 650 | |
| | 60 | | 60 | 60 | 73 | 190 | 740 | 14 | | 680 | |
| | 75 | | 60 | 60 | 73 | 200 | 760 | 16 | | 520 | |

- Notes:
- Minimum N₂ inlet supply pressure remains at one setting of 150 psi (10.3 bar) for all material thickness.
 - Water inlet pressure is 150 psi (10.3 bar) minimum to RHF, gas console & MV console.
 - N₂ flow rate at full scale is 374 scfh (176 l/min) @ 150 psi (10.3 bar) inlet pressure.
 - Set initial torch height (before piercing) to approximately twice the Torch Standoff distance for the material you are cutting.
- Note: If arc does not transfer when set at twice the torch standoff (in the case of thick metal being cut at high current), gradually lower the initial height of the torch until transfer occurs.

OPERATION

CHANGING CONSUMABLE PARTS



WARNING



Always disconnect the power supply from the main power source before inspecting or changing the torch parts.

Inspect the consumable parts before cutting for wear, and replace when needed. **Always place the consumables on a clean, dry, oil free surface after removing. Dirty consumables can cause the torch to malfunction.** Refer to Figure 4-2.

Removal and Inspection

1. Unscrew the retaining cap.
2. Remove the nozzle from the torch. Check the ceramic portion of the nozzle for signs of wear and arcing.
3. Unscrew the electrode from the torch head using a 7/16" (11 mm) hex wrench (wrench supplied in all of the spare parts kits). Replace the electrode if the crater in the center of the insert is in excess of .050 inch (1.3 mm) deep.
4. Remove the swirl ring from the electrode and inspect it for plugged holes or other damage.
5. If the tip of the water tube is damaged at all, see *Changing the Water Tube* later in this section.

Replacement

Before replacing the consumable parts, clean the current ring in the torch - see Figure 4-2. Use a clean paper towel or cotton swab to remove any dirt, grease, etc., from the current ring.

1. Replace the electrode by screwing it back into the torch head. Use the 7/16" (11 mm) socket wrench to tighten down the electrode. **Do not overtighten.**
2. Apply a light coating of silicone grease to both O-rings of the swirl ring before installing. As a guideline, you should be able to feel the grease on your fingers, but not see it. **Do not use an excessive amount of grease.** Too much grease will plug the swirl ring ports, causing improper gas flow during operation.

When installing the swirl ring, make sure to place the smaller diameter end up toward the rear of the torch.

3. Before installing the nozzle, apply a small amount of silicone grease to the nozzle's O-rings. As a guideline, you should be able to feel the grease on your fingers, but not see it. **Do not use an excessive amount of grease.** Insert the nozzle into the torch and push it into place.
4. Replace the retaining cap by **tightening it snugly by hand to insure good electrical contact** between the nozzle and the torch.

If the cap does not go on easily, clean the threads on the torch body and the retaining cap and apply a small amount of silicone grease to the O-ring located just below the threads of the torch body.

Note: Failure to tighten the retaining cap snugly (or to keep the threads and current ring clean) will result in pitting of the stainless steel current ring causing gas and water leaks around the upper nozzle O-ring, impairing cut quality. The **retaining cap should be tightened by hand only**.




Figure 4-2 Changing Consumable Parts

OPERATION

Changing the Water Tube

Problems and causes you may find with a defective or improperly installed water tube:

- Short electrode life: Water tube not screwed in tightly; wrong water tube for consumables
- Flow switch interlock shutting down the system: Water flow restricted due to loose water tube
- Humming or rattling sound coming from the torch: Water tube bent or loose

If you suspect a problem with the water tube, you may need to replace it.

1. Disconnect power supply from power source.
2. Remove all consumables from torch (see *Changing Consumable Parts* earlier in this section).
3. Verify that the correct water tube is installed - The standard water tube (020990) is recessed about 5/64 of an inch (2 mm) from the end of the torch head. The nitrogen beveling water tube (020991) extends about 19/64 of an inch (7.5 mm) from the end of the torch head. The oxygen beveling water tube (020992) extends about 23/64 of an inch (9.1 mm) from the end of the torch head.
Note: part numbers are laser engraved on the water tubes.
4. Look for any damage or bends in the water tube.
5. Remove and replace the water tube by using the water tube wrench (027347) supplied with the consumable parts kits - Fig. 4-3. **When installing water tube, do not overtighten!** Snug down by hand only.





Figure 4-3 Changing the Water Tube

Section 5

PARTS LIST

This section provides part numbers for the components in the HT4001 Titan Gas Panel, Remote High Frequency&Motor Valve Console (also called “High Frequency Console”) and PAC620 torch for the Titan Integrated Plasma System.

- See *Installation* in this manual for cable and hose part numbers.
- See HT4001 Instruction Manual 802000 for consumable parts kits, power supply breakdown, and parts for other HT4001 options.

PARTS LIST




Figure 5-1 HT4001 Titan Gas Panel

GAS PANEL - 077024

| Item | Part Number | Description | Designator | Qty. |
|------|---------------|--|------------|-------|
| 1 | 001628 | Panel:HT4001 Titan Gas Console | | 1 |
| 2 | 004117 | Cap:Needle Valve | | 3 |
| 3 | 004718 | Manifold:Motor Valve | | 1 |
| 4 | 005042 | Toggle Switch:Momentary ON/OFF/ON | S3 | 1 |
| 5 | 005089 | Lens:White | | 1 |
| 6 | 005149 | Bulb:120VAC | LT1 | 1 |
| 7 | 005151 | Lamp Holder | | 1 |
| 8 | 005243 | Pressure Switch:80 psi 1/8 NPT | PS1 | 1 |
| 9 | 005243 | Pressure Switch:80 psi 1/8 NPT | PS2 | 1 |
| 10 | 005180 | Toggle Switch:SP3T ON/OFF/ON | S2 | 1 |
| 11 | 005181 | Toggle Switch:DPDT ON/NONE/ON | S1 | 1 |
| 12 | 006064 | Motor Valve:1/8 FPT .125 Orifice | MV2 | 1 |
| 13 | 006064 | Motor Valve:1/8 FPT .125 Orifice | MV3 | 1 |
| 14 | 006064 | Motor Valve:1/8 FPT .125 Orifice | MV4 | 1 |
| 15 | 006109 | Solenoid Valve:1/8FPT120V2W NC MANF | SV1A,SV1B | 2 |
| 16 | 006106 | Solenoid Valve:1/8FPT 120V TFE Plunger | SV2 | 1 |
| 17 | 006106 | Solenoid Valve:1/8FPT 120V TFE Plunger | SV3 | 1 |
| 18 | 011053 | Flowmeter:0-10 SC/BP-8 Float Cal 2% | FM2 | 1 |
| | 011058 | Flowtube/BP-8 Float:0-10 SC Cal. 2% | | 1 |
| | 011081 | Float Stop | | 1 |
| | 011008 | Shield, Plastic, 63S0503M0010 | | 1 |
| 19 | 011056 | Flowmeter:0-10 SC/BT-8 Float Cal 2% | FM1 | 1 |
| | 011057 | Flowtube/BT-8 Float:0-10 SC Cal. 2% | | 1 |
| | 011081 | Float Stop | | 1 |
| | 011008 | Shield, Plastic, 63S0503M0010 | | 1 |
| 20 | 011069 | Flowmeter:1.9 SCFM/3F9 Float (NO-V) | FM3 | 1 |
| 21 | 022027 | Pressure Gauge:160# 1.5" 1/8CBM Panel | PG1 | 1 |
| 22 | 022027 | Pressure Gauge:160# 1.5" 1/8CBM Panel | PG2 | 1 |
| 23 | 022027 | Pressure Gauge:160# 1.5" 1/8CBM Panel | PG4 | 1 |
| 24 | 046077 | Tubing:1/4"OD .04W Blue Nylon | | 11 ft |
| 25 | 129213 | Harness:HT4001 Titan Gas Assy | | 1 |
| 26 | 008176 | Pin:24-20 AWG TYPE III+CRP | | 27 |
| 27 | 008186 | Socket:24-20 AWG TYPE III+CRP | | 14 |
| 28 | 008208 | Receptacle Shell:CPC 23-37 Reverse Sex 3X1 | | 1 |
| 29 | 008447 | Receptacle Shell:CPC 23-37 Standard Sex 3X2 | | 1 |

PARTS LIST




Figure 5-2 HT4001 Titan RHF&MV Console

RHF&MV CONSOLE - 077028

| Item | Part Number | Description | Designator | Qty. |
|------|---------------|--|------------|------|
| 1 | 002279 | Enclosure:2000/4001/3070 Titan RHF | | 1 |
| 2 | 002285 | Foot:Titan RHF Console | | 4 |
| 3 | 005100 | Limit Switch:Door Interlock | S1 | 1 |
| 4 | 009045 | Filter:1A 1B1 AC Electric | FL1 | 1 |
| 5 | 077025 | HT4001 Titan RHF PNL | | 1 |
| 6 | 001629 | Box:HT4001 Titan RHF | | 1 |
| 7 | 004718 | Manifold:Motor Valve | | 1 |
| 8 | 006063 | Motor Valve:Electric 1/8FPT .125 Orifice | MV1 | 1 |
| 9 | 006109 | Solenoid Valve:1/8FPT120V2W NC MANF | SV4A,SV4B | 2 |
| 10 | 009246 | Capacitor:.5μF 2500WV | C4A, C4B | 2 |
| 11 | 009247 | Bracket:009246 Cap Mounting | | 2 |
| 12 | 009350 | Spark Gap Assembly:40-200/2000/HD | SG1 | 1 |
| 13 | 004061 | Electrode:Spark Gap 1/8 X 1.6 | | 3 |
| 14 | 004140 | Base:40/0/100/200/HD Spark Gap | | 1 |
| 15 | 004144 | Bar:009350 Spark Gap Cap Mounting | | 1 |
| 16 | 009280 | Capacitor:.002μF 15KV | C5A,C5B | 2 |
| 17 | 109075 | Inductor:HT4001-Titan HF Coil | T2 | 1 |
| 18 | 129209 | Negative Bus SA:HT4001 Titan | | 1 |
| 19 | 004074 | Block:200/400/500 Cath Neg Bus | | 1 |
| 20 | 009224 | Capacitor:.22μF 1000WV 10% | C7 | 1 |
| 21 | 129306 | High Voltage Xfmr SA:HT4001 Titan RHF | T1 | 1 |
| 22 | 129210 | Panel SA:HT4001 Titan | | 1 |
| 23 | 001632 | Panel:HT4001 Titan Side | | 1 |
| 24 | 006031 | Solenoid Valve:350# 1/4 FPT 120V NC | SV6 | 1 |
| | 129214 | Harness:HT4001 Titan HF & Motor-Valve | | 1 |
| 25 | 008186 | Socket:24-20 AWG Type III+CRP | | 4 |
| 26 | 008193 | Receptacle Shell:CPC 17-16 Std Sex | 2X1 | 1 |
| 27 | 008210 | Receptacle Shell:CPC 11-4 Rvs Sex | 4X2 | 1 |
| 28 | 008447 | Receptacle Shell:CPC 23-37 Std Sex | 4X1 | 1 |
| 29 | 008985 | Pin:18-16AWG TypeIII | | 10 |
| | 129224 | Manifold SA:HT4001 Kobold Flowswitch | | 1 |
| 30 | 004457 | Manifold:500/4X00 Kobold Flowswitch | | 1 |
| 31 | 005139 | Flowswitch:0.25 GPM SPST 1/4 NPT | FS2 | 1 |
| 32 | 005140 | Flowswitch:1.20 GPM SPST 1/4 NPT | FS1 | 1 |

PARTS LIST

HT4001 TITAN STANDARD TORCH ASSEMBLY WITH 25' LEADS - 128256

| <u>Item</u> | <u>Part Number</u> | <u>Description</u> | <u>Qty.</u> |
|-------------|--------------------|--|-------------|
| | 128256 | HT4001 Titan Standard Torch Assy w/25' Leads | |
| 1 | 028507* | PAC620 Standard Torch Assy | 1 |
| 2 | 028944 | Leads:Torch Power with Sleeve 25' | 1 |
| 3 | 024214 | Hose Assy:3/16Blue RH'A' 25' | 1 |
| 4 | 123315 | Cable:4001 Titan MotorValve/Tch Off Vlv 25' | 1 |
| 5 | 024317 | Hose Assy:1/4Blue RH'A' 5' | 1 |
| 6 | 129159 | Off-Valve SAIII:PAC620 Tch | 1 |

* See page 5-8 for detail of PAC620 Standard Torch Assy

HT4001 TITAN BEVEL TORCH ASSEMBLY WITH 25' LEADS - 128257

| <u>Item</u> | <u>Part Number</u> | <u>Description</u> | <u>Qty.</u> |
|-------------|--------------------|---|-------------|
| | 128257 | HT4001 Titan Bevel Torch Assy w/25' Leads | |
| 1 | 028741** | PAC620 Bevel Torch Assy | 1 |
| 2 | 028944 | Leads:Torch Power with Sleeve 25' | 1 |
| 3 | 024214 | Hose Assy:3/16Blue RH'A' 25' | 1 |
| 4 | 123315 | Cable:4001 Titan MotorValve/Tch Off Vlv 25' | 1 |
| 5 | 024317 | Hose Assy:1/4Blue RH'A' 5' | 1 |
| 6 | 129159 | Off-Valve SAIII:PAC620 Tch | 1 |

** See page 5-7 for detail of PAC620 Bevel Torch Assy




Figure 5-3 128256 or 128257 Torch Assembly




Figure 5-4 PAC620 Beveling Torch Assembly

PAC620 BEVEL TORCH ASSEMBLY - 028741

| <u>Part Item</u> | <u>Number</u> | <u>Description</u> | <u>Qty.</u> |
|----------------------|---------------|-----------------------------------|-------------|
| | 028741 | PAC620 Bvling Torch Assy | |
| 1 | 020749 | Torch mounting Sleeve:PAC610/620 | 1 |
| 2 | 020970 | PAC620 Bev Torch Main Body | 1 |
| 3 | 020991 | Water Tube:620 Bev N2 Electdcool | 1 |
| 4 | 020968 | Electrode:PAC620 Bev N2 | 1 |
| 5 | 020039 | Swirl Ring: .120/.166/.187 N2 | 1 |
| 6 | 120387 | Nozzle:PAC620 Bev. .166 N2 | 1 |
| 7 | 120392 | Ret Cap:PAC620 Bev N2 Noz Vectra | 1 |

TORCH MOUNTING BRACKET - 020046

| <u>Part Number</u> | <u>Description</u> | <u>Designation</u> | <u>Qty.</u> |
|------------------------|---|--------------------|-------------|
| 020046 | Torch Mounting Bracket w/Clevis:2" | | 1 |
| 020032 | Bracket: 2" Torch Mounting | | 1 |
| 020044 | Clevis: Torch Mounting Bracket | | 1 |

PARTS LIST




Figure 5-5 PAC620 Standard Torch Assembly


PAC620 STANDARD TORCH ASSEMBLY - 028507


| <u>Part Item</u> | <u>Number</u> | <u>Description</u> | <u>Qty.</u> |
|------------------|---------------|--|-------------|
| | 028507 | PAC620 Standard Torch Assy | |
| 1 | 020041 | Torch mounting Sleeve:2" Generic | 1 |
| 2 | 020328 | PAC620 Standard Torch Main Body | 1 |
| 3 | 020990 | Water Tube:400/600/170 Electdcool | 1 |
| 4 | 020663 | Electrode:O2 | 1 |
| 5 | 020623 | Swirl Ring:O2 | 1 |
| 6 | 020086 | Nozzle: .099 O2 | 1 |
| 7 | 020579 | Ret Cap:PAC620 Standard (Vectra) | 1 |


TORCH MOUNTING BRACKET - 020046

| <u>Part Number</u> | <u>Description</u> | <u>Designation</u> | <u>Qty.</u> |
|--------------------|---|--------------------|-------------|
| 020046 | Torch Mounting Bracket w/Clevis:2" | | 1 |
| 020032 | Bracket: 2" Torch Mounting | | 1 |
| 020044 | Clevis: Torch Mounting Bracket | | 1 |

See HT4001 Instruction Manual 802000 for consumable parts kits, power supply breakdown, and parts for other HT4001 options.







- FM1 FLOW METER, NITROGEN
 FM2 FLOW METER, OXYGEN
 FM3 FLOW METER, INJECTION WATER
 PG1 PRESSURE GAUGE, NITROGEN INLET
 PG2 PRESSURE GAUGE, OXYGEN INLET
 PG4 PRESSURE GAUGE, INJECTION
 PS1 PRESSURE SWITCH, NITROGEN INLET
 PS2 PRESSURE SWITCH, OXYGEN INLET
 MV1 METERING VALVE, PLASMA MOTOR
 MV2 METERING VALVE, N₂ PREFLOW
 MV3 METERING VALVE, O₂ PREFLOW
 MV4 METERING VALVE, INJECTION WATER
 SV1A SOLENOID VALVE, O₂ CUTFLOW
 SV1B SOLENOID VALVE, N₂ CUTFLOW
 SV2 SOLENOID VALVE, N₂ PREFLOW
 SV3 SOLENOID VALVE, O₂ PREFLOW
 SV4A SOLENOID VALVE, CUTFLOW
 SV4B SOLENOID VALVE, PREFLOW
 SV5 SOLENOID VALVE, PLASMA OFF
 SV6 SOLENOID VALVE, INJECTION WATER
 FS1 FLOW SWITCH, COOLING WATER
 FS2 FLOW SWITCH, INJECTION WATER

NOTES:
 1. FOR ELECTRICAL DIAGRAM SEE DWG. NO.

| | | | | |
|--|---|-------------|-----------|--------------|
| MATERIAL | DRAWN BY | AD | DATE | 4-5-97 |
| | CHECKED BY | AD | DATE | 9-16-97 |
| | APP. BY | DJR | DATE | 9-17-97 |
| | UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES. TOLERANCES ON: 2 PL. DECIMALS ± .015 3 PL. DECIMALS ± .005 FRACTIONS ± 1/64 BREAK SHARP CORNERS WITH CHAMFER OR RADII .015 MAX. | | | |
| THIS DRAWING AND ALL INFORMATION CONTAINED HEREON IS UNCLASSIFIED PROPRIETARY AND MAY NOT BE USED FOR MANUFACTURING OR FABRICATION PURPOSES WITHOUT PERMISSION FROM HYPERTHERM, INC. | | | | |
| HYPERTHERM, INC. Hypertherm, Incorporated Box-5010 Hanover, NH 03755-5010 603/643-3441 | | | | |
| DESCRIPTION ELEC SCHEM:HT4001-TITAN | | | | |
| STOCK NO. | 013316 | DRAWING NO. | 013-2-316 | FILE NAME |
| SCALE | N/A | MODEL | HT4001 | SHEET 3 OF 4 |

ELECTRICAL SCHEMATIC RHF & GAS PANEL SEE 013316 SHEET 2
 POWER UNIT ELECTRICAL DIAGRAM SEE 013254
 TIMING DIAGRAM SEE 013254 SHEET 14

| | | | | |
|---|--|-------------|--------|--------------|
| MATERIAL | DRAWN BY | AD | DATE | 4-5-97 |
| | CHECKED BY | AD | DATE | 9-16-97 |
| | APP. BY | DJR | DATE | 9-17-97 |
| | UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES. TOLERANCES ON: 2 PL. DECIMALS ± .015 3 PL. DECIMALS ± .005 FRACTIONS ± 1/64 BREAK SHARP CORNERS WITH CHAMFER OR RADIUS .015 MAX. | | | |
| THIS DRAWING AND ALL INFORMATION CONTAINED HEREON IS CONSIDERED PROPRIETARY AND MAY NOT BE USED FOR MANUFACTURING OR FABRICATION PURPOSES WITHOUT PERMISSION FROM HYPERTHERM, INC. | | | | |
| HYPERTHERM, INC. Hypertherm, Incorporated Box-5010 Dover, NH 03755-5010 603/643-3441 | | | | |
| DESCRIPTION ELEC SCHEM:HT4001-TITAN | | | | |
| STOCK NO. | | DRAWING NO. | | FILE NAME |
| 013316 | | 013-2-316 | | 013316B4 |
| SCALE | N/A | MODEL | HT4001 | SHEET 4 OF 4 |