



XPR300™ VDC3 Board Installation

Field Service Bulletin

809700 | Revision 0 | December 2016

Hypertherm Inc.

Etna Road, P.O. Box 5010
Hanover, NH 03755 USA
603-643-3441 Tel (Main Office)
603-643-5352 Fax (All Departments)
info@hypertherm.com (Main Office Email)

800-643-9878 Tel (Technical Service)

technical.service@hypertherm.com (Technical Service Email)

800-737-2978 Tel (Customer Service)

customer.service@hypertherm.com (Customer Service Email)

866-643-7711 Tel (Return Materials Authorization)**877-371-2876 Fax (Return Materials Authorization)**

return.materials@hypertherm.com (RMA email)

Hypertherm México, S.A. de C.V.

Avenida Toluca No. 444, Anexo 1,
Colonia Olivar de los Padres
Delegación Álvaro Obregón
México, D.F. C.P. 01780
52 55 5681 8109 Tel
52 55 5683 2127 Fax
Soporte.Tecnico@hypertherm.com (Technical Service Email)

Hypertherm Plasmatechnik GmbH

Sophie-Scholl-Platz 5
63452 Hanau
Germany

00 800 33 24 97 37 Tel
00 800 49 73 73 29 Fax

31 (0) 165 596900 Tel (Technical Service)**00 800 4973 7843 Tel (Technical Service)**

technicalservice.emea@hypertherm.com (Technical Service Email)

Hypertherm (Singapore) Pte Ltd.

82 Genting Lane
Media Centre
Annexe Block #A01-01
Singapore 349567, Republic of Singapore
65 6841 2489 Tel
65 6841 2490 Fax
Marketing.asia@hypertherm.com (Marketing Email)
TechSupportAPAC@hypertherm.com (Technical Service Email)

Hypertherm Japan Ltd.

Level 9, Edobori Center Building
2-1-1 Edobori, Nishi-ku
Osaka 550-0002 Japan
81 6 6225 1183 Tel
81 6 6225 1184 Fax
HTJapan.info@hypertherm.com (Main Office Email)
TechSupportAPAC@hypertherm.com (Technical Service Email)

Hypertherm Europe B.V.

Vaartveld 9, 4704 SE
Roosendaal, Nederland
31 165 596907 Tel
31 165 596901 Fax
31 165 596908 Tel (Marketing)
31 (0) 165 596900 Tel (Technical Service)
00 800 4973 7843 Tel (Technical Service)
technicalservice.emea@hypertherm.com
(Technical Service Email)

Hypertherm (Shanghai) Trading Co., Ltd.

B301, 495 ShangZhong Road
Shanghai, 200231
PR China
86-21-80231122 Tel
86-21-80231120 Fax
86-21-80231128 Tel (Technical Service)
techsupport.china@hypertherm.com
(Technical Service Email)

South America & Central America: Hypertherm Brasil Ltda.

Rua Bras Cubas, 231 – Jardim Maia
Guarulhos, SP – Brasil
CEP 07115-030
55 11 2409 2636 Tel
tecnico.sa@hypertherm.com (Technical Service Email)

Hypertherm Korea Branch

#3904. APEC-ro 17. Heaundae-gu. Busan.
Korea 48060
82 (0)51 747 0358 Tel
82 (0)51 701 0358 Fax
Marketing.korea@hypertherm.com (Marketing Email)
TechSupportAPAC@hypertherm.com
(Technical Service Email)

Hypertherm Pty Limited

GPO Box 4836
Sydney NSW 2001, Australia
61 (0) 437 606 995 Tel
61 7 3219 9010 Fax
au.sales@Hypertherm.com (Main Office Email)
TechSupportAPAC@hypertherm.com
(Technical Service Email)

Hypertherm (India) Thermal Cutting Pvt. Ltd

A-18 / B-1 Extension,
Mohan Co-Operative Industrial Estate,
Mathura Road, New Delhi 110044, India
91-11-40521201/ 2/ 3 Tel
91-11 40521204 Fax
HTIndia.info@hypertherm.com (Main Office Email)
TechSupportAPAC@hypertherm.com
(Technical Service Email)


© 2016 Hypertherm Inc. All rights reserved.

XPR300 and Hypertherm are trademarks of Hypertherm Inc. and may be registered in the United States and/or other countries. All other trademarks are the property of their respective holders.

One of Hypertherm's long-standing core values is a focus on minimizing our impact on the environment. Doing so is critical to our, and our customers', success. We are always striving to become better environmental stewards; it is a process we care deeply about.

Introduction

WARNING



ELECTRIC SHOCK CAN KILL

Disconnect electrical power before performing any maintenance.

All work requiring removal of the plasma power supply cover must be performed by a qualified technician.

See the *Safety and Compliance Manual (80669C)* for more safety precautions.

CAUTION



Static electricity can damage circuit boards. Use proper precautions when handling printed circuit boards.

Store PC boards in anti-static containers.

Wear a grounded wrist strap when handling PC boards.


Purpose

This Field Service Bulletin describes how to install a voltage divider board/VDC3 board in an XPR300 plasma power supply, and how to make all of the necessary cable and wire connections.

Diagram of board, cable, and wire connections

See *Figure 1* for an overview of the board, cable, and wire connections inside the plasma power supply.

Figure 1 – Connections inside the plasma power supply



- | | |
|--|---|
| <p>1 Plasma power supply</p> <p>2 Board: VDC3 (141201)</p> <p>Wire harness in the plasma power supply</p> <p>3 Wires: VDC3 board 120 VAC</p> <p>4 Wires: Arc voltage</p> | <p>5 Male connector to VDC3 board (pre-installed on the VDC3 board)</p> <p>6 Cable and connector to the computer numerical controller (CNC) (customer supplied)</p> |
|--|---|



Part numbers are shown for parts included in the kit. For more information about parts included in the kit, see *Kit contents* on page 5.

Tools and materials needed

- #2 Phillips® screwdriver
- 10 mm hex socket wrench or nut driver

Kit contents


Part number	Description	Quantity
141201	Board: VDC3 (includes connector)	1
809700	FSB: XPR300 VDC3 Board Installation	1



The wire harness to connect the VDC3 board is located in a clip inside of the plasma power supply. The wiring harness includes the arc voltage wires and the power wires.

Install and connect the VDC3 board (141201)

Figure 2 – VDC3 board




J1 120 VAC wires connector

J3 Arc voltage wires connector


J2 VDC3 board cable connector

1. Use a 10 mm hex socket wrench or nut driver to remove the rear panel of the plasma power supply.


Figure 3



2. Use a #2 Phillips screwdriver to remove the 4 screws from the studs.




3. With J3 on top, use the 4 screws to install the board on the studs. Tighten the screws to 9.2 kg·cm (8.0 in·lb).



Connect the VDC3 board (141201)


1. Remove the wire bundle from the wire clip in the plasma power supply.



The wire bundle is included in the plasma power supply. The bundle includes the arc voltage wires and power wires.


2. Connect one end of the VDC3 120 VAC harness to J1 of the VDC3 board with the tab on top. See *Figure 4*.
3. Connect the other end of the VDC3 120 VAC harness to the 120 VAC connector.

Figure 4




4. Attach the spade connector of the yellow wire (WORK) to the J3-WORK terminal. See *Figure 5*.
5. Attach the spade connector of the yellow/black wire (NEG) to the J3-ELECTRODE terminal.


Figure 5



- 6.** Attach the ring connector on the yellow wire (WORK) to the work bolt in the plasma power supply. Tighten the nut to 20 N·m (15 ft·lb).
- 7.** Attach the ring connector on the yellow/black wire (NEG) to the negative bolt in the plasma power supply. Tighten the nut to 20 N·m (15 ft·lb).

 Other wires are already attached to the bolts in the plasma power supply. Attach the arc voltage wires on top of the existing wires.

- 8.** Use NCS (pin 3), NCE (pin 4), Aout+ (pin 6), and Aout- (pin 7) to connect to the CNC. See *Figure 2* on page 5 for the locations of the pins. See *Table 1* for the pinout.

 Use the interface requirements of your CNC for additional connection requirements.




Table 1 – Pinout for J2 on the VDC3 board

J2 on the VDC3 board	
Pin number	Signal
1	Not connected
2	+24 VDC (out)
3	Nozzle contact sense (output)
4	Nozzle contact enable (input)
5	24 VDC common
6	+ Analog out (40:1)
7	- Analog out (analog common)
8	EMI chassis ground (cable shield)

- 9.** Install the rear panel of the plasma power supply.