

***Hypertherm***<sup>®</sup>

Phoenix<sup>®</sup> Softwareversionen 10.7.0

Versionshinweise

809720DE | Revision 8 | April 2018

**Hypertherm Inc.**

Etna Road, P.O. Box 5010  
Hanover, NH 03755 USA  
603-643-3441 Tel (Main Office)  
603-643-5352 Fax (All Departments)  
info@hypertherm.com (Main Office Email)

**800-643-9878 Tel (Technical Service)**

technical.service@hypertherm.com (Technical Service Email)

**800-737-2978 Tel (Customer Service)**

customer.service@hypertherm.com (Customer Service Email)

**866-643-7711 Tel (Return Materials Authorization)****877-371-2876 Fax (Return Materials Authorization)**

return.materials@hypertherm.com (RMA email)

**Hypertherm México, S.A. de C.V.**

Avenida Toluca No. 444, Anexo 1,  
Colonia Olivar de los Padres  
Delegación Álvaro Obregón  
México, D.F. C.P. 01780  
52 55 5681 8109 Tel  
52 55 5683 2127 Fax  
Soporte.Tecnico@hypertherm.com (Technical Service Email)

**Hypertherm Plasmatechnik GmbH**

Sophie-Scholl-Platz 5  
63452 Hanau  
Germany

00 800 33 24 97 37 Tel  
00 800 49 73 73 29 Fax

**31 (0) 165 596900 Tel (Technical Service)****00 800 4973 7843 Tel (Technical Service)**

technicalservice.emea@hypertherm.com (Technical Service Email)

**Hypertherm (Singapore) Pte Ltd.**

82 Genting Lane  
Media Centre  
Annexe Block #A01-01  
Singapore 349567, Republic of Singapore  
65 6841 2489 Tel  
65 6841 2490 Fax  
Marketing.asia@hypertherm.com (Marketing Email)  
TechSupportAPAC@hypertherm.com (Technical Service Email)

**Hypertherm Japan Ltd.**

Level 9, Edobori Center Building  
2-1-1 Edobori, Nishi-ku  
Osaka 550-0002 Japan  
81 6 6225 1183 Tel  
81 6 6225 1184 Fax  
HTJapan.info@hypertherm.com (Main Office Email)  
TechSupportAPAC@hypertherm.com (Technical Service Email)

**Hypertherm Europe B.V.**

Vaartveld 9, 4704 SE  
Roosendaal, Nederland  
31 165 596907 Tel  
31 165 596901 Fax  
31 165 596908 Tel (Marketing)  
**31 (0) 165 596900 Tel (Technical Service)**  
**00 800 4973 7843 Tel (Technical Service)**  
technicalservice.emea@hypertherm.com  
(Technical Service Email)

**Hypertherm (Shanghai) Trading Co., Ltd.**

B301, 495 ShangZhong Road  
Shanghai, 200231  
PR China  
86-21-80231122 Tel  
86-21-80231120 Fax  
**86-21-80231128 Tel (Technical Service)**  
techsupport.china@hypertherm.com  
(Technical Service Email)

**South America & Central America: Hypertherm Brasil Ltda.**

Rua Bras Cubas, 231 – Jardim Maia  
Guarulhos, SP – Brasil  
CEP 07115-030  
55 11 2409 2636 Tel  
tecnico.sa@hypertherm.com (Technical Service Email)

**Hypertherm Korea Branch**

#3904. APEC-ro 17. Heaundae-gu. Busan.  
Korea 48060  
82 (0)51 747 0358 Tel  
82 (0)51 701 0358 Fax  
Marketing.korea@hypertherm.com (Marketing Email)  
TechSupportAPAC@hypertherm.com  
(Technical Service Email)

**Hypertherm Pty Limited**

GPO Box 4836  
Sydney NSW 2001, Australia  
61 (0) 437 606 995 Tel  
61 7 3219 9010 Fax  
au.sales@Hypertherm.com (Main Office Email)  
TechSupportAPAC@hypertherm.com  
(Technical Service Email)

**Hypertherm (India) Thermal Cutting Pvt. Ltd**

A-18 / B-1 Extension,  
Mohan Co-Operative Industrial Estate,  
Mathura Road, New Delhi 110044, India  
91-11-40521201/ 2/ 3 Tel  
91-11 40521204 Fax  
HTIndia.info@hypertherm.com (Main Office Email)  
TechSupportAPAC@hypertherm.com  
(Technical Service Email)

© 2018 Hypertherm Inc. Alle Rechte vorbehalten.

EDGE, Phoenix, HPR, HPRXD, CutPro, ProNest, SensorTHC, True Hole, XPR300 und Hypertherm sind Schutzmarken von Hypertherm Inc., die in den Vereinigten Staaten und/oder anderen Ländern registriert sein können. EtherCAT ist eine Schutzmarke von Beckhoff Automation. Alle anderen Schutzmarken sind Eigentum ihrer jeweiligen Besitzer.

Seit langer Zeit schon besteht einer der wichtigsten Werte von Hypertherm darin, unsere Einwirkung auf die Umwelt so gering wie möglich zu halten. Darauf baut unter anderem unser Erfolg, aber auch jener unserer Kunden auf. Wir sind stets bemüht, unser Umweltbewusstsein noch mehr zu verbessern; dieser Prozess ist uns sehr wichtig.

# ***Inhalt***

<b>Install updates</b> .....	<b>7</b>
Before you begin .....	7
Available updates .....	8
Download the updates.....	9
Install the updates .....	10
Update the EDGE Connect Suite Installer.....	10
Update Phoenix .....	12
Update the cut charts.....	12
Update the online CNC help .....	13
Update manuals.....	13
Install ProNest 2017 version x.x.x.....	13
Update the XPR firmware.....	13
Replacing the launcher shortcut.....	14
<b>Version 10.7.0</b> .....	<b>17</b>
Versionshinweise.....	17
Neue Merkmale.....	17
Neue und aktualisierte Dokumentation .....	18
Verbesserungen .....	18
Phoenix-Fehlerbehebungen.....	18
Softwareversionen .....	21
Wird auf dem Phoenix-Diagnose-Bildschirm angezeigt .....	21
Wird auf dem Schneidtabellen-Bildschirm angezeigt .....	21
Wird in der XPR-Webanwendung angezeigt.....	22

Wird auf dem Windows-Bildschirm „Programme und Funktionen“ angezeigt.....	22
Sonst.....	22
<b>Version 10.6.1 .....</b>	<b>23</b>
Release notes .....	23
Phoenix resolutions.....	23
Software versions.....	25
Shown on the Phoenix Diagnostics screen .....	25
Shown on the Cut Chart screen.....	25
Shown in the XPR web application .....	26
Shown on the Windows Programs and Features screen .....	26
Other .....	26
<b>Version 10.6.0 .....</b>	<b>27</b>
Release notes .....	27
New and updated documentation.....	27
Improvements.....	27
ProNest CNC resolutions .....	29
Phoenix resolutions.....	29
Software versions.....	32
Shown on the Phoenix Diagnostics screen .....	32
Shown on the Cut Chart screen.....	32
Shown in the XPR web application .....	33
Shown on the Windows Programs and Features screen .....	33
Other .....	33
<b>Version 10.5.0 .....</b>	<b>35</b>
Release notes .....	35
New and updated documentation.....	35
Improvements.....	35
Phoenix resolutions.....	36
XPR .....	37
ProNest.....	37
Software versions.....	37
Shown on the Phoenix Diagnostics screen .....	37
Shown on the Cut Chart screen.....	38
Shown in the XPR web application .....	38
Shown on the Windows Programs and Features screen .....	38
Other .....	38

<b>Version 10.4.0 .....</b>	<b>39</b>
Release notes .....	39
Announcements.....	39
New features .....	39
Improvements.....	40
Torch types .....	41
V code.....	41
New tip types .....	42
Phoenix resolutions.....	43
XPR .....	44
ProNest.....	44
Software versions.....	45
Shown on the Diagnostics screen .....	45
Shown on the cut chart screen.....	46
 <b>Version 10.3.1 .....</b>	 <b>47</b>
Release notes .....	47
ProNest CNC.....	47
Version information for this release of ProNest CNC software.....	47
Phoenix resolutions.....	48
Software versions.....	49
 <b>Version 10.3.0 .....</b>	 <b>51</b>
Versionshinweise .....	51
Neue Merkmale.....	51
Verbesserungen .....	52
Phoenix-Fehlerbehebungen.....	52
Softwareversionen .....	53
 <b>Version 10.2.0 .....</b>	 <b>55</b>
Versionshinweise .....	55
Merkmale.....	55
Verbesserungen .....	55
Phoenix-Fehlerbehebungen.....	56
ProNest CNC-Fehlerbehebungen .....	57
Softwareversionen .....	58

<b>Version 10.01.0 .....</b>	<b>59</b>
Versionshinweise.....	59
Merkmale.....	59
Verbesserungen .....	59
Fehlerbehebungen .....	60
Softwareversionen .....	62
Version 10.01.0 installieren .....	63
Bevor Sie beginnen .....	63
Download und Installation des Updates.....	63

# ***Install updates***

## **Before you begin**

---

### **CAUTION**



**Create a backup of your CNC before AND after any updates are performed.  
Run the EDGE Connect Suite Installer before you update Phoenix.**

Do the following:

- **Make sure the CNC has image 27 or later and Phoenix version 10.00.0 or later.** Do not install this update if the CNC does not have these software versions.
  - To check which versions the CNC has, choose **Main > Setups > Diagnostics > Control Information**. Under **Software Versions**, see the **Phoenix** and **System Image** boxes. If you need to update the system to image 27 or later and Phoenix version 10.00.0 or later, contact your regional Product Application Engineer (PAE) or Technical Support Team.
- Create a back up of your CNC before and after any updates are performed. See *Backup and Restore the System* in the *EDGE Connect Installation and Setup manual* (809340) for details.
- Back up the CNC's system files: choose **Main > Files > Save to Disk > Save System Files to Disk**.

## Install updates


- If the CNC has a custom software operator console (Soft Op Con), back up the custom Soft Op Con application and associated **steps.json** file by copying the files to a USB memory stick. The steps.json file is located in the C:\Phoenix folder. The custom Soft Op Con files are located wherever they were saved originally. They are often located in a folder in the Phoenix folder.



If a unique name was not used for the custom Soft Op Con when it was created, the custom Soft Op Con will be replaced and any existing files will be overwritten with the standard Hypertherm Soft Op Con when this update is installed.

## Available updates

Based on your system configuration you may need to complete all of the updates shown below.

- CNC software (CNC system software **only**)
  - EDGE® Connect Suite Installer (updates ProNest® CNC, EtherCAT® Master Stack, Backup and Restore utility, and INtime®)
  - Phoenix software
  - Cut charts
  - Online help file
- XPR firmware
  - For instructions on updating the firmware and where to find the update see the *XPR300 Firmware Updates Field Service Bulletin* (809820).
  - Go to *Software versions* on page 37 to see the XPR firmware version that is compatible with this Phoenix release.
- ProNest 2017
  -  ProNest 2017 is the desktop version. **This is not the update for ProNest CNC.**
- Manuals



## Download the updates

1. On the [www.hypertherm.com](http://www.hypertherm.com) website, choose **Customer support > Product service > Phoenix software updates**.
2. Click **GET FILES** for the software updates
3. Right-click on the software file for the applicable language and save it to the root directory of a USB memory stick.



We recommend updating Phoenix in two parts if you are installing a language. First update the CNC with the English version and then update Phoenix using the language of choice.

4. Install the software in the following order. See figure below.
  - a. EDGE Connect Suite Installer
  - b. Phoenix software
  - c. Cut charts
  - d. Online help

Phoenix version 10 is only to be used with EDGE® Connect CNCs.

### To install update:

1. Check the **release notes** for important product and software installation information.

- English (900KB)

2. Download the **cut chart file** (includes all languages).



**DOWNLOAD CUT CHARTS (412KB)**

3. Click on the language below and download the files you need.



Language	Release notes	Phoenix update	Online CNC Help file	EDGE Connect Suite installer (ProNest CNC only)
English	900KB	15MB	700KB	280MB
Chinese - simplified		26MB	700KB	


The EDGE Connect Suite Installer now updates: ProNest CNC, EtherCAT Master Stack, Backup and Restore utility, and INtime

- e. ProNest 2017. See *Install ProNest 2017 version x.x.x.* on page 13.
- f. Manuals. See *Update manuals* on page 13.


## Install the updates


### Update the EDGE Connect Suite Installer

1. At the CNC, put the USB memory stick in a USB connector on the CNC.
2. Click anywhere in the **Main** screen of Phoenix, and then press **Alt+F4** to exit Phoenix.
3. Close any other software running on the CNC.
4. Click the Windows® Start button and go to File Explorer to view the USB contents.
5. Copy the EDGE\_Connect\_Suite\_x.x.x.x\_x86\_en.exe file to the **C:\Phoenix** directory.


 Delete the file after the update is complete.

6. Double-click the **EDGE\_Connect\_Suite\_x.x.x.x\_x86\_en.exe** file. An installer window opens.
7. Check the box to agree to the terms and conditions, and then click **Install** to begin the process.



 The CNC may restart multiple times during the update.

8. When you see the Installation Successfully Completed message shown below, click Restart.



9. After the CNC restarts two errors **ntx.dll and nttext.dll missing** may appear. Click OK to clear the errors. When the installation is complete, two messages are displayed - **Installation Successfully Completed** and **The Archive Was Restored Successfully** (disregard this message). Click Restart again.



If your cutting system has Phoenix version 10.3.1 or earlier and you are using Yaskawa EtherCAT drives, you need to re-configure the EtherCAT network after installing this update. That is, re-scan the EtherCAT network and create a new Phoenix.xml file. See the *Configure the EtherCAT Network* section in the *EDGE Connect Installation and Setup Manual* (809340) for instructions.


## Update Phoenix

1. To update Phoenix choose **Setups > Password** on the **Main** screen.
2. Type **UPDATESOFTWARE** (one word) and then choose **OK**.



The update software password will cause Phoenix to look for the PhoenixSuiteInstaller.exe file on your thumb drive.

3. When prompted, choose **OK**.



4. Wait while the update is installed.




Multiple windows will open and close automatically. This is normal.

5. Once the update is installed, the CNC restarts and Phoenix opens and begins to start the EtherCAT network.

## Update the cut charts

1. Download the cut charts to a USB memory stick. See *Download the updates* on page 9.
2. At the CNC, put the USB memory stick in a USB connector on the CNC.
3. Go to the **Cut Chart** screen (**Main > Setups > Process > Cut Chart**) and select the **Load Cut Charts** soft key.
4. Select Yes when the following message appears.



5. A status message appears. The update is complete when the status message disappears.



Phoenix must be restarted to make the new cut charts available

## Update the online CNC help

1. Download the **Online CNC Help** file to a USB memory stick. See *Download the updates* on page 9.
2. At the CNC, put the USB memory stick in a USB connector on the CNC.
3. Go to the **Special Setups** screen (**Main > Setups > Password > Special Setups**) and select the **Update Help** soft key.
4. A status message appears. The update is complete when the status message disappears.

## Update manuals

1. Go to the Hypertherm Document Library at [www.hypertherm.com/docs](http://www.hypertherm.com/docs) and download the manuals you want to update onto the USB memory stick.
2. At the CNC, put the USB memory stick in a USB connector on the CNC.
3. Go to the **Special Setups** screen (**Main > Setups > Password > Special Setups**) and select the **Update Manuals** soft key.
4. Click **OK** when the status message appears that says the update is complete.

## Install ProNest 2017 version x.x.x.

1. Log in (or create a new account as needed) to the [Hypertherm CAD/CAM Software Knowledge Base](#).
2. Choose **ProNest > Downloads > ProNest 2017 > Get the latest version of ProNest 2017**.
3. Follow the instructions provided in the knowledge base.



The knowledge base contains more information about the ProNest update as well as a variety of relevant CAM-specific training and educational content for channel partners.

4. Contact your regional Product Application Engineer (PAE) or [Technical Support Team](#) to get the latest XPR Machine Setup for this version of ProNest.

## Update the XPR firmware

For instructions on how to update the XPR firmware see the *XPR300 Firmware Updates Field Service Bulletin (809820)*. If you do not have this document, Technical documentation is available at [www.hypertherm.com/docs](http://www.hypertherm.com/docs).


## Replacing the launcher shortcut

This section is for TSEs, PAEs, and OEMs who are upgrading an existing system to Phoenix 10.6.


In the 10.6 release the name of the launcher changed from Phoenix Launcher to EDGE Connect Launcher to highlight that more than just Phoenix software is launched when the EDGE Connect launcher is used.

The Edge Connect software automatically starts when the EDGE Connect is powered on. The software can be launched manually by opening the Windows Start menu and selecting the Phoenix Launcher shortcut. In the 10.6 release the short cut was removed from the Start Menu. To add a short cut back to the Start menu follow the steps below.


1. To make the task bar visible, position the mouse at the top of the screen or drag a finger from the top of the screen down.
2. Select the Start menu icon in the upper left corner of the screen and select All apps at the bottom of the menu.



3. Look for the Hypertherm folder and select it to expand the list and show the EDGE Connect Launcher short cut.



4. Pin the EDGE Connect Launcher short cut to the Start menu by dragging and dropping the EDGE Connect Launcher to the Start Menu.



***Install updates***



# Version 10.7.0

## Versionshinweise

---

### Neue Merkmale

- Es wurde die Möglichkeit hinzugefügt, die Diagnose für bis zu zwei XPR300-Plasma-Stromversorgungen am CNC-over-EtherCAT-System zu überwachen. Von Phoenix aus können Sie nun die meisten Informationen über die Plasma-Stromquelle, das Gassystem und den Diagnosecode sehen, die Sie im XPR-Webinterface auf Ihrem drahtlosen Gerät finden.
  - Um zur XPR-Diagnoseansicht in Phoenix zu gelangen, wählen Sie Konfiguration > Diagnose > XPR System.
  - Weitere Informationen siehe *Cut and Mark with an XPR300™ auf einer EDGE® Connect CNC (809900 Revision 3)*.
- Phoenix überprüft nun die Bildschirmauflösung, um festzustellen, ob sie mit den von Hypertherm empfohlenen Einstellungen übereinstimmt. Wenn die Bildschirmauflösung nicht mit den von Hypertherm empfohlenen Einstellungen übereinstimmt, wird beim Start eine Meldung angezeigt.
  - Wählen Sie Nein, um die aktuellen Einstellungen beizubehalten. Die Nachricht wird nicht erneut angezeigt.
  - Wählen Sie Ja, um das Bedienfeld zu starten und die Anzeigeeinstellungen zu ändern. Nachdem die Anzeigeeinstellungen geändert wurden, wird die Nachricht nicht erneut angezeigt.

Der Bildschirm „Systemtools“ wurde um eine Schaltfläche „Anzeigeeinstellungen“ erweitert, über die das Systemanzeige-Bedienfeld aufgerufen wird, um die Anzeigeeinstellungen jederzeit einfacher anpassen zu können.
- Wenn Phoenix startet, wird das Logo Hypertherm „50 YEARS OF SHAPING POSSIBILITY“ für 3 Sekunden angezeigt. Das Logo wird nur im Kalenderjahr 2018 erscheinen.

## Neue und aktualisierte Dokumentation

- Das Mitteilungsblatt für den Außendienst *RMA Process for Software Features* (810150), in dem Anweisungen zum Entfernen von Softwarefunktionen aus EDGE Connect CNCs enthalten sind, wurde erstellt. Das Mitteilungsblatt für den Außendienst ist in der Hypertherm Document Library unter [www.hypertherm.com/docs](http://www.hypertherm.com/docs) verfügbar.
- Der Handbucharhang *Cut and Mark with an XPR300 auf einer EDGE Connect CNC* (809900) wurde aktualisiert. Der Handbucharhang ist in der Hypertherm Document Library unter [www.hypertherm.com/docs](http://www.hypertherm.com/docs) verfügbar.
- Die Phoenix-HTML-Hilfe mit Anweisungen zur Anzeige der XPR-Diagnose auf dem CNC-over-EtherCAT wurde aktualisiert.

## Verbesserungen


- Unterstützung für das Beckhoff EL2004 4-Kanal-Digital-Ausgangsmodul wurde hinzugefügt.

## Phoenix-Fehlerbehebungen

- Ein Problem wurde behoben, bei dem zugeordnete Netzwerkordner nach dem Neustart von Phoenix und EDGE Connect nicht ordnungsgemäß beibehalten wurden.
- Ein Szenario wurde behoben, in dem Joystick-Jogging stoppen, starten und in die falsche Richtung gehen kann, wenn die folgenden Bedingungen erfüllt sind. Es ist auch möglich, auf einem Softlimit festzustecken, wenn die folgenden Bedingungen erfüllt sind:
  - Doppel-Transversale ist aktiviert und wurde gespiegelt.
  - Die Maschine wurde referenziert und Softlimits sind in den Konfigurationsbildschirmen Transversal- und Schienenachse aktiviert.
- Ein Problem mit einer einzigen Plasmastation und deaktivierter Einstellung „Stopp bei Einzelbogenverlust“, während mit einem einzigen XPR-Plasmabrenner an Station 1 geschnitten wird, wurde behoben. Wenn der Lichtbogen während des Schneidens verloren ging (Verlust des Schneidsinns ist aufgetreten), zog sich der Brenner zum oberen Ende der Höhenverstellung zurück, aber die Schnittbewegung wurde fortgesetzt, bis der Benutzer auf Stopp drückte.
  - Jetzt wird bei einer einzigen Plasmastation und deaktiviertem „Stopp bei Einzelbogenverlust“ das Programm nach Ablauf der Auslösezeit angehalten und die CNC zeigt die Statusmeldung „Verlust des Schneidsinns“ an.
  - Bei mehreren Plasmastationen und deaktiviertem „Stopp bei Einzelbogenverlust“ wird, wenn ein Brenner den Schneidsinn verliert, dieser Brenner zurückgezogen und der Schneidvorgang an den übrigen Arbeitsstationen fortgesetzt.
- Ein Problem wurde behoben, bei dem Phoenix keinen FieldbusDeviceFault für Kollmorgen-AKD-Antriebe generierte, wenn ein Antriebslevelfehler auftrat, während der Field Bus im Betriebszustand war.
- Ein Problem mit dem CutPro-Assistenten wurde behoben, das bei der Auswahl von „Zurück“ (zum vorherigen Bildschirm) oder bei der Auswahl einer Schneidtablelle zu einem Phoenix-Anwendungsfehler führte. Außerdem wurde ein Problem behoben, bei dem das

Navigieren vorwärts (Überspringen) und rückwärts (Zurück) im CutPro-Assistenten dazu führte, dass die falschen Schneidtabellenfelder im Auswahlprozessfenster des CutPro-Assistenten angezeigt wurden.

- Ein Problem wurde behoben, das auftrat, wenn ein Teil manuell mit den Einstellungen gespiegelte X oder Y im Bildschirm „Aktuelle Teileoptionen“ geändert wurde. Wenn ein Teil mit diesen Einstellungen gespiegelt wurde, konnten die Eilgangsegmente im Teil einen Hardware- oder Software-Overtravel verursachen.
- Ein Problem wurde behoben, bei dem die Installation der EDGE Connect Suite während des ProNest-CNC-Segments der Installation fehlschlug. Die Fehlermeldung „Konfiguration fehlgeschlagen“ wird mit dem Fehlercode „0x80042000 - Unspezifizierter Fehler“ angezeigt.



- Ein Problem wurde behoben, bei dem Phoenix nicht mehr reagierte, wenn der Benutzer ein Teil mit einem Prozess für ein Werkzeug geladen hatte, das nicht für seine Schneidmaschine konfiguriert war (ein HPR-Programm wurde auf einer für XPR konfigurierten CNC geladen). Jetzt pausiert Phoenix und gibt „Ungültiger Prozess im Teileprogramm angefordert“ als Grund an. Der Benutzer muss dieses Problem lösen, bevor er das Programm neu starten darf.
  - Mögliche Ursache:
    - Laden Sie ein gültiges Teileprogramm für dieses Schneidsystem
    - Das Teileprogramm enthält Codes der Form G59 V5xx Fxx, die eine Schneidtable für ein anderes Werkzeug auswählen.
    - Das Teileprogramm enthält einen Schneidprozess (Markierung, Wasserstrahl, Laser, Plasma 2), der nicht konfiguriert ist. Beispiel: M09/M10-Markiercodes im Teileprogramm, aber der Markierprozess wird in der Schneidtable auf „Keiner“ gesetzt, oder der Schneidprozess hat keinen Markierungsprozess (Unterwasser als Schnittfläche ausgewählt).
  - Mögliche Lösungen:
    - Deaktivieren Sie vorübergehend den **EIA G59 Code Override** in der Programmcodetabelle des Schneidbildschirms.
    - Wählen Sie einen Schneidprozess aus der Schneidtable, der dem Teileprogramm entspricht. Bei Markierung muss ein Markierungsgas gewählt werden (N2 oder Ar).
    - Deaktivieren Sie **Prozessauswahl-Override**, wenn das Programm einen Prozess aufruft, der nicht in der CNC konfiguriert ist.

- Ein Problem wurde behoben, das dazu führte, dass der Geschwindigkeitssollwert-Parameter im watch window bei der Verwendung des Geschwindigkeits-Potenzimeters während des Testens einen falschen Wert anzeigte. Die Maschine bewegte sich mit der richtigen Geschwindigkeit, aber diese Geschwindigkeit wurde im watch window nicht korrekt angezeigt.
- Die Operation zum Wiederherstellen der letzten Version setzt jetzt sowohl im Verzeichnis C:\Phoenix als auch in der gewünschten Sprache korrekt auf die vorherige Version der Software zurück.
- Die Möglichkeit, dass ein Bediener ein Teil in ein Softlimit verschieben und weiterschneiden konnte, nachdem ihm der Dialog für Softlimits angezeigt wurde, wurde entfernt. Die Option zum Abbrechen des Dialogs wurde entfernt. Dieses Szenario ist nun konsistent mit vorhandenen Softlimit-Prüfungen.
- Ein Problem wurde behoben, bei dem die spanischen Übersetzungen „für Field Bus antriebe nicht bereit“ und „Systeminformationen fehlgeschlagen - Fehler“ falsch waren.

## Softwareversionen



Sie müssen bei Image 27 oder höher sein, um dieses Update durchzuführen.

Die Versionen für die Software und Firmware im aktuellen Update werden an verschiedenen Stellen auf der EDGE Connect CNC angezeigt. Die folgende Tabelle ist nach dem Ort gruppiert, an dem die Versionsinformationen angezeigt werden.

- So können Sie sich Versionsinformationen für Windows-, Phoenix-, Real-Time-OS-, Fieldbus-Master-, Real-Time-Module-, PLC-engine-, System-Image- und Op-Con-APIs ansehen:

Wählen Sie **Hauptmenü > Konfiguration > Diagnose > Steuerungs-Informationen**.

- Um Versionsinformationen für Schneidtabellen anzeigen zu lassen, wählen Sie **Hauptmenü > Konfiguration > Prozess > Schneidtablette**. Die Versionsinformationen werden in der oberen linken Ecke des Bildschirms angezeigt.
- Um Versionsinformationen für andere Elemente anzeigen zu lassen, klicken Sie auf die Windows-Startschaltfläche und rufen Sie **Alle Anwendungen > Windows-System > Systemsteuerung > Programme und Funktionen** auf.



Wenn Sie die CNC aktualisieren müssen oder weitere Fragen zu Softwareversionen haben, wenden Sie sich an Ihr regionales [technisches Support-Team](#).

### Wird auf dem Phoenix-Diagnose-Bildschirm angezeigt

Position	Versionen/Revisionen
Windows	10.00.10240
Phoenix	10.7.0
Real-Time OS	6.3.17188.1
Field Bus Master	1.5.61015.0
Real-Time Module	10.7.0.1507
PLC engine	1.1.0.0
Phoenix OpCon API	2.0.0.0
Active OpCon APIs	2.0.0.0

### Wird auf dem Schneidtabellen-Bildschirm angezeigt

Position	Versionen/Revisionen
XPR	K
HPRXD	AA
HPR	80003Ea und 80003Eb
Oxyfuel	F – Erweitertes Format A

**Wird in der XPR-Webanwendung angezeigt**

Position	Versionen/Revisionen
XPR main control	G – 472
XPR torch connect	G – 180
XPR gas connect	G – 122
XPR choppers	G – 169
XPR wireless	24095

**Wird auf dem Windows-Bildschirm „Programme und Funktionen“ angezeigt**

Position	Versionen/Revisionen
ProNest CNC Client	1.1.5.210
ProNest CNC Package	1.1.9
ProNest CNC Nesting software	12.1.3.6507
KPA EtherCAT Studio	1.12.259.0
KPA Licensing utilities	2.3.106.0
Microsoft XML Notepad	2.7.1.15
EDGE Connect Suite	1.4.6673.34133
EDGE Connect Launcher	1.4.6673.33634
Backup and Restore Utility	1.1.6592.40703
EtherCAT ESI Library	1.0.23.0

**Sonst.**

Position	Versionen/Revisionen
MULTIPROG	1.2
SoftOpCon	2.1.0.410
MinReqOpCon	2.1.0.410
Bedienerkonsole	1.0

# ***Version 10.6.1***

## **Release notes**

---

### ***NOTICE***



This is an unplanned release for EDGE Connect CNCs to address a reported field issue discovered in Phoenix version 10.6.0 software that was released earlier in January. For improved safety, all customers, especially any customers currently using version 10.6.0, are urged to update their software to Version 10.6.1.

## **Phoenix resolutions**

- Resolved an issue for incorrect motion on mirrored part programs in Phoenix that resulted in the rapid traverse segment moving in the opposite direction, and significantly farther, than expected.
- Removed the ability for an operator to move a part into a soft limit and continue cutting after canceling the soft limits dialog. The option to Cancel the dialog was removed to be consistent with existing soft limit checks.

- Resolved an issue where the EDGE Connect Suite installer failed during the ProNest CNC segment of the installation and the message shown below was displayed.





## Software versions



You must be at image 27 or higher to perform this update.

The versions for the software and firmware in the current update are shown in different locations on the EDGE Connect CNC. The table below is grouped by the location where the version information is shown.

- To see version information for Windows, Phoenix, Real-Time OS, Field Bus Master, Real-Time Module, PLC engine, System Image, and Op Con APIs:  
Choose **Main > Setups > Diagnostics > Control Information**.
- To see version information for cut charts choose **Main > Setups > Process > Cut Chart**. The version information is displayed in the top left corner of the screen.
- To see version information for other items click the Windows Start button and go to **All apps > Windows System > Control Panel > Programs and Features**.



If you need to update the CNC or have any other questions about software versions, contact your regional [Technical Support Team](#).

### Shown on the Phoenix Diagnostics screen

Item	Versions / Revisions
Windows	10.00.10240
Phoenix	10.6.1
Real-Time OS	6.3.17188.1
Field Bus Master	1.5.61015.0
Real-Time Module	10.6.1.1504
PLC engine	1.1.0.0
Phoenix OpCon API	2.0.0.0
Active OpCon APIs	2.0.0.0

### Shown on the Cut Chart screen

Item	Versions / Revisions
XPR	K
HPRXD	AA
HPR	80003Ea and 80003Eb
Oxyfuel	F - Extended format A

**Shown in the XPR web application**

Item	Versions / Revisions
XPR main control	F - 472
XPR torch connect	F - 180
XPR gas connect	E - 122
XPR choppers	E - 169
XPR wireless	22311

**Shown on the Windows Programs and Features screen**

Item	Versions / Revisions
ProNest CNC Client	1.1.5.210
ProNest CNC Package	1.1.9
ProNest CNC Nesting software	12.1.3.6507
KPA EtherCAT Studio	1.12.259.0
KPA Licensing utilities	2.3.106.0

**Other**

Item	Versions / Revisions
MULTIPROG	1.2
SoftOpCon	2.1.0.410
MinReqOpCon	2.1.0.410
Hardware operator console	1.0

# Version 10.6.0

## Release notes


---

### New and updated documentation

- Updated the application note, *Panasonic EtherCAT Drives Supported by EDGE Connect CNCs* (809760) to add support for Panasonic A6 drives. The application note is available in the Hypertherm Document Library at [www.hypertherm.com/docs](http://www.hypertherm.com/docs).
- Updated the application note *Bosch Rexroth EtherCAT Drives Supported by EDGE Connect CNCs* (809600) to add support for Bosch economy drives. The application note is available in the Hypertherm Document Library at [www.hypertherm.com/docs](http://www.hypertherm.com/docs).
- Updated the application note *Mitsubishi EtherCAT Drives Supported by EDGE Connect CNCs* (809750) to add support for J4 drives. The application note is available in the Hypertherm Document Library at [www.hypertherm.com/docs](http://www.hypertherm.com/docs).

### Improvements

- Added support for Bosch economy drives.
- Added support for Panasonic A6 drives.
- Updated the Phoenix simulation software so the EtherCAT screens look like a real EtherCAT network is present. This allows a demonstration of Phoenix that shows how the setup screens would look on a real CNC.
- The operator is no longer able to choose to run a part or nest when the Soft Limits will be exceeded. The operator has to fix the overshoot. If this is not acceptable, the Nest/Soft Limit Checks can be disabled in the Special Setups (Not Recommended).

- Updated the Transfer Height and Pierce Height fields for XPR in Phoenix to support only absolute values in inches or millimeters. This change creates consistency with the XPR cut charts which list Transfer Height and Pierce Height as absolute values instead of percentages of Cut Height.
  - Updated the timeout in the Hypertherm EtherCAT Studio launcher for version 1.12.259.0 to allow acquiring a license with a larger number of slave ESI files in the slave library directory. This corrects an issue where the Hypertherm EtherCAT Studio name on the title bar has “- Trial” at the end of it. In the About dialog box the Product name: also says, “Hypertherm EtherCAT Studio - Trial” and the Licensed to: and Expire date: both say “No license”.
  - Updated the Marker Font Generator to support Retract to Transfer for all segments of a text string except the last segment where a normal Retract is used. This update provides faster marking and prevents torch crashes on warped or uneven surfaces when marking multiple locations on a plate.
  - Added the ability to resume a part after a fault that requires homing on a table with a dual transverse axis, to allow a part or nest to finish cutting. When the cut is resumed with both the Transverse and the Dual Transverse unparked, the Dual Transverse now re-spaces to the previous spacing before moving to the Resume Part location.
  - Added support for Yaskawa sigma7 series 400 V drives.
    - SGD7S-xxxxA0xxxF64 models with rev 7.01, 7.03, 7.06, 7.08, 7.10, 7.11 firmware. Product Code 0x02200401.
  - Updated the Phoenix Simulation software to include the features listed below when no HASP is found. This change allows the use of the Phoenix simulation software without a HASP.
    - Oxyfuel: Advanced and Bevel
    - Plasma: Advanced, 2 Bevel, 4 Advanced Sensor THCs, Pipe and Tube Bevel, and Dual Transverse
    - Waterjet: Advanced, 2 Sensor WHCs, and 2 Bevel
-  An announcement will be distributed in early 2018 when the simulation is available.
- Added the ability to move the THC up and down the full length of the slide when cutting in manual mode and using a waterjet process. Added a manual increment parameter to the machine setups for the THC. This parameter has a range of 0.001 – 0.100 inches. This parameter is the distance the THC travels when the raise or lower THC button is pressed while cutting in manual mode. In previous versions the THC could only raise up 1 inch above cut height and could only lower back down to the cut height.
  - Improved the installation experience by keeping Phoenix and Software Operator Console (Soft Op Con) applications from being launched when the CNC restarts as part of the EDGE Connect Suite installation process.

## ProNest CNC resolutions

- Fixed the following part program issues in ProNest CNC
  - HPRXD Stainless Steel HDi process information
  - MAXPRO200 transfer height process information
  - Updated cutting techniques and part lead-ins for HPR

## Phoenix resolutions

- Resolved issue where an HPR plasma supply could get stuck without motion after an arc has been established. The state of each HPR plasma supply is now updated every time the operator begins or resumes a part program or activates a Rip Cut or Rip Mark operation.
- This corrects an issue where ArcWriter could not be selected in the Station Configuration screen. Re-enabled the capability for Marking Only power supplies in the Station Configuration screen.
- Resolved an issue where AC style bevel heads would not return to the proper bevel angle when pausing, going off path and resuming a part program.
- When pausing an XPR marking segment, the operator only has marking process options in the Cut Chart screen. Previously, both plasma and marking process options were displayed but only changes to marking options are valid.
- Fixed an issue that could cause an analog input mapped to a speed pot to momentarily display a different speed or zero in the process speed watch window. This would also cause the speed of the motion to change during that period.
- When an XPR operator uses the Cut Pro Wizard to load a part, they will now see the consumables needed to cut that part, unless G59 codes are disabled. If G59 codes are disabled, then the operator will see the process selection screen (Cut Chart screen), followed by the consumables that match the process that is selected.
- Resolved an issue where an unexpected command window was displayed when the network was being phased up while using Mitsubishi drives.
- Fixed an issue where changing the cut height in an XPR part program would also incorrectly change the transfer height and the pierce height. Changing the cut height with M07 overrides now only changes the cut height.
- Resolved the following issues with Soft Limits:
  - Repeated parts are now checked against the soft limits.
  - Non-repeated and repeated parts are now checked against the soft limits when the part programs are resumed after a pause in cutting, Power Down or Power Loss.
  - Transposed parts will now be properly checked against the Soft Limits.
- Improved a stability issue that occurred when restarting the EtherCAT network after turning off the power to a plasma supply. When power is restored, the network can be restarted without displaying an error. The improvement was made by updating the Field Bus Master to 1.5.61015.0.
- Resolved an issue where the metric units were not displayed in the oxyfuel cut chart screen, when the system was set to metric mode.

- When an operator changes language, the following will now happen as expected:
  - The manuals folder holds a copy of all the PDF files for the system. If there are language files for the selected language, those will be displayed. If there are not files for the selected language, the English copy of the file will be displayed.
  - When the Help button is selected, a help screen will be displayed with information. If the selected language has translated help, it is displayed. If the selected language does not have translated help it will be displayed in English.
- Resolved an issue with the XPR plasma supply that caused cutting instead of marking. If the operator pauses an XPR during marking and manually changes to a cutting process on the Cut Chart screen, the marking process is maintained when cutting resumes.
- Resolved an issue where pressing the E-Stop button during a rip cut prevented cutting or motion after the E-Stop has been cleared.
- Resolved an issue where the Ready to Start message was displayed incorrectly. If the Ready to Start message is disabled and an operator pressed the green Cycle Start button on the Soft Op Con while a cycle start operation (cutting, trialing, rip cutting, etc.) was already in progress, the Ready to Start message was displayed the next time the F9 keyboard key or green hard OpCon Cycle Start button was pressed to initiate a cycle start operation.
- Resolved an issue with the XPR where the part program did not pause if the XPR failed to produce an arc at the pierce point. If an XPR fails to transfer an arc to the work piece or fails to produce a pilot arc, the cut is now paused and a dialogue box is displayed to inform the user of the issue. The cut is also now paused instead of remaining locked on the cut screen when a Cut Sense Lost error occurs while using an XPR.
- Resolved an issue where XPR Not Ready dialog was taking precedence over an XPR Error or Fault. The XPR Not Ready message was displayed when an XPR had an active error and Cycle Start was pressed. The correct message is now displayed when the program is paused due to an XPR error. The operator may still receive the dialog message XPR Not Ready, but the message will only show when cycle start is pressed and the XPR is not in the Wait for Start or Initial Checks state.
- Fixed an issue that allowed the cutting table to move through a soft limit during table alignment. Support was added for a warning message to indicate that soft limits will be exceeded prior to final alignment. If the machine has been homed, this message will prevent final alignment until the alignment settings and final alignment are within the soft limits. The message is shown below:
  - Final Alignment will exceed Machine Software Travel Limits. Please check corner to align with, and repeat alignment.
- Made the following improvements to the XPR Not Ready dialog message:
  - Removed the “error” label. This message does not indicate an error condition.
  - Rewrote the message description for clarity. The description now states: “XPR must be in the Wait For Start or the Initial Checks state to start.”
  - Fixed an issue where the dialog incorrectly displayed because of an alarm, warning, or error condition. Dialogs for these conditions now include a more specific message.

- Resolved an issue where the CNC appeared to freeze (no response when the stop button was pressed) after trying to perform a plasma cut with the plasma station and the oxyfuel station enabled.
  - A part program is now paused and the Conflicting Process on Active Station status message is displayed if the cutting tool on an enabled station (such as an oxyfuel torch) does not match the cutting process. For example, the cut type is set to plasma 1 and the operator has the Oxyfuel cutting station enabled.
- Resolved an issue where the oxyfuel cut mode was not maintained when using ProNest CNC for nesting parts. Now the cut mode does not need to be changed after nesting when the CNC is in oxyfuel mode.
- Improved the ability of the Soft Op con to detect HID devices which prevents the Soft Op con from exiting when a 3rd party touchscreen is connected.

## Software versions



You must be at image 27 or higher to perform this update.

The versions for the software and firmware in the current update are shown in different locations on the EDGE Connect CNC. The table below is grouped by the location where the version information is shown.

- To see version information for Windows, Phoenix, Real-Time OS, Field Bus Master, Real-Time Module, PLC engine, System Image, and Op Con APIs:  
Choose **Main > Setups > Diagnostics > Control Information**.
- To see version information for cut charts choose **Main > Setups > Process > Cut Chart**. The version information is displayed in the top left corner of the screen.
- To see version information for other items click the Windows Start button and go to **All apps > Windows System > Control Panel > Programs and Features**.



If you need to update the CNC or have any other questions about software versions, contact your regional [Technical Support Team](#).

### Shown on the Phoenix Diagnostics screen

Item	Versions / Revisions
Windows	10.00.10240
Phoenix	10.6.0
Real-Time OS	6.3.17188.1
Field Bus Master	1.5.61015.0
Real-Time Module	10.6.0.1501
PLC engine	1.1.0.0
Phoenix OpCon API	2.0.0.0
Active OpCon APIs	2.0.0.0

### Shown on the Cut Chart screen

Item	Versions / Revisions
XPR	K
HPRXD	AA
HPR	80003Ea and 80003Eb
Oxyfuel	F - Extended format A



**Shown in the XPR web application**

Item	Versions / Revisions
XPR main control	F - 472
XPR torch connect	F - 180
XPR gas connect	E - 122
XPR choppers	E - 169
XPR wireless	22311

**Shown on the Windows Programs and Features screen**

Item	Versions / Revisions
ProNest CNC Client	1.1.5.210
ProNest CNC Package	1.1.9
ProNest CNC Nesting software	12.1.3.6507
KPA EtherCAT Studio	1.12.259.0
KPA Licensing utilities	2.3.106.0

**Other**

Item	Versions / Revisions
MULTIPROG	1.2
SoftOpCon	2.1.0.410
MinReqOpCon	2.1.0.410
Hardware operator console	1.0



# Version 10.5.0

## Release notes

---

### New and updated documentation

- Created an application note, *Absolute Positioning for Homing* (809870). It is available in the Hypertherm Document Library at [www.hypertherm.com/docs](http://www.hypertherm.com/docs).
- Updated the application note *Panasonic EtherCAT Drives Supported by EDGE Connect CNCs* (809760) with all the drives that are now supported. It is available in the Hypertherm Document Library at [www.hypertherm.com/docs](http://www.hypertherm.com/docs).

### Improvements

- Updated the Phoenix cut charts and ProNest CNC to support corrections and additions for Revision K of the XPR cut charts. The updates include:
  - 60A F5/N<sub>2</sub> stainless steel cut speed fixes.
  - Thick non-ferrous pierce setting fixes (170 A and 300 A non-ferrous).
  - 130A O<sub>2</sub>/Air pierce setting updates.
  - Added the 12 mm Al, 80A, N<sub>2</sub>/H<sub>2</sub>O process.
  - Added the 1.25 inch Al, 300 A, N<sub>2</sub>/H<sub>2</sub>O process.
- The EDGE Connect suite installer now updates INtime.
- Updated INtime to version 6.3 as part of routine maintenance.
- Support was added for absolute positioning for homing. For details see the application note *Absolute Positioning for Homing* (809870) in the Hypertherm Document Library at [www.hypertherm.com/docs](http://www.hypertherm.com/docs).

- Added support for Panasonic A5 drives. To see a list of all the drives that are now supported see the application note *Panasonic EtherCAT Drives Supported by EDGE Connect CNCs* (809760) in the Hypertherm Document Library at [www.hypertherm.com/docs](http://www.hypertherm.com/docs).
- A Conflicting Process on Active Station message is now displayed when a plasma process is used and an oxyfuel station (Station 9 and above) is enabled.
- M50H and M50N codes can now be used without the Click-Wrap license for the MAXPRO200®.
- Duplicate parameters are no longer listed in the Unable to Load the Following Setups dialog box.

## **Phoenix resolutions**

- Updated the EDGE Connect suite installer to resolve an issue where performing a system restore from a User Backup did not correct a corrupted INtime configuration.
- Resolved an issue with cut height override in a bevel part program that caused the pierce height to decrease by 2.5 times per pierce. The G59 V603 Fx code should be used for cut height override in bevel part programs.
- The Bevel Homing Prompt is no longer displayed if the Auto Home on Power Up setting is on.
- Resolved an issue where an unexpected transverse position error or dual gantry command-output error prevented a part program from being completed.
- Resolved an issue that caused Phoenix to stop working unexpectedly when a part program was started in Plasma mode when only an oxyfuel station was enabled.
- Resolved an issue where part programs with station select and process select codes corrupted oxyfuel cut charts when Phoenix translated the codes.
- Resolved an issue where Phoenix displayed the Invalid Process error from an XPR and would not allow a new part to be started.
- Resolved an issue that occurred when saving data in the Cut Chart screen. If values were modified and then saved to the cut chart data file, it was possible that the data could be corrupted. This corrupt data could cause Phoenix to stop working unexpectedly. This fix requires the latest cut charts files provided in this release.
- Resolved an issue with cut chart file formatting that resulted in corrupted oxyfuel and plasma cut charts.
- To safely stop cutting, waterjet pumps are turned off when Stop is pressed during a pierce.
- Resolved a Phoenix exception error that occurred with part programs that used the M65 auto reload code with filenames that contain all numbers (no letters in the filename prefix).
- Removed a soft key labeled F7 that was displayed in error on the laser mapping screen.
- Resolved an issue where a conflicting process error was displayed when a zinc marker was assigned to station 2 with an XPR assigned to station 1.

## XPR

- Updated firmware to support revision K of the cut charts. See *Improvements* on page 35 for details.

## ProNest

- Added support for revision K of the XPR cut charts. See *Improvements* on page 35 for details.

## Software versions



You must be at image 27 or higher to perform this update.

The versions for the software and firmware in the current update are shown in different locations on the EDGE Connect CNC. The table below is grouped by the location where the version information is shown.

- To see version information for Windows, Phoenix, Real-Time OS, Field Bus Master, Real-Time Module, PLC engine, System Image, and Op Con APIs:

Choose **Main > Setups > Diagnostics > Control Information**.

- To see version information for cut charts choose **Main > Setups > Process > Cut Chart**. The version information is displayed in the top left corner of the screen.

- To see version information for other items click the Windows Start button and go to **All apps > Windows System > Control Panel > Programs and Features**.



If you need to update the CNC or have any other questions about software versions, contact your regional [Technical Support Team](#).

### Shown on the Phoenix Diagnostics screen

Item	Versions / Revisions
Windows	10.00.10240
Phoenix	10.5.0
Real-Time OS	6.3.17188.1
Field Bus Master	1.5.61009.0
Real-Time Module	10.5.0.1495
PLC engine	1.1.0.0
Phoenix OpCon API	2.0.0.0
Active OpCon APIs	2.0.0.0

**Shown on the Cut Chart screen**

Item	Versions / Revisions
XPR	K
HPRXD	AA
HPR	80003Ea and 80003Eb
Oxyfuel	F - Extended format A

**Shown in the XPR web application**

Item	Versions / Revisions
XPR main control	F - 472
XPR torch connect	F - 180
XPR gas connect	E - 122
XPR choppers	E - 169
XPR wireless	22311

**Shown on the Windows Programs and Features screen**

Item	Versions / Revisions
ProNest CNC Client	1.1.4.209
ProNest CNC Package	1.1.9
ProNest CNC Nesting software	12.0.4.6250
KPA EtherCAT Studio	1.12.210.0
KPA Licensing utilities	2.1.104.0

**Other**

Item	Versions / Revisions
MULTIPROG	1.2
SoftOpCon	2.0.0.406
MinReqOpCon	2.0.0.406
Hardware operator console	1.0

# ***Version 10.4.0***

## **Release notes**

---

### **Announcements**

- Windows 10 is not affected by the latest ransomware malware attacks. All Windows 10 Security Updates are included in this update.
- There is a change in Delta EtherCAT drive support:  
Until a solution is found and proven by Delta, Hypertherm strongly advises against the use of Delta EtherCAT drives in combination with HPR, XPR, and MAXPRO200 cutting systems and in environments with the potential for high frequency electrical noise. This is due to the drive's susceptibility to high-frequency electrical noise, which causes EtherCAT field bus faults.

### **New features**

- A feature named Nest Limit Checks has been added to let you know if a part's nest will exceed the soft limits set for the cutting system. If a nest exceeds the soft limits, a warning message is displayed when start is pressed. The operator can stop and re-position the nest to fit on the table or proceed to run the part (not recommended).

The message is displayed if:

- The machine was homed
- Soft limits are enabled and programmed in the axis setup screens

The message is NOT displayed if you are using the following part programs:

- ABXYZ dual tilting bevel part programs. This feature may be supported in a future release.

- Pipe and tube part programs. This feature may be supported in a future release.
- Go to home commands that are programmed to exceed the soft limits set for the cutting system will now display a message to update the programmed go to home location.
- The HPR or XPR Cut Sense input is now used when the ResetPositionLog or RPL password is used to record position data. This feature requires either the Cut/Mark Sense or Cut Sense # input to be assigned to an input.
- Argon marking is now supported by using M07 AR in part programs. Argon or nitrogen can be selected as the marking gas from the manual cut chart selection screen.
- 3 new commands (R, G, and V) have been added to the Phoenix Marker Font Generator for XPR nitrogen and argon marking. They are intended to be used within ProNest software. The commands are not supported for use with the Shape Wizard.



See the ProNest software documentation for more details about marking with Argon.

The 3 new commands are:

- R: The sixth information block determines if a Retract to Transfer is used at the end of each segment of the marked text. The R is followed by a number to indicate the type of retract:
  - 0 = a full or partial retract depending on CNC setting
  - 1 = a retract to transfer height
- G: The seventh information block determines the type of marking gas used for XPR marking. The G is followed by a number to indicate the type of gas:
  - 0 = none
  - 1 = argon
  - 2 = nitrogen
- V: The eighth information block determines if the default marking speed is overridden with another speed. The V is followed by a number to indicate the new marking speed. Zero indicates that the default marking speed will be used. This number can be a decimal value.
- Gas flow tests can be started from the CNC, if the CNC is in control of the XPR. The test results are still viewed on the XPR web interface, but now the XPR web interface does not have to control the XPR for gas flow tests to be performed. Gas flow tests are started on the CNC via a new XPR System soft key on the Setups > Diagnostics screen.
- The Remote Status fixed function input can now be viewed in the Watch window and recorded in the Oscilloscope.

## Improvements

- A new cut type called Interior Features has been added. An alias, O2S, for the O<sub>2</sub>/O<sub>2</sub> cutting process is supported in the part program. M07 TH and M07 O2S have the same effect in the part program. ProNest determines when to output these codes. O2S has been added to avoid confusion if you read the part program when an O<sub>2</sub>/O<sub>2</sub> process is being used on something that is not a hole.



- Estimated creep time for XPR systems is now set to 0 as the default. Creep time is generally not needed with the XPR.
- Resolved an issue where the Pulley simple shape caused an invalid process with XPR systems. The EIA Pulley simple shape caused redundant G41, M07 codes.
- Phoenix now supports bidirectional torque limits for supported Panasonic drives.
- Support has been added for higher resolution encoder devices. To take advantage of these settings, reference the Application Note for the model of drive that you have. Use of higher resolutions is dependent on your particular application.
- A maintenance release from our software supplier has been applied to our existing PLC engine. With version 1.1.0, MULTIPROG now supports new versions of both PLC Connect and PLC Connect LT.
- Oxyfuel cut chart changes (see the tables below for details)

Oxyfuel cut charts have a new format and there are new tip types and EIA codes, and a new V code. The older cut charts still work, but the drop-down list of Tip Types is not shown.

### Torch types

Torch type	EIA code
Airco	62
Generic	47
Harris model 80	48
Harris model 98	49
IHT	63
Koike 100L	59
Koike 200L	60
Koike 500L	61
Meco	64
Messer	65
Oxyweld	66
Smith	67
Victor MT 200	50
Victor MT 300	51

### V code

V code	Description
V566	Tip type for oxyfuel cut charts

## New tip types

Tip type	EIA code
Standard	1
Divergent	2
Heavy preheat	3
Divergent Hvy PH	4

- The Phoenix help is now available in the following languages: Chinese (Simplified), Chinese (Traditional), French (Canadian), German, Italian, Korean, Polish, Portuguese, Russian, Slovenian, Spanish, and Turkish.

When Phoenix is running in a supported language, German for example, and the Help button is chosen, the help page is presented in German. If the Phoenix help is not available for a language, the English version is displayed. A new self-extracting Help.exe file is now available for updating a CNC with this language support.

- XPR or HPR plasma power supply ready status is now shown on the main screen. PS - Ready is shown for a single-torch table or PS# - Ready for a multi-torch table.
  - The ready message will be shown if:
    - The tool's station is in the Manual or Program position
    - The cut mode is Plasma
    - The tool (XPR or HPR EtherCAT) is in the Wait for Start or Initial Checks state
    - The part program is paused or has not started and there are no errors

The message only shows before cutting starts. When a cut starts the individual cutting states and error messages are shown.

## Phoenix resolutions

- An issue was resolved where Phoenix was getting an incorrect F-code for the G59 V564 entry. The decimal value 0.040 inches (19 GA, 1 mm) was mistakenly taking the value for 0.024 inch, which caused an F8 value, instead of the correct F12 value.
- Resolved an issue where the Nozzle Contact Sense 1 input was not working when doing an IHS with water injection or underwater processes. A change was made in Phoenix 10.3.0 to ignore all Nozzle Contact Sense inputs, both fixed function and general purpose, when using an XPR water injection or underwater process. The code has been changed to now only ignore the XPR fixed function input and XPR Nozzle Contact Sense when XPR water injection or underwater processes are used.
- Resolved an issue that caused the XPR torch to momentarily fire in the air. The issue occurred when Preflow During IHS was on and the Stop button was pressed when an Offset IHS offset was being removed. The torch will no longer fire if the machine is paused during the Offset IHS canceling traverse motion.
- Resolved invalid process dialog or status messages for the XPR that occurred in the following cases:
  - During the second cut in a part when Offset IHS was used. To resolve the issue XPR process updates are now sent at the beginning of the IHS, which is part of the Offset IHS sequence.
  - When a user sent a process from the Cut Chart when the XPR was not ready (for example, when the XPR was purging).
  - When a user paused a program and made a change on the Process screen when Offset IHS is on.
  - After a process was sent when the XPR was not ready, the error dialog would continue to show after subsequent program starts because the error did not clear in Phoenix and Phoenix did not send another process update.
  - When a marking gas of None was selected in the cut chart and the user tried to run a marking program.
- Resolved an issue where the Station Configuration screen closed unexpectedly when using non-English languages.
- Resolved an issue that caused Phoenix to close unexpectedly when the Help window was minimized. The Help window can no longer be Minimized.
- Resolved an issue where analog input values for the Beckhoff EL3008, 8-channel analog input were not properly read by Phoenix. The value shown on the diagnostic screen or in the watch window was at the + or - 10v limit.
- Resolved an issue where nozzle contact during IHS was disabled when switching from marking to cutting while cutting with an HPR.
- M65 Auto Reload of sequentially numbered parts now works with EDGE Connect. There are no setup parameters associated with this because it has been permanently enabled. Hypertherm recommends that you use M79Tx Go to Home Commands to re-position the table between each M65 Sheet/Nest that is being auto loaded.

- Resolved an issue where the user could not exit the Manual Options screen. The Manual Options screen is now exited properly under all conditions and regardless of which dialog was active previous to entering the Manual Options screen. Torch spacing on the Manual Options screen is no longer allowed when a part program is active or paused.
- Resolved an issue that caused the Test Lifter button to stay depressed after motion was interrupted on the main screen with the Stop button on the hardware operator panel or the Soft Op Con. The Test Lifter button works correctly on the process screen.
- Resolved an issue with the Cross w/ Circular Hole and Concave Inside Corners simple shapes that caused duplicate G41 and M07 EIA commands prior to cutting the hole. The duplicate EIA commands have been removed. This issue exists in all prior versions of Phoenix.
- Resolved an issue that caused the torch to lower into the plate after a torch collision occurred while cutting. When the user acknowledged the torch collision dialog the torch lowered toward the plate. The issue also occurred when an emergency stop or drive disabled command occurred while cutting.
- All HPR Auto Gas fields are now always displayed in the HPR Diagnostics screen. The user will see the pressure value fields for Cut Gas 1, Cut Gas 2, Mixed Gas 1, and Mixed Gas 2, even if there is no pressure on these channels or the gas channels do not exist (manual gas console).
- Resolved an issue where the speed pot did not work properly after the slide control on the Soft Op Con was used. The issue was only seen when an analog signal was used for the speed pot.

## **XPR**

- Resolved an issue where the torch fired in the air under the following condition: With XPR fixed function I/O, if water remains in the torch after a water injection process, the THC's IHS will be immediately satisfied at the next cut or mark. The XPR firmware was updated to correct the issue. The XPR now pulses gas on and off 7 times (for 14 seconds) when switching from a wet to dry process to make sure the ohmic contact is not shorted out by the water remaining in the torch.

## **ProNest**

- The ProNest CNC Package was updated from 1.1.4 to 1.1.9 and includes the latest XPR cut charts (Revision J).

Summary of the Revision J cut chart changes:

- Fixes:
  - Corrections to arc voltage data for thick, non-ferrous processes
  - Corrections to pierce height and transfer height data
  - Correction to a process name and a shield gas name that did not match

- Pierce times corrected for edge start on 300A MS processes
- Corrections to kerf width data
- Metric value corrected for 170A Air/Air process
- New capabilities:
  - True Hole processes added – More thicknesses covered within the existing ranges
  - 3-1/8 inch mild steel added to the 300A process
  - 12 mm stainless steel added to 80A N<sub>2</sub>/H<sub>2</sub>O process
  - Version 1.1.8 of ProNest CNC Installer created

## Software versions



You must be at image 27 or higher to perform this update

The versions for the software and firmware in the current update are found in different locations on the EDGE Connect CNC. The table below is grouped by the location where the version information is shown.

- To see version information for Windows, Phoenix, Real-Time OS, Field Bus Master, Real-Time Module, PLC engine, System Image, and OpCon APIs:  
choose **Main > Setups > Diagnostics > Control Information**.
- Version information for cut charts is displayed on the cut chart screen in Phoenix
- To see version information for other items Go to **Control Panel > Programs and Features**



If you need to update the CNC or have any other questions about software versions, contact your regional Product Application Engineer (PAE).

### Shown on the Diagnostics screen

Item	Versions / Revisions
Windows	10.00.10240
Phoenix	10.4.0
Real-Time OS	6.1.16110.1
Field Bus Master	1.5.59902.0
Real-Time Module	10.4.0.1469
PLC engine	1.1.0.0
Phoenix Op Con API	2.0.0.0
SoftOpCon	2.0.0.406
MinReqOpCon	2.0.0.406
Hardware operator console	1.0

**Shown on the cut chart screen**

Item	Versions / Revisions
XPR	J
HPRXD	AA
HPR	80003Ea and 80003Eb
Oxyfuel	F - Extended format A

**Shown on the Windows Programs and Features screen**

ProNest CNC	Versions / Revisions
Client	1.1.4.209
ProNest CNC package	1.1.9
Nesting software	12.0.4.6250
<b>KPA</b>	<b>Versions / Revisions</b>
EtherCAT Studio	1.12.210.0
License utilities	2.1.104.0
<b>PLC Connect</b>	<b>Versions / Revisions</b>
MULTIPROG	1.2
<b>Plasma power supplies</b>	<b>Versions / Revisions</b>
XPR main control	E - 458
XPR torch connect	E - 175
XPR gas connect	E - 122
XPR choppers	E - 169
XPR WiFi tool	21493
<b>Drives</b>	<b>Versions / Revisions</b>
Bosch IndraDrive C and Cs	19V08, 18V10, 18V20
Delta ASD A2	1.643 or higher
Kollmorgen AKD	1.15
Mitsubishi MR-J4	Drive: BCD-B46W500 B1 Communication module: 1.10.01
Panasonic MINAS-A5B	1.01
Yaskawa Sigma-5	5.0, 5.04, 6.00
Yaskawa Sigma-7	0023 2016.10

# ***Version 10.3.1***

## **Release notes**

---



Version 10.3.1 is an unplanned interim release to address reported field issues and to provide additional safety improvements. It is recommended that all customers update to 10.3.1 or higher software.

## **ProNest CNC**

### **Version information for this release of ProNest CNC software**

- ProNest CNC Nesting Software 12.0.4.6250
- ProNest CNC Client 1.1.4.209
- ProNest CNC Package 1.1.4.0



To view the version information for ProNest CNC software, right-click the Windows Start button, and then click Programs and Features. Click Publisher to sort the items. The Hypertherm items for ProNest CNC are grouped near the top of the list.

- Resolved an issue with an incorrect feed rate being applied to True Hole parts from ProNest CNC that was affecting XPR™ True Hole quality.
- Enabling and disabling height control using M50/M51 part programs codes was not being applied on XPR non-True Hole interior features, affecting cut quality. This has been corrected.
- Incorrect speeds used for lead-out techniques with XPR thick stainless and aluminum processes has been resolved.

## Phoenix resolutions

- Resolved an issue where the fault ramp time was not recognized for the Independent Drive Enable and Series Drive Enable wiring settings. The front panel E-stop input now recognizes fault ramp-down times. The drive enable is now maintained for the programmed Fault Ramp Time instead of turning off immediately.



If your drive supports Safe Torque Off and you are using it for Emergency Stop, Hardware Overtravels, or other Machine Fault Conditions, the Safe Torque Off will then override motor deceleration instead of any programmed Fault Ramp times.

- Resolved an issue where the Hardware Op Con and Soft Op Con Stop keys only stopped motion momentarily with a stuck joystick input if Stop was pressed and released. The Hardware Op Con button will completely stop motion if pressed and held for at least 1 second. This issue exists in all previous versions of Phoenix software. Software was changed so both the Hardware Op Con and Soft Op Con Stop keys completely stop motion generated by a stuck joystick input when pressed and released or pressed and held. Motion cannot be restarted until the input that generated the motion turns off.
- Resolved an issue where the Stop button and Safety Mat input did not stop motion during the Test Lifter function from the Process screen. The Stop button and Safety Mat input can now be used to stop the Test Lifter function from the Process screen.
- Resolved an issue that prevented the selection of an analog input for the Sensor THC on the Machine setup screen when a MAXPRO200 was configured on Plasma 1 on the Station Configuration screen.
- The ResetTHCLog password now supports logging both THC Command position and Actual Position. Previously the THC log file only contained Command Position. The addition of Actual Position to the THC log file adds additional diagnostic capabilities when troubleshooting Sensor THC issues.
- Resolved an issue where coolant would flow during bevel calibration with an XPR plasma power supply. Bevel calibration with XPR requires that you turn off the main power switch (at the wall), turn the main power switch on again, and no process has been sent to the XPR. Bevel calibration is typically performed during machine setup only.
- Resolved an issue where the Hardware Op Con speed pots did not work until the Soft Op Con speed controls were used first.
- A Ready to Move message is now displayed when you attempt manual motion using the jog keys in the Soft Op Con.
- Eliminated an issue where speed pots were briefly jumping from 0 speed to maximum speed when the speed pot was set close to the 0 speed set point.
- Resolved an issue where the Invalid Process message was shown when you tried to start a Cut, Rip Cut, or Rip Mark when an XPR was not in the Wait for Start state or the Initial Checks state. The message has been updated to XPR Not Ready.



- Resolved an issue where quickly switching from Rip Cut to Rip Mark caused an XPR to cut the plate instead of marking the plate.
- Resolved an issue where an HPR plasma supply fired an arc in the air under certain specific conditions when switching from Rip Cut IHS to Rip Mark IHS before the IHS was completed.

## Software versions

The following table shows the software versions before and after this update, for reference purposes.



This table also includes the software versions for new EDGE Connect CNCs shipped with Phoenix version 10.3.1.

To check which software versions the CNC has, choose **Main > Setups > Diagnostics > Control Information**.



If you need to update the CNC or have any other questions about software versions, contact your regional Product Application Engineer (PAE).

Software	Before update	After update	New CNCs
Windows	10.00.10240	10.00.10240	10.00.10240
Phoenix	10.3.0	10.3.1	10.3.1
Real-Time OS	6.1.16110.1	6.1.16110.1	6.1.16110.1
Field Bus Master	1.5.59902.0	1.5.59902.0	1.5.59902.0
Real-Time Module	10.3.0	10.3.1	10.3.1
PLC Engine	1.0.0.0	1.0.0.0	1.0.0.0
System Image	30	32	32
Phoenix OpCon API	2.0.0.0	2.0.0.0	2.0.0.0
Active OpCon APIs	2.0.0.0	2.0.0.0	2.0.0.0



# Version 10.3.0

## Versionshinweise

---

### Neue Merkmale

- Die neue Plasmaschneidanlage XPR300 wird jetzt unterstützt. Genauere Informationen hierzu finden Sie im Anhang des EDGE Connect-Handbuchs 809900 (EDGE Connect-Handbuch 809340). Einige Unterschiede im Vergleich zu einer HPR:

- Die Markierung benötigt nicht mehr ein separates Tool bzw. einen separaten Prozess; jeder Datensatz umfasst Schneiden, Markierung und True Hole (falls zutreffend).

Dementsprechend gilt:

- **M36 T3** (Ausw. Markierungsprozess 1) and **M36 T4** (Ausw. Markierungsprozess 2) werden nicht mehr verwendet; **M36 T1** (Ausw. Plasmaprozess 1) und **M36 T2** (Ausw. Plasmaprozess 2) werden sowohl für Schneiden als auch für Markierung verwendet.
- **M09** (Mark. 1 Ein), **M10** (Mark. 1 Aus), **M13** (Mark. 2 Ein) und **M14** (Mark. 2 Aus) werden nicht mehr verwendet; **M07** (Schn. ein) und **M08** (Sch. aus) werden sowohl für Schneiden als auch für Markierung verwendet.
- Sie können die Markierungsgeschwindigkeit in der Schneidtable in ProNest jetzt mit einem Fwert überschreiben.
- Überschreibungen, True Hole und Markierung werden mit Codes auf der M07-Linie im Teileprogramm angezeigt.
- Alle Prozess- und Schneidtabellenparameter werden in der Zeile G59 V509/V519 im Teileprogramm angezeigt. Beispiel: G59 V509 F11189. Dieser Befehl teilt der CNC mit, welcher Datensatz in der Datenbank der Prozess- und Schneidtabellenparameter für dieses Teileprogramm verwendet werden soll. Der Datensatz enthält alle Parameter,

die Phoenix und die XPR300 für die Ausführung des Teileprogramms brauchen. Der Datensatz umfasst die entsprechenden XPR-Prozess-IDs für Schneiden, Markierung und True Hole (wenn zutreffend), die Phoenix bei der Ausführung des Teileprogramms an die XPR300 sendet.

## Verbesserungen

- Das Installationsprogramm der EDGE Connect Suite installiert jetzt die ProNest CNC.
- Laufwerke vom Typ Yaskawa Sigma 7 werden jetzt unterstützt. Siehe FSB 809910 für Einzelheiten.

## Phoenix-Fehlerbehebungen

- Durch ein Update der HPR-Firmware (3.19) wurde ein Problem behoben, bei dem der Brenner nicht zündete, wenn mit Ar bei 25 bis 35 Ampere markiert werden sollte. Die Gasarten Ar/Luft wurden von der HPR-Firmware auf Ar/Ar\_Luft gesetzt.
- Problem bei der Sensor THC IHS-Hartplattenerkennung behoben. Die Eingaben des Düsenkontaktsensors wurden während der IHS ignoriert, wenn die HPR beim Kontakt des Brenners mit der Platte gespült wurde.
- Die HT4400 wurde in die Liste der Plasmaquellen aufgenommen, bei denen die Sensor THC eine Einfahrverzögerung von 0,5 Sekunden am Ende jedes Schnitts verwendet, um zu verhindern, dass der Brenner während des Herunterfahrens am Ende jedes Schnitts einfährt.
- Die EDGE Connect CNC hat bei der Achsenbeschleunigung fälschlicherweise den Fehler „Berechneter Fehler hat Servo-Fehlertoleranz um das Zweifache überschritten“ angezeigt. Die Fehlerbedingung wurde herausgenommen, denn sie überschneidet sich mit der Fehler-/Ausfallfunktionalität des Slave-Geräts und wurde nicht benötigt.
- Ein Problem, durch das HPR-Fehler nur im Beobachtungsfenster angezeigt wurden, wenn der Brenner abgesenkt wurde, wurde behoben.
- Ein Problem, durch das Fehler, die einen nicht behebbaren EtherCAT-Netzwerkfehler ausgelöst haben, nicht zum Zurücksetzen des Home-Flags der Sensor THC führten, wenn die THC bereits zurückgestellt war, wurde behoben. Wenn das Netzwerk neu gestartet wurde, schien die Brennerposition für Phoenix ganz oben am Schlitten zu sein, so dass der Brenner nicht höhergestellt werden konnte. Der Bediener wurde nicht daran gehindert, einen Schnitt zu beginnen, so dass der Brenner auf die falsche IHS-Starthöhe abgesenkt werden konnte, wodurch der Brenner mit hoher Geschwindigkeit auf die Platte prallen konnte, wenn sich der Brenner beim Auftreten des Netzwerkfehlers nah genug an der Platte befand.

## Softwareversionen

In der folgenden Tabelle sind die Softwareversionen vor und nach diesem Update zum Nachschlagen aufgeführt.



In dieser Tabelle sind auch die Softwareversionen für neue EDGE Connect CNCs enthalten, die mit der Phoenix-Version 10.3.0 ausgeliefert werden.

Um die Softwareversion der CNC zu ermitteln, wählen Sie **Haupt > Konfiguration > Diagnostik > Steuerungs-Info**.



Wenn Sie Ihre CNC aktualisieren müssen oder irgendwelche sonstigen Fragen zu Softwareversionen haben, wenden Sie sich an Ihren regionalen Produkt-Anwendungstechniker (PAE).

Software	Vor dem Update	Nach dem Update	Neue CNCs
Windows	10.00.10240	10.00.10240	10.00.10240
Phoenix	10.2.0	10.3.0	10.3.0
Echtzeit-OS	6.1.16110.1	6.1.16110.1	6.1.16110.1
Feldbus-Master	1.5.59902.0	1.5.59902.0	1.5.59902.0
Echtzeitmodul	10.2.0	10.3.0	10.3.0
PLC Engine	1.0.0.0	1.0.0.0	1.0.0.0
Systemabbild	30	31	31
Phoenix OpCon-API	2.0.0.0	2.0.0.0	2.0.0.0
Aktive OpCon-APIs	2.0.0.0	2.0.0.0	2.0.0.0




# Version 10.2.0

## Versionshinweise

---

### Merkmale

- Support für bestimmte Mitsubishi-Laufwerke der Serie MR-J4 hinzugefügt. Zu den unterstützten Typen siehe Anwendungshinweis 809750.
  -  Normale Encoder-Auflösung, Serie J3, Mitsubishi-Motoren sind mit der Software Phoenix 10.2 erforderlich.
- Support für bestimmte Panasonic-Laufwerke der Serie Minas-A5B hinzugefügt. Drehmomentsteuerung wird derzeit nicht unterstützt. Zu den unterstützten Typen siehe Anwendungshinweis 809760.
- Support für bestimmte Delta-Laufwerke der Serie ASDA-A2 hinzugefügt. Zu den unterstützten Typen siehe Anwendungshinweis 809770.

### Verbesserungen

- Die Versionsnummer der Phoenix-Software wurde vereinfacht. Zusätzliche Nullen als Platzhalter entfallen. So wird die aktuelle Version beispielsweise als 10.2.0 dargestellt, anstelle von 10.02.00. Die Änderung soll helfen, Verwechslungen zwischen Versionen zu vermeiden.
- Unterstützung für HPRXD 80 A und 400 A SilverPlus auf unlegiertem Stahl hinzugefügt. Bild und Teile-Nummer der Elektrode wurden auf dem Bildschirm „Verschleißteile wechseln“ hinzugefügt, und Prozessparameter wurden in die Schneidtabellen-Datenbank aufgenommen.

- Die Funktion „Handbuch aktualisieren“ unterstützt jetzt auch die Powermax45 XP. Die Handbücher für die Powermax45 XP können mit dem Passwort „UPDATEMANUALS“ oder der Schaltfläche „Handb.aktualis“ auf dem Bildschirm „Spezial-Konfig.“ importiert werden.



Die Unterstützung des Schneidprozesses der Powermax45 XP ist nicht Teil der Version 10.2.

- Das True-Hole-Konversionstool wird jetzt vom Installationsprogramm der Phoenix Suite aktualisiert.
- Das True-Hole-Konversionstool wurde in mehreren Punkten verbessert:
  - Der Phoenix-Parameter „EIA I- und J-Codes Absol“ wird jetzt unterstützt und dementsprechend immer von Phoenix an das True-Hole-Konversionsutility übergeben. Dadurch bleiben die beiden Softwarepakete synchron (bei inkrementellem oder absolutem EIA IJ), wenn das EIA-Programm interpretiert oder ausgegeben wird.
  - Die True-Hole-Konversion akzeptiert jetzt Teile mit den optionalen Codes I oder J. Wenn der Code I oder J gleich 0 ist, wird er nicht mehr benötigt.
  - Die True-Hole-Konversion generiert jetzt ordnungsgemäß True-Hole-Ausgaben für Löcher, die in einem Teileprogramm später gebohrt werden, selbst wenn der Durchmesser des ersten Lochs oder der ersten Löcher zu groß sind, um in True-Hole-Ausgaben konvertiert zu werden.

## Phoenix-Fehlerbehebungen

- Bedienkonsolen, die NICHT mit dem Nuget-Paket erstellt wurden, werden nicht funktionieren, wenn Sie die von Ihnen aktuell verwendete Sprache auf Phoenix 10.2 updaten. Das liegt daran, dass das Update zwei DLL-Dateien (InternalComms.dll und Models.dll) in einen Ordner namens ObsoletePhoenixOpConAPI im Verzeichnis C:\Phoenix verschiebt. Es gibt zwei Möglichkeiten, dies zu beheben:
  - Verschieben Sie die beiden DLL-Dateien aus dem Ordner ObsoletePhoenixOpConAPI in das Verzeichnis C:\Phoenix. Damit ist die individuelle Bedienkonsole einsetzbar, aber Sie können dann NICHT die standardmäßige Phoenix-Bedienkonsole verwenden, die mit 10.2.0 mitgeliefert wird.
  - Aktualisieren Sie Ihre individuelle Bedienkonsole auf das neue Nuget-Paket. Diese Lösung ist die beste und wird von Hypertherm empfohlen. So funktioniert die individuelle Bedienkonsole und auch die neue standardmäßige Bedienkonsole.
- Der Schneidprozess hat bisher fälschlicherweise vom Markieren auf Schneiden umgeschaltet, wenn das Programm vor dem anfänglichen Schnittsensor mehrmals angehalten wurde. Dieser Fehler wurde behoben.
- Der Prozess-Updatezähler wird jetzt auf 0 zurückgesetzt, wenn ein Teileprogramm angehalten wird, bevor das Plasma-System einen Lichtbogen erzeugt. Dadurch wird verhindert, dass das Programm anhält und anzeigt, dass ein neuer Versuch eines Prozessupdates erforderlich ist.



- Ein Fehler bei HPR-Systemen wurde behoben, der auftrat, wenn bei Argon vom Schneiden auf Markierung umgeschaltet wurde und der Markierungsstrom zwischen 25 und 35 Ampere lag. Der Prozess wurde nicht korrekt aktualisiert und das Programm hielt an. Wenn das Programm neu gestartet wurde, aktualisierte Phoenix die HPR mit dem Schneidprozess, nicht mit dem Markierungsprozess.
- Die Softwareaktualisierungsoperation installiert übersetzte Sprachen jetzt korrekt.
- Um zu verhindern, dass Phoenix hängen bleibt, wenn Sie im Ladebildschirm bei eingeschalteter Vorschau schnell durch die Teileprogramme blättern, verhindert Phoenix nun, dass ein neues Teileprogramm geladen wird, während das vorhergehende Teileprogramm noch gezeichnet wird.
- Phoenix bleibt nun nicht mehr mit deaktivierten OK- und Abbrechen-Softkeys im Manuell-Bildschirm, wenn bei aktivem Cut Pro oder Align Wizard der Not-Aus gedrückt wird.
- Bei unbeabsichtigter Drehzahl-Poti-Aktivität oder übermäßigem elektrischem Rauschen werden Phoenix-Ausnahmefehler jetzt unterbunden.

## **ProNest CNC-Fehlerbehebungen**

- Je nach Phoenix-Maschinen-/Achsenausrichtung kann es sein, dass die ProNest CNC ein Teil mit dem Schneidweg in falscher Richtung erstellt, wenn in Phoenix einfache Formen verwendet werden. Einige Achsenausrichtungen (+Y -X, wenn X die Schiene ist) konnten bei Verwendung einfacher Formen zu falschen Ausgaben von ProNest CNC führen. DXF-Teile waren nicht betroffen. Jetzt führen alle Achsenausrichtungen zur selben Eingabe in ProNest CNC für einfache Formen, so dass bei allen Ausrichtungen die Ausgabe einer einfachen Form mit ProNest CNC korrekt ist.
- Ein Fehler in den Schneidprozessdaten von ProNest CNC wurde korrigiert, so dass jetzt der korrekte Vorschub bei der Einfahrt für True Hole angewendet wird.

## Softwareversionen

In der folgenden Tabelle sind die Softwareversionen vor und nach diesem Update zum Nachschlagen aufgeführt.



In dieser Tabelle sind auch die Softwareversionen für neue EDGE Connect CNCs enthalten, die mit der Phoenix-Version 10.2.0 ausgeliefert werden.

Um die Softwareversion der CNC zu ermitteln, wählen Sie **Haupt > Konfiguration > Diagnostik > Steuerungs-Info**.



Wenn Sie Ihre CNC aktualisieren müssen oder irgendwelche sonstigen Fragen zu Softwareversionen haben, wenden Sie sich an Ihren regionalen Produkt-Anwendungstechniker (PAE).

Software	Vor dem Update**	Nach dem Update	Neue CNCs
Windows	10.00.10240	10.00.10240	10.00.10240
Phoenix*	10.01.0	10.2.0	10.2.0
Echtzeit-OS	6.1.16110.1	6.1.16110.1	6.1.16110.1
Feldbus-Master	1.5.59902.0	1.5.59902.0	1.5.59902.0
Echtzeitmodul*	10.01.0	10.2.0	10.2.0
PLC Engine	1.0.0.0	1.0.0.0	1.0.0.0
Systemabbild*	27 oder 28	27 oder 28	30
Phoenix OpCon-API*	2.0.0.0	2.0.0.0	2.0.0.0
Aktive OpCon-APIs*	2.0.0.0	2.0.0.0	2.0.0.0

\* Zeigt an, dass die Softwareversion mit diesem Update geändert wurde.

# Version 10.01.0

## Versionshinweise

---

### Merkmale

- Support für die Beckhoff EL1809 16-Kanal-Digitaleingangs- und Beckhoff EL2809 16-Kanal-Digitalausgangs-EtherCAT-E/A- Module hinzugefügt. Für weitere Informationen dazu siehe den Anwendungshinweis (809660) zu *EtherCAT®-Laufwerken und E/A-Modulen, die von EDGE® Connect/T/TC CNCs* unterstützt werden.
- Phoenix-Oszilloskop verbessert. Datenplayback unterstützt jetzt mehrere Einstellungen für unterschiedliche Vorspulgeschwindigkeiten.
- Wenn eine Schneidmaschine korrekt zurückgestellt wurde, werden die X- und Y-Softwarebewegungsgrenzen jetzt vor der Ausführung der Funktion „Vorschubabstand“ auf dem manuellen Bildschirm aktiviert. Der CNC-Bediener wird jetzt vor dem Einsetzen der Bewegung gewarnt.

### Verbesserungen

- Das Installationsprogramm der Phoenix Suite kann die Dateien der EtherCAT-Slave-Bibliothek jetzt nach Bedarf automatisch aktualisieren.
- Gelegentliche ruckartige Bewegungen beim Maschinenvorschub, die durch EtherCAT-Netzwerkverzögerungen im Zusammenwirken mit RTOS-Threadprioritäten und Phoenix-Timing ausgelöst wurden, wurden eliminiert.
  - RTOS-Threadprioritäten und PLC-E/A-EtherCAT-Netzwerkupdates optimiert, um einheitliche und zeitgerechte Bewegung zu gewährleisten.
  - Fehler und Fehlermeldung für alle versäumten zyklischen EtherCAT-Paketupdates definiert.

- Abwärtskompatibilität mit früheren Versionen der Phoenix OpCon-API hergestellt.
- Eine Bestätigungsmeldung (Funktionen erfolgreich aktualisiert) zeigt jetzt an, wenn neu gekaufte Software-Features mit dem Kennwort UPDATEFEATURES aktiviert werden.
- Zusätzliche Prüfungen für die Rohr/Drehachse eingebaut. Drehungsbezogene F-Codes des Teileprogramms werden jetzt ignoriert, wenn die Einstellung für die Drehgeschwindigkeit auf dem Bildschirm „Geschwindigkeiten“ fälschlicherweise auf Null (0) gestellt ist. Die Drehbewegung wird jetzt blockiert, bis der Höchstwert für die Geschwindigkeit auf einen korrekten Wert ungleich Null gesetzt wird.
- Wenn Sie die Schneidspitze im Bildschirm der Autogen-Schneidtablette bearbeiten, wird jetzt die alphanumerische Tastatur anstelle des Ziffernblocks auf dem Bildschirm benutzt, so dass Sie Buchstaben und Ziffern eingeben können.
- Negative Werte für Analogausgänge werden jetzt unterstützt.
- Ein Bereich von  $\pm 10$  VDC wird jetzt für die Analogeingangswerte unterstützt, anstelle eines Bereichs von 0–10 VDC. Hierdurch werden EtherCAT-Laufwerke und E/A-Module mit dieser Fähigkeit unterstützt.
- Gelegentliche ruckartige Maschinenvorschübe beim Hochfahren des EtherCAT-Netzwerks eliminiert. Diese ruckartigen Bewegungen wurden ausgelöst, weil Phoenix die Laufwerke aktiviert hatte, bevor das Netzwerk einsatzbereit war, und dadurch falsche Positionsinformationen von den Laufwerken gemeldet werden konnten.
- Die Signale „HPR-Prozess bereit“ und „HPR-Remote Ein“ sind jetzt in den E/A-Beobachtungs- und Oszilloskop-Fenstern verfügbar, um die Diagnostik zu verbessern.
- Die Beschriftungen der Phoenix OpCon-API auf dem Steuerungs-Infobildschirm wurden klarer gestaltet. Die Beschriftung „Unterstützte API“ lautet jetzt „Phoenix OpCon-API“ und die „Client-API“ heißt jetzt „Aktive OpCon-APIs“.

## Fehlerbehebungen

- Phoenix ignoriert jetzt einen nicht zutreffenden Slave-Fehler der Geräte-Bedienerkonsole, der während des Hochfahrens des EtherCAT-Netzwerks auftreten konnte.
- Ein auf eine Geschwindigkeit Null gestelltes Drehzahl-Poti wird jetzt korrekt behandelt, wenn „Teil wiederaufnehmen“ während „Not-Aus aktiv“ aktiv ist, wenn ein Maschinenfehler auftritt oder wenn „Teil wiederaufnehmen“ nicht aktiviert ist.
- Die Statusanzeige der Software-Bedienkonsole mit den Tasten für Deaktivierung, Man. Modus und Programm-Modus der Software-Bedienkonsole synchronisiert. (Grün zeigt aktivierten Status an. Rot zeigt deaktivierten Status an.)
- Falsche Zurück-zum-Start-Bewegung korrigiert, wenn der Not-Aus genutzt wird, und wenn Teileprogramm-Wiederaufnahme/Stromausfall bei Ausführung eines Teileprogramms genutzt wird.
- Zuverlässigkeit des Ein- und Ausschaltens des manuellen Modus der Software-Bedienkonsole verbessert.
- Prüfungen auf Vorhandensein des Pausenbildschirms eingebaut, um mögliche Phoenix-Ausnahmefehler beim Speichern der Stromausfall-Teileprogrammdateien zu eliminieren.

- Der Lochstechzähler bleibt jetzt nicht mehr im Watch Window sichtbar, wenn andere Elemente im gleichen unteren Bereich des Watch Window angezeigt werden.
- Unterstützung für Positionsfehler von Yaskawa-Laufwerken eingebaut.



Wenn die Schneidmaschine über Yaskawa-EtherCAT-Laufwerke verfügt, rekonfigurieren Sie das EtherCAT-Netzwerk nach der Installation dieses Updates. D. h., scannen Sie das EtherCAT-Netzwerk neu und erstellen Sie eine neue Datei Phoenix.xml. Siehe das Kapitel *Konfiguration des EtherCAT-Netzwerks* im *EDGE Connect Installations- und Einrichtungshandbuch (809340)* für Hilfestellung hierzu.

- Die THC-Lichtbogen-Spannung wird jetzt bei Plasmasystemen korrekt mit diskreten Analogeingängen erfasst.
- Die Fehlerbehandlung wurde insgesamt verbessert und ungültige EtherCAT-Feldbus-Fehler wurden entfernt.
- Die Ausgänge „Zündung 1 halten“ und Watch Window werden im Beobachtungsfenster jetzt korrekt aktualisiert.
- Wenn von einem Beobachtungsfenster Watch Window genutzt wird (bzw. die Pfeiltasten an einer angeschlossenen Tastatur), wenn eine Pfeiltaste in der Software-Bedienkonsole verwendet wird, wird „Latched Jogging“ abgeschaltet.

## Softwareversionen

In der folgenden Tabelle sind die Softwareversionen vor und nach diesem Update zum Nachschlagen aufgeführt.



In dieser Tabelle sind auch die Softwareversionen für neue EDGE Connect CNCs enthalten, die mit der Phoenix-Version 10.01.0 ausgeliefert werden.

Um die Softwareversion der CNC zu ermitteln, wählen Sie **Haupt > Konfiguration > Diagnostik > Steuerungs-Info**.



Wenn Sie Ihre CNC aktualisieren müssen oder irgendwelche sonstigen Fragen zu Softwareversionen haben, wenden Sie sich an Ihren regionalen Produkt-Anwendungstechniker (PAE).

Software	Vor dem Update	Nach dem Update	Neue CNCs
Windows	10.00.10240	10.00.10240	10.00.10240
Phoenix*	10.00.0	10.01.0	10.01.0
Echtzeit-OS	6.1.16110.1	6.1.16110.1	6.1.16110.1
Feldbus-Master	1.5.59902.0	1.5.59902.0	1.5.59902.0
Echtzeitmodul*	10.0.0	10.01.0	10.01.0
PLC Engine	1.0.0.0	1.0.0.0	1.0.0.0
Systemabbild*	27	27	28
Phoenix OpCon-API*	1.x.x.x	2.0.0.0	2.0.0.0
Aktive OpCon-APIs*	1.1.0.11	2.0.0.0	2.0.0.0

\* Zeigt an, dass die Softwareversion mit diesem Update geändert wurde. Die anderen Versionen sind unverändert.

## Version 10.01.0 installieren

---

### Bevor Sie beginnen

Gehen Sie folgendermaßen vor:

- **Vergewissern Sie sich, dass die CNC das Image 27 und die Phoenix-Version 10.00.0 oder höher hat.** Installieren Sie dieses Update nicht, wenn die CNC nicht diese Softwareversionen hat.
  - Um die Softwareversionen der CNC zu ermitteln, wählen Sie **Haupt > Konfiguration > Diagnostik > Steuerungs-Info**. Unter **Softwareversionen** sehen Sie die Kästen **Phoenix** und **Systemabbild**. Wenn Sie Ihr System auf Image 27 und Phoenix Version 10.00.0 oder höher aktualisieren müssen, wenden Sie sich an Ihren regionalen Produkt-Anwendungstechniker (PAE).
- **Sicherung der CNC-Systemdateien:** Wählen Sie **Haupt > Dateien > Auf Disk speich. > Syst.-Dat. auf Disk speich.**
- Wenn die CNC eine individuelle Software-Bedienerkonsole (Soft Op Con) hat, sichern Sie die individuelle Software-Bedienkonsolen-Anwendung und die zugehörige Datei **steps.json**. Wenn bei der Erstellung der individuellen Software-Bedienkonsole kein eindeutiger Name benutzt wurde, kann die individuelle Software-Bedienkonsole bei der Installation dieses Updates durch die standardmäßige Hypertherm-Software-Bedienkonsole ersetzt werden.


Bitte beachten Sie Folgendes:

- Dies ist **nur** ein Interims-Update der Phoenix-Software. Dieses Update enthält keine Updates von Schneidtabellen, dem Phoenix-Hilfesystem oder der technischen Dokumentation.
- Wenn Sie dieses Update installieren, startet Phoenix automatisch neu.
- Wenn die Schneidmaschine über Yaskawa-EtherCAT-Laufwerke verfügt, rekonfigurieren Sie das EtherCAT-Netzwerk nach der Installation dieses Updates. D. h., scannen Sie das EtherCAT-Netzwerk neu und erstellen Sie eine neue Datei Phoenix.xml. Siehe das Kapitel *Konfiguration des EtherCAT-Netzwerks* im *EDGE Connect Installations- und Einrichtungshandbuch* (809340) für Hilfestellung hierzu.

### Download und Installation des Updates

1. Wählen Sie auf der Website [www.hypertherm.com](http://www.hypertherm.com) **Kundensupport > Phoenix-Softwareupdates**.
2. Laden Sie die Datei **PhoenixSuiteInstaller.exe** für die entsprechende Sprache in das Stammverzeichnis eines USB-Speichersticks.
3. Stecken Sie den USB-Speicherstick in eine USB-Buchse an der CNC.
4. Wählen Sie auf dem **Hauptbildschirm Konfig. > Passwort**.
5. Geben Sie **UPDATESOFTWARE** (in einem Wort) ein und wählen Sie dann **OK**.

6. Wählen Sie bei Aufforderung wieder **OK**.




7. Warten Sie, bis das Update installiert wurde.



Mehrere Fenster öffnen und schließen sich dabei automatisch. Das ist normal.

8. Die CNC startet sich nach der Installation des Updates automatisch neu, Phoenix wird geöffnet und beginnt das EtherCAT-Netzwerk zu starten. Es erscheint folgende Meldung.




9. Wählen Sie **Abbrechen**, um das Hochfahren des Netzwerks zu stoppen.
10. Klicken Sie irgendwo auf den Phoenix-Hauptbildschirm und drücken Sie dann Alt+F4, um Phoenix zu verlassen.



**Wenn die CNC eine individuelle Software-Bedienkonsole hatte:** Wenn die CNC eine individuelle Software-Bedienkonsole (Soft Op Con) hatte, deren individuelle Software-Bedienkonsolen-Anwendung und die zugehörige Datei **steps.json** Sie zuvor gesichert hatten, kopieren Sie diese Dateien zurück in den Ordner **C:\Phoenix** auf der CNC.

11. Klicken Sie auf die Windows-„Start“-Schaltfläche und dann auf **Phoenix-Startprogramm**.



**Wenn die Schneidmaschine über Yaskawa-EtherCAT-Laufwerke verfügt:** Sie müssen das EtherCAT-Netzwerk jetzt neu konfigurieren. D. h., scannen Sie das EtherCAT-Netzwerk neu und erstellen Sie eine neue Datei **Phoenix.xml**. Siehe das Kapitel *Konfiguration des EtherCAT-Netzwerks* im *EDGE Connect Installations- und Einrichtungshandbuch* (809340) für Hilfestellung hierzu.