


PLASMA CUTTING SAFETY

**ARE YOU
PROTECTED?**



Don't get burned!

Is there a fire extinguisher nearby? Are flammables at least 35 feet away?


Never point the torch toward yourself or others. Let metal cool before touching it.



Stay grounded!

Is your work cable securely attached to the workpiece/ table with good metal-to-metal contact?

Don't connect to the piece that falls away.



Avoid toxic fumes!

Are there hazardous coatings or toxic materials?

Ensure adequate ventilation or use a respirator.



Don't get shocked!

Never touch the torch body, workpiece or water when the plasma system is operating on a CNC table.



Drawings by Kane Lynch